

# Fire Risk Assessment

## Bowater House

Moor Street, West Bromwich,  
B70 7AZ



**Date Completed:** 20<sup>th</sup> January 2026

**Review Period:** 12 months

**Officer:** Louis Conway **Building Safety Manager**

**Checked By:** Carl Hill **Building Safety Manager**

**Current Risk Rating = Moderate**

**Subsequent reviews**

<u>Review date</u>	<u>Officer</u>	<u>Comments</u>
<b>18/02/2026</b>	<b>Louis Conway</b>	Following an initial FRAEW step 2-5 the external contractor was instructed to undertake a more intrusive inspection of the external wall system and provide a detailed report of their findings. This inspection took place on 17/02/2026. Upon receipt and review of this intrusive survey report, this fire risk assessment will be formally revisited and updated as necessary to reflect any additional findings, risk considerations, or recommended control measures arising from the contractor's inspection.
<b>30/04/2026</b>	<b>Louis Conway</b>	A desktop review of the Fire Risk Assessment has been completed in light of recent findings from the external wall report valid from 03/03/2026. The assessment has been updated to incorporate this new evidence, following the additional intrusive survey on the south facing façade and evaluate its impact on the building's fire safety profile, and amend recommendations where necessary. Please see updates to section 6 in blue font and mitigation measures that are being put in place to further enhance life safety.

<b>12/05/2026</b>	<b>Carl Hill</b>	<p>A desktop review of the Fire Risk Assessment has been completed in response to the following. All amendments are in green font:</p> <ul style="list-style-type: none"><li>• LD1 Upgrade to detection in all flats including leaseholder properties. Section 8.</li><li>• A new L1 Automatic Fire Alarm system has been installed to replace the previous. Section 8.</li><li>• A simultaneous evacuation strategy has been introduced. Sections 1, 7, 12 &amp; 13.</li><li>• The 6 outstanding annual flat entrance door inspections have been completed. Section 10.</li><li>• An RPEEP &amp; PCFRA has been offered to all residents in the building. Section 2.</li><li>• New Fire Action notices have been installed. Section 12.</li><li>• Building Safety Notice has been updated. Section 13.</li><li>• On arrival information for WMFS updated. Section 4.</li></ul>
-------------------	------------------	---

## Contents

<a href="#">Section 0</a>	<b>Introduction</b>	
<a href="#">Section 1</a>	<b>Significant Findings (executive summary)</b>	
<a href="#">Section 2</a>	<b>People at Significant Risk of Fire</b>	
<a href="#">Section 3</a>	<b>Contact Details</b>	
<a href="#">Section 4</a>	<b>Description of Premises</b>	
<a href="#">Section 5</a>	<b>Building Plan</b>	
<a href="#">Section 6</a>	<b>External Envelope</b>	
<a href="#">Section 7</a>	<b>Means of Escape from Fire</b>	
<a href="#">Section 8</a>	<b>Fire Detection and Alarm Systems</b>	
<a href="#">Section 9</a>	<b>Emergency Lighting</b>	
<a href="#">Section 10</a>	<b>Compartmentation</b>	
<a href="#">Section 11</a>	<b>Fire Fighting Equipment</b>	
<a href="#">Section 12</a>	<b>Fire Signage</b>	
<a href="#">Section 13</a>	<b>Employee Training</b>	
<a href="#">Section 14</a>	<b>Sources of Ignition</b>	
<a href="#">Section 15</a>	<b>Waste Control</b>	
<a href="#">Section 16</a>	<b>Control and Supervision of Contractors and Visitors</b>	
<a href="#">Section 17</a>	<b>Arson Prevention</b>	
<a href="#">Section 18</a>	<b>Storage Arrangements</b>	
<a href="#">Section 19</a>	<b>Additional Control Measures. Fire Risk Assessment – Action Plan</b>	
<a href="#">Appendix 1</a>	<b>Significant Hazards on Site and Information to be provided for the Fire Service Risk Rating of Block</b>	

---

## Section

# 0

## Introduction

---

The [Regulatory Reform \(Fire Safety\) Order 2005 \(RR\(FS\)O\)](#) places a legal duty on landlords to complete a fire risk assessment (FRA). Specifically, RR(FS)O article 9. — (1) *“The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order”*.

This Type 1 Fire Risk Assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on <https://www.wmfs.net/our-services/fire-safety/#reportfiresafety>. In the first instance however, we would be grateful if you could contact us directly via <https://www.sandwell.gov.uk/contact/log-complaint> or by phone on 0121 569 6000.

The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation, but the Council will as a minimum review:

- High Risk Residential Buildings annually
- Other Buildings every 3 years

The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment. If the review suggests the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.

The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring, and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.

---




The above processes and procedures are overseen by the Fire Safety, Manager who reports to the Head of Building Safety.

These managers attend the Building Safety and Compliance Group for scrutiny which is part of the governance structure below.

---

Governance Structure



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire. This is recorded here in [section 1](#). Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring, and review of the preventative and protective measures. The information shown above is part of this requirement.

---

## Section

## 1

## Significant findings

The significant findings (executive summary) of the fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005.

Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors and contractors unfamiliar with the building layout as well as those with physical, sensory or mental health issues.

A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring and review of the preventive and protective measures. These are shown in the introduction.

### Significant findings

*Include a brief summary of protective and preventative measures where relevant along with any issues found.*

The escape strategy is no longer 'Stay Put Unless'. **With effect from the 8<sup>th</sup> May 2026 the escape strategy for Bowater House is Simultaneous Evacuation.** This means in the event of a fire affecting any part of the building then all persons should evacuate.

Section number	Section Area	Individual Risk Level
<a href="#">Section 6</a>	<p><b>External Envelope</b></p> <p>Partial blockwork and 3mm solid aluminium cladding on each elevation.</p> <p>All balconies enclosed and cladded with 3mm solid aluminium cladding.</p> <p>PUR tongue &amp; groove insulation boards provide insulation to the external wall systems.</p>	Moderate

	<p>Some provision for cavity barriers identified during previous type 4 FRA 05/09/23.</p> <p>Internal walls to enclosed balconies are single layer standard gypsum plasterboard with bonded polystyrene rear.</p> <p>External wall survey (step 1) was completed on the 04/11/2024 Further discussions are to be held with Contractors to discuss outcomes of the surveys. awaiting results from PAS:9980 Steps 2-5.</p> <p>Solar PV panels attached to the south elevation.</p>	
<p><a href="#">Section 7</a></p>	<p><b>Means of Escape from Fire</b></p> <p>The site has two protected staircases that serve all floors of the block, located at the front and rear of the building providing suitable and sufficient means of escape.</p> <p>All communal doors along the means of escape are self-closing nominal FD30s fire doors with combined intumescent strips / cold smoke seals &amp; vision panels.</p> <p>Automatic smoke ventilation is employed within each protected stair, with natural ventilation at the head of the stairs.</p> <p>There are 2 final exit doors.</p>	<p>Trivial</p>
<p><a href="#">Section 8</a></p>	<p><b>Fire Detection and Alarm Systems</b></p> <p>Fire detection within flats is installed to a minimum of an LD3 standard. Previous FRA's identified LD1 and LD2 systems in place. <b>On 5<sup>th</sup> May 2026 work began to upgrade all flats to LD1 standard.</b></p>	<p>Tolerable</p>

	<p>Automatic fire alarm with detection to stairs, landing, mains service cupboards, lift shaft, internal roof space, and also with a heat detector in each flat hallway. Fault is displayed on the repeater panel on the ground floor.</p> <p>5<sup>th</sup> to 8<sup>th</sup> May 2026 the communal fire alarm was replaced with a new L1 system. Work is ongoing to connect the new fire alarm system to an alarm receiving centre at SMBC CCTV control room.</p> <p>Automatic Fire Alarm system to be decommissioned once FRAEW and any resulting remedial works have been completed and accepted.</p> <p>A deluge system is provided to the bin store.</p>	
<p><a href="#">Section 9</a></p>	<p><b>Emergency Lighting</b></p> <p>The premises have a sufficient emergency / escape lighting system.</p>	<p>Trivial</p>
<p><a href="#">Section 10</a></p>	<p><b>Compartmentation</b></p> <p>The building is designed to provide as a minimum 1-hour vertical fire resistance and 60-minute horizontal fire resistance around flats stairwells and lift shafts. All doors are a minimum 30-minute fire resistant with intumescent strips &amp; cold smoke seals, including those in 1-hour rated walls.</p> <p>The premise has sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire.</p> <p>All flat entrance doors are minimum 30-minute nominal fire doors with intumescent strips &amp; cold smoke seals, including those in 1-hour rated walls.</p>	<p>Tolerable</p>

	<p>Passive fire-resisting barriers and nominal fire doors to facilitate access have been installed within the roof void to provide compartmentation.</p>	
<p><a href="#">Section 11</a></p>	<p><b>Fire Fighting Equipment</b></p> <p>There is a fire hydrant adjacent the rear entrance.</p> <p>The dry riser serves all floors.</p> <p>There is a CO2 fire extinguisher within the lift motor room.</p> <p>There is a deluge system in the bin store.</p>	<p>Trivial</p>
<p><a href="#">Section 12</a></p>	<p><b>Fire Signage</b></p> <p>Sufficient signage is displayed throughout the building.</p> <p>The block utilises Wayfinding Signage depicting floor level and flat numbers Fires Safety England Regulations 2022.</p> <p>Fire door keep shut signage ordered and to be installed on fire curtain doors upon delivery.</p> <p>New fire action notices have been displayed depicting the Simultaneous Evacuation strategy. Previous versions have been removed.</p>	<p>Trivial</p>
<p><a href="#">Section 13</a></p>	<p><b>Employee Training</b></p> <p>All staff receive basic fire safety awareness training.</p>	<p>Trivial</p>

<p><a href="#">Section 14</a></p>	<p><b>Sources of Ignition</b></p> <p>The fixed electric tests should be done every 5 years, last test date: 02/01/2022.</p>	<p>Trivial</p>
<p><a href="#">Section 15</a></p>	<p><b>Waste Control</b></p> <p>Regular checks by Caretakers minimise risk of waste accumulation.</p> <p>Refuse containers are secured within the bin store.</p>	<p>Trivial</p>
<p><a href="#">Section 16</a></p>	<p><b>Control and Supervision of Contractors and Visitors</b></p> <p>Contractors are controlled centrally, hot works permits and RAMS are required where necessary.</p>	<p>Trivial</p>
<p><a href="#">Section 17</a></p>	<p><b>Arson Prevention</b></p> <p>A door entry system prevents unauthorised access.</p> <p>Perimeter lighting is in place.</p> <p>There have been no reported fire incidents since the last FRA.</p>	<p>Trivial</p>
<p><a href="#">Section 18</a></p>	<p><b>Storage Arrangements</b></p> <p>Residents instructed not to bring L.P.G cylinders into block.</p> <p>Residents have access to storage sheds detached from the block located in the Parking.</p>	<p>Trivial</p>

## Risk Level Indicator

The following simple risk level estimator is based on commonly used risk level estimator:

Likelihood of fire	Potential consequences of fire		
	Slight harm	Moderate harm	Extreme harm
Low	Trivial risk	Tolerable risk	Moderate risk
Medium	Tolerable risk	Moderate risk	Substantial risk
High	Moderate risk	Substantial risk	Intolerable risk

Considering the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Low  Medium  High

In this context, a definition of the above terms is as follows:

**Low** Unusually low likelihood of fire because of negligible potential sources of ignition.

**Medium** Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).

**High** Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

---

Considering the nature of the premises and the occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:

Slight Harm     Moderate Harm     Extreme Harm

In this context, a definition of the above terms is as follows:

<b>Slight harm</b>	Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).
<b>Moderate harm</b>	Outbreak of fire could foreseeably result in injury including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.
<b>Extreme harm</b>	Significant potential for serious injury or death of one or more occupants.

Accordingly, it is considered that the risk to life from fire at these premises is:

Trivial     Tolerable     Moderate     Substantial     Intolerable

---

## Comments

This type 1 Fire Risk Assessment covers comments on the external envelope, flat entrance doors, roof space and communal areas of this High-Rise residential block also utilising reports / surveys completed by third party verified contractors and considering previous Intrusive FRA's.

In conclusion, the likelihood of a fire is set at a high level of risk prior to the implementation of the action plan because of the concerning potential fire hazards that have been highlighted within this and the previous risk assessment, which includes the PUR insulation boards that have been used throughout the external wall system and the installation of a single layer of standard gypsum plasterboard with a polystyrene thermal board bonded to rear on the internal wall of the enclosed balconies.

A severe fire within any of the rooms with the enclosed balconies could potentially penetrate the single layer of standard plasterboard within 30 minutes and ignite the combustible materials behind. However, it should be noted that some provisions for cavity barriers have been identified with the limited resources available to the risk assessor during the intrusive type 4 survey September 2023.

Cavity barriers are installed as passive fire protection to prevent the spread of fire and flames through the walls. It should also be noted that it may not be necessary to replace combustible materials that make up the components an external wall system or upgrade the internal walls to the balconies, once the appropriate level of safety, correct design and installation has been confirmed by a competent fire safety professional or qualified engineer with adequate experience and knowledge of external wall systems. Firntec Building Compliance were appointed to conduct an FRAEW of the external wall system at Bowater House which commenced March 2025 with an additional inspection to be scheduled for early 2026.

After considering the use of the premise and the occupants within the block, the consequences for life safety in the event of a fire would be slight harm. This is due to there being sufficient compartmentation to include nominal timber FD30s fire doors with intumescent strips and cold smoke seals to flat entrances, communal doors and service cupboards, combined with suitable smoke detection to a minimum of LD3 standard within flats, automatic smoke ventilation system between floors 1-2, 3-4, 5-6, 7-8 in both stairwells and natural ventilation at the head of the staircase, a communal fire alarm system with detectors in stairwells,

---

landings, mains cupboards, lift shaft, internal roof space with linked heat detectors within resident's hallway noting, that the system will eventually be decommissioned subject to the results of the FRAEW and any subsequent remedial works.

Overall, the level of risk at the time of this FRA is moderate, this will be lowered to trivial once recommended actions have been completed.

A suitable risk-based control plan should involve effort and urgency that is proportional to risk. The following risk-based control plan is based on one that has been advocated for general health and safety risks:

<b>Risk level</b>	<b>Action and timescale</b>
<b>Trivial</b>	No action is required, and no detailed records need to be kept.
<b>Tolerable</b>	No major additional fire precautions are required. However, there might be a need for reasonably practicable improvements that involve minor or limited cost.
<b>Moderate</b>	It is essential that efforts are made to reduce the risk. Risk reduction measures, which should take cost into account, should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
<b>Substantial</b>	Considerable resources might have to be allocated to reduce the risk. If the premises are unoccupied, it should not be occupied until the risk has been reduced. If the premises are occupied, urgent action should be taken.
<b>Intolerable</b>	Premises (or relevant area) should not be occupied until the risk is reduced.

*(Note that, although the purpose of this section is to place the fire risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)*

---

## Section

# 2

## People at Significant Risk of Fire

---

Persons at significant risk of fire does not just refer to those people with physical, sensory, or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council takes the health, safety and wellbeing of its colleagues, contractors, residents, and leaseholders seriously. It is our policy to exceed, where possible, the minimum health and safety requirements of the law.

Any risk-reduction measures that are found where a PEEP is necessary and completed will be documented and taken quickly.

With the consent of the resident, we will make a referral for West Midlands Fire Service to conduct a Safe and Well visit.

When a PEEP is in place, the relevant information will be kept in the secure Premise Information Box (High Rise Buildings only), which is set up to help WMFS in an emergency. The data is classified as level 1, which means it complies with the General Data Protection Regulations.

During recent LD1 and communal L1 fire alarm upgrade works (5<sup>th</sup> – 8<sup>th</sup> May 2026) all residents were informed in person of SMBC's responsibility to identify those who cannot evacuate independently due to impairment and, offer a potential Person Centred Fire Risk Assessment and Personal Emergency Evacuation Plan as per the Fire Safety (Residential Evacuation Plans) (England) Regulations 2025.

On this occasion, there were no residents who identified themselves as requiring assistance to evacuate and therefore declined a PCFRA and RPEEP.

---

**Section**

**3**

**Contact Details**

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.

The Chief Executive has put a structure in place to support the management of the site.

This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

<b>Chief Executive</b> Shokat Lal		
<b>Executive Director Asset Manager &amp; Improvement</b> Alan Lunt		
<b>Assistant Director Asset Management &amp; Improvement</b> Sarah Agar		
<b>Building &amp; Fire Safety Manager</b> Tony Thompson		
<b>Team Lead Fire Safety</b> Jason Blewitt		
<b>Team Lead Building Safety</b> Anthony Smith		
<b>Housing Office Manager</b> Lisa Ellis		
<b>Building Safety Managers</b> Adrian Jones Andrew Froggatt Carl Hill Louis Conway	<b>Fire Risk Assessors</b> Craig Hudson Mohammed Zafeer Stuart Henley	<b>Resident Engagement Officers – Fire Safety</b> Abdulmonim Khan Ethan Somaiya Hannah Russon

*Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change.*

## Section 4

# Description of Premises

Bowater House  
Moor Street  
West Bromwich  
B70 7AZ

### Description of the Property

Bowater House is a nine-storey high-rise residential block, originally constructed in 1963 under the authority of Smethwick Council, now managed by Sandwell Metropolitan Borough Council. Built by contractors Five Oaks Ltd, Bowater House was developed alongside one other similar block and comprises of 36 self-contained flats, with two protected stairwells and served by a single lift.

The original structure features a reinforced concrete frame, including stair cores, lift shaft, floor slabs, and foundations. A major external refurbishment was completed in 1999, which included enclosing all balconies, the addition of a lightweight steel-framed aluminium pitched roof and with solar photovoltaic panels to the south facing side elevation.



Balconies were also clad with 3mm solid Aluminium and enclosed to form part of the living room for each dwelling during the 1999 refurbishment works.

## Fire Risk Assessment

---



A lightweight pitched roof was constructed during the refurbishment utilising steel beams and purlins with aluminium standing / mineral wool core profiled panels. The solar PV inverters and switch gear are located within the roof space. The roof space is divided into 5 voids each separated by fire curtains and nominal 30-minute timber fire door.



## Fire Risk Assessment

---

The block consists of 9 stories inclusive of ground. There are 4 numbered dwellings per floor.



Bowater House	
Floor	Flat No's
G	1,2,3,4
1	5,6,7,8
2	9,10,11,12
3	13,14,15,16
4	17,18,19,20
5	21,22,23,24
6	25,26,27,28
7	29,30,31,32
8	33,34,35,36

The block has a main entrance/exit to the front elevation, and a further entrance/exit located on the rear elevation.



The main entrance to the front elevation has a door entry system with a fob reader installed. The entrance to the rear elevation is accessed by the installed fob reader. The front entrance only, has a firefighter override by use of a drop latch key.




## Fire Risk Assessment

---

There is a single lift car that serves to the 7<sup>th</sup> floor with the lift motor room being located on the 8<sup>th</sup>. The motor room is secured with a 54 suited key / mortice lock.




There are two protected stairwells that provide a means of escape.



Access to the rear carpark is restricted by an automated barrier. The Access code for the barrier is recorded on the on arrival form. It was noted that during the assessment the barrier was continually in the raised position.



On arrival Information (for WMFS)



Symbols			
fire hydrant	Orientation Plan: Bowater House, Moor Street, West Bromwich B70 7AZ. The map shows the house with various symbols: a yellow square (fire hydrant) near the rear entrance, a white circle with 'E' (gas stop valve) at the top and bottom, a white square with 'MAP' (main access point) on the right, a blue square (dry riser inlet) inside the house, and a red square (premise information box) inside the house.		
Gas stop valve			
Main access point			
Water isolation			
Firefighters white box			
Premise Information Box			
Dry Riser Inlet			
<b>Orientation Plan</b>	Bowater House, Moor Street, West Bromwich B70 7AZ	Survey date last updated: 20/12/2024	UPRN – 000032110730 BSR Registration Number - HRB04509L9Z2


There is a firefighter's white box externally to the right-hand side of the main entrance to the front of the building. The box contains keys for the building and is secured with a bridge-door padlock. Keys stored will be relocated to the PIB box once confirmed with WMFS.



Access to the building can be gained via the Fire Control switch at the front entrance utilising a Drop Latch Key.



There is a Secure Premise Information Box (PIB) located in the ground lobby front entrance lobby. It is a Gerda box that utilises a standard WMFS suited key. The PIB contains floor plans, vertical plans, orientation plans, information for WMFS and documents for those with vulnerabilities who may require additional consideration if there is a fire incident (PEEP).



## Fire Risk Assessment

---

There is a fire alarm system installed, the panel and zone plan are in the front entrance lobby. The key to the panel is secured both in the firefighter's white box and the key safe adjacent the panel.



5<sup>th</sup> to 8<sup>th</sup> May 2026 the communal fire alarm was replaced with a new L1 system. Work is ongoing to connect the new fire alarm system to an alarm receiving centre at SMBC CCTV control room. The new system includes the same functions as the previous with additional smoke detectors outside the chute room door on each floor, a lift interface that will send the lift to ground floor upon alarm activation and the removal of the sounder silence function within all flats. For clarity all detector heads have been replaced including, those linked heat detector heads within the hallway of each flat, lift shaft and roof void. The AOV's in each staircase will operate upon detection of smoke in each respective stairwell. The AOV override switch in each stairwell has not been affected by the new fire alarm installation and works as designed too.



There's a fire hydrant adjacent the rear entrance. The dry riser inlet is in a ground floor cupboard opposite the lift car. Riser outlets are in cupboards on all floors 1-8. All riser cupboards are secured with a budget type lock.


---

## Fire Risk Assessment

---



Automatic opening vents are present in both stairwells between floors 1-2, 3-4, 5-6, 7-8. The firefighter control switch has been installed to the wall of the front stairwell from ground to 1<sup>st</sup> floor.



The Firefighter lift control switch is also located to the right-hand side of the main entrance.



Access to the lift motor room is obtained from the 8<sup>th</sup> floor lobby. The key (54 suited) is stored within the firefighter's white box.



Access to the roof void where the solar PV inverter & switch gear is, is via a fixed steel ladder and timber fire door from the lift motor room. The roof void is divided in 5 compartments with mineral wool fire curtains and nominal 30-minute timber fire doors.



The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021.

The enforcing authority is West Midlands Fire Service.

---

## Fire Risk Assessment

Address: Bowater House, Moor Street West Bromwich, B70 7AZ		Survey date: 08/05/2026	ON ARRIVAL INFORMATION
<b>BUILDING LAYOUT</b>			
Height	21.6 metres		
Construction	Insitu concrete frame with masonry infill construction (Wates). The external walls consists of brick, solid 3mm aluminium panels and solar PV panels to the south west side elevation only. PUR foil faced boards are installed as cavity installation. The precise fire classification of the PUR boards is unknown but believed to be combustible European (equivalent to EN13501 class D-F).		
Number of floors	9 inclusive of ground floor .		
Layout	<p>The block has a main entrance/exit at the front and also to the rear. Access to the rear carpark via a barrier. The code is <b>2580A</b>.</p> <p>The block consists of 9 storeys (inclusive of the ground floor) each floor contains 4 number dwellings, total of 36 flats.</p> <p>There are two staircases that serves all floors to the block. The lift car serves to the 7<sup>th</sup> floor with access to the 8<sup>th</sup> floor via either staircase.</p> <p>Lift motor room located on the 8<sup>th</sup> floor.</p> <p>There is an outer building adjacent to the rear of the block which contains the booster pumps. In addition to this there is a Caretakers office / welfare room.</p>		
Lifts	1		
Types of entrance doors	Nominal FD30s timber fire doors to flats, FD30s timber fire doors to the communal areas.		
Rubbish chutes/ bin rooms	Bin store accessed externally from the rear of the building. Chute system installed with hopper on each floor.		
Common voids	Yes above 8 <sup>th</sup> floor.		
Access to roof void	The motor room is located on the 8th floor; access to motor room via full height door from 8th floor landing, with further fixed steel ladder leading up to the timber fire door then into the enclosed roof void. Roof void is compartmented with fire curtains and timber fire doors.		
Occupants	Approx. 72 based on an average of 2 occupants per flat (36 flats).		
Evacuation strategy	The escape strategy is Simultaneous Evacuation.		
Fire alarm/ evacuation alarm	There is a fire alarm system installed. The panel and zone plan can be found within the lobby on the ground floor. The system provides detection to the communal areas which includes stairs, landings, mains cupboards, lift shaft and roof area, as well as each individual flat having a hardwired heat detector connected to the system. The evacuation button will operate the sounders throughout the building including in each flat. The automatic opening vents in either staircase will open on detection of smoke within that stairwell.		
Caretaker/ concierge	Caretaking/cleaning service that conducts regular checks of the building		
<b>FIREFIGHTING SYSTEMS</b>			
Water supplies	Fire hydrant is adjacent the rear entrance of the building, fire hydrant location/ water isolation points located on the orientation plan. There is a dry riser that serves floors ground to 8.		
Fire mains	The dry riser inlet is located within the ground floor dry riser cupboard (twin valve) secured with a type 54 suited mortice lock. This is also located on the floor plans.		
Firefighting shafts	No firefighting lifts/shafts however, firefighters lift override switch is external, right hand side of front entrance.		
Smoke control vents	Automatic smoke ventilation is employed to each staircase between floors 1-2, 3-4, 5-6, 7-8. There is a master reset switch located on the bulkhead of the front 1 <sup>st</sup> floor staircase. Ventilation grill to head of each staircase.		
Sprinkler system	A sprinkler system is provided to the bin store		
<b>DANGEROUS SUBSTANCES</b>			
Location, type, and quantity	N/A		
<b>SERVICES</b>			
Electricity	Electric cupboards are secured with nominal FD30s fire doors secured with type 138 suited mortice locks. Residents have been provided with a key for access to their electricity meters		
Gas	Gas isolation points located on the orientation plan. Gas is present within the block		

High/Low Rise	High
Number of Floors	9
Date of Construction	1963
Construction Type	Concrete Frame / Masonry Infill
Last Refurbished	1999
External Cladding	3mm solid aluminium panels and brick, PUR foam within cavity wall. Solar PV panels to the upper façade of the south west facing gable end.
Number of Lifts	1
Number of Staircases	2
Automatic Smoke Ventilation to communal area	Yes, to both Stairwells.
Fire Alarm System	Yes, with detection to both stairwells, all lobby floors, roof space, lift shaft and a heat detector within each flat hallway. L1 alarm system has been upgraded as per section 8.
Refuse Chute	Yes
Access to Roof	Access in to roof space via fixed steel ladder in lift motor room.
Equipment on roof (e.g. mobile phone station etc)	Inverters for the solar PV system are in the enclosed roof space.

**Persons at Risk**

Residents / Occupants of 36 flats,  
 Visitors,  
 Sandwell MBC employees,  
 Contractors,  
 Service providers (e.g. meter readers, delivery people etc)  
 Statutory bodies (e.g. W.M.F.S, Police, and Ambulance)


---

**Section  
5**

**Building Plan**

A basic outline of the building's footprint.


Ground Floor




Floors 1-7

*AOV, s are located between floors on the half landings.*


# Fire Risk Assessment



## 8<sup>th</sup> Floor



# Fire Risk Assessment



Section

6

---

## External envelope

---

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.

Details of the external wall construction have been provided to the fire service via the WMFS portal in line with fire safety regulations 2022.

A survey of the external wall construction including balconies, windows and doors has been undertaken in accordance with the flow chart detailed in PAS 9980:2022 – Fire Risk Appraisals of External Walls (FRAEW) for existing multi-story, multi-occupied residential buildings. An External wall survey (PAS9980 step1) was completed on the 04/11/2024. This FRAEW was undertaken by Firntec Building Compliance.

Following the survey an intrusive fire risk appraisal (PAS9980 steps 2-5) had been completed and followed the guidance in accordance and reference to PAS9980:2022 Fire Risk Appraisal of External Walls construction and cladding of existing blocks of flats – Code of Practice and addresses life safety only in the appraisal of the external walls of the building and in corresponding risk this is only in relation to the threat to the occupants in the building and not in terms of property damage or other potential objectives, such as safety of firefighters.

Further meetings were held with Firntec Building Compliance to discuss the findings of the fire risk appraisal (PAS 9980, Steps 2–5). As a result of these discussions on 29/01/2026, it was concluded that Firntec Building Compliance would undertake a further site inspection to re-examine and provide additional clarification on elements identified within the building's external envelope. The findings of the fire risk appraisal (PAS 9980, Steps 2–5) will not be included within this FRA. **On receipt of the revised & approved report, SMBC will consider the contents and the requirements of a capital project to carry out any suggested works.**

---

## Fire Risk Assessment

This review has been undertaken following Firntec Building Compliance's return to site on 10/02/26 to carry out an intrusive survey of the south-facing façade under instruction from SMBC. The purpose of the survey was to clarify the potential risk of external fire spread involving the solar PV panels, PUR insulation, and enclosed balconies.

SMBC received the revised PAS 9980 Steps 2–5 assessment, which identified additional recommended interim measures due to the findings of the report. These, together with further mitigation measures proposed by SMBC Building Safety Team, are to be implemented as soon as reasonably practicable to enhance life safety within the block.

During the intrusive works, sections of the cladding system adjacent to the solar PV units were removed, revealing open cavities behind the balcony cladding with no evidence of open-state cavity barriers.

Please see the following findings from the latest report.

17 areas were inspected to gain data about the building's wall constructions.

The table below outlines the ratings of the various wall systems and constructions to the property. Each element is explained in more detail within the original report.

8 Items	Effect	Risk
Wall Construction Brickwork (Masonry) (SHUAZH)	Positive	Low
Wall Construction Wall Type 2 - Curtain Walling (9SRKKS)	Neutral	Low
Wall Construction Wall Type 3 - Cladding (79N1PY)	Negative	Medium
Penetration Flue (QI1JSE)	Neutral	Low
Penetration Air Brick (7W5FYT)	Neutral	Low
External Window Top, Mid, Side Hung Casements (A9GLUG)	Neutral	Low
External Window Top, Mid, Side Hung Casements (5TBTRJ)	Neutral	Low
External Door Single Leaf Entrance Doors (FHTNU8)	Neutral	Low

In accordance with the PAS 9980 Guidance, any items of construction which are considered as "Medium Risk" should be subject to periodic review, to ensure that conditions do not change, such that the risk may be upgraded to high, prompting the requirement for remediation.

A risk factor analysis was then conducted this is a three-stage process:

1. rating the wall construction fire performance
2. façade configuration
3. fire strategy/fire hazards on a sliding risk scale.

This then provides an overall risk to the building.

### Overall Building Risk Rating

High

Our professional opinion is that overall this Building represents a Negative PAS9980:2022 Outcome.

The following recommendations were proposed to lower the overall risk.

#### Façade Configuration: FH2KWM

Remove and replace all combustibile materials within this external wall type for materials that achieve Euroclass A2-s1,d0 rating or better.

Ensure fire/cavity barriers are installed at the relevant locations (such as at compartment junctions and around openings) as required by the system in conjunction with the current Building Regulations and guidance provided in Approved Document B.

This remediation will reduce the spread of fire within the external wall and prolong conditions for the means of evacuation or external intervention.

### 3 Recommended Interim Measures

#### Façade Configuration: FH2KWM

Although we have indicated that it is our opinion that the 'Stay Put Unless' policy remains suitable, it is our professional opinion that upon receiving this report, the building's Fire Risk Assessor should review their holistic assessment of this building's evacuation policy to ensure it remains suitable in line with the overall risk profile of the building and the information provided to them.

In the event of any change, the occupants of the building must also be informed and given suitable training regarding any alternative means of raising the alarm.

#### General Interim Measures

**Resident engagement strategy.**

Residents of the building should be informed of the outcome of the FRAEW and ways in which the responsible persons are managing the risks presented and any remediation proposals pursued.

**Retain the communal alarm system.**

For the purposes of mitigating the risk of fire spread within the building.

---

In light of the findings outlined within the external wall report, further mitigation measures are scheduled for implementation to reduce the risk to life safety within the block.

As of the date of this review, the following measures have been agreed and have been or will be introduced to support a reduction in the building's overall risk profile.


- External wall information has been updated on WMFS portal.
- 5th - 8th May 2026 - Smoke detection in all flats to be upgraded to LD1 standard (all habitable rooms).
- 5th - 8th May 2026 - The communal L1 fire alarm system is being upgraded to include a new panel and all detector heads including sounders will be replaced. This includes the linked heat detector to the hallway in each flat which forms part of the previous system. The new fire alarm will also be linked to SMBC CCTV control room.
- 8th May 2026 the evacuation strategy will change to simultaneous evacuation. All fire action notices will be updated.
- April / May 2026 resident engagement with tenants and leaseholders.
- 5th - 8th May 2026 the outstanding annual flat entrance door checks will be completed.
- April 2026 the manufacturers of a solar PV block product have been approached. Additional discussions are to be held to determine the suitability and application of the product.

It is considered that the short-term actions outlined above are sufficient to further reduce the overall risk level of the building while the following longer-term, permanent solutions are considered:

- Remove existing PUR insulation and external wall system
  - Install new external wall system that is compliant to European Classification A2-s1,d0 or Class A1 as per amendments to the 2010 Building Regulations.
-

## Fire Risk Assessment

Below is a breakdown of the materials believed to be used within the external envelope and, as part of the external wall system. This is based on the information available at the time of this FRA.



- 1) The exterior of the pitched roof consists of profiled aluminium standing seam mineral wool core composite panels and 14-gauge polyester coated aluminium panels to the soffits and fascia's.



- 2) Marshalls Airedale Armitage multi cut brick work covering approximately 43% of the external walls surface area.



- 3) 3mm solid aluminium panels clad approximately 32% of the external walls to include the enclosure of the former balconies. Information available at the time of the risk assessment (delta submission) records fire classification as A1.




- 4) Solar PV panels clad the southwest facing side elevation.




- 5) Insulation to the masonry cavity has been identified as 30mm foil faced PUR tongue & groove boards manufactured by NESTAAN. This detail is recorded on an architect drawing.

- 6) The original concrete floor slab was extended and now forms approximately 2% of the external tray wall surface area.



- 7) Windows to individual flats are uPVC double glazed units. Communal windows are double glazed powder coated aluminium.



- 8) Both front and rear entrances are also clad with a combination of flat and profiled aluminium panels.



- 9) Both front and rear entrance doors are glazed powder coated aluminium.



- 10) The documentation available to the Fire Risk Assessor prior to the commencement of the risk assessment, revealed 30mm foil faced PUR tongue & groove boards manufactured by Nestaan, were installed throughout the external wall systems. The fire classification of these boards was unknown prior to the commencement of this FRA however; they are believed to be combustible. It should be noted that that the author of this report was also present when the original type 4 was conducted in September 2023.

**The information below in this section is taken from the previous type 4 FRA September 2023.**

*Within a void flat, inspection holes were created behind the skirting board and beneath the window sills to the enclosed balcony / bay window. The inspection holes revealed the following materials within the construction;*

- *uPVC window cill board with ply beneath.*
-

- 9.5mm gypsum plasterboard with a 10mm polystyrene layer bonded to the rear for basic thermal insulation.
- Damp proof membrane (polythene sheet).
- Timber studwork.
- PUR board.,

*The borescope could not access beneath or behind the PUR boards or the area where the cavity within the balcony meets the masonry or masonry cavity.*



*Historic images were provided inhouse which appear to show a horizontal layer of mineral wool between the cantilevered concrete base and PUR board (enclosed balconies).*



*It appears that the extended concrete floor slabs could provide horizontal fire stopping between floors.*

---



*At the time of the assessment, it was not determined if cavity barriers are in place around openings for windows, ventilation pipework and flues.*




*An MDF strip with unknown fire rating was removed to inspect the cavity between the 1-hour party wall between a flat and the stairwell. This is where external masonry returns into the protected front stairwell. The cavity between the two surfaces was insulated with mineral wool. At the time of the inspection, it could not be determined if this cavity extended into the cavity of the external wall system.*



*Additional information was received after the inspection confirming that these cavities are in fact closed off by the return of the blockwork at the window positions. The MDF trim is in place for decorative purposes.*

---



*Further inspection holes were created within the external masonry at ground floor level to the north east facing side elevation. A borescope revealed evidence of PUR insulation board and what appeared to be a vertical cavity barrier contained within a green sock to the party wall. This type of cavity barrier can provide up to 4 hours of fire integrity dependant on which version was installed. Due to the limitations of the available resources, it could not be determined if the cavity barrier was consistent throughout the vertical lines of the party walls.*

*All holes created for inspection were appropriately sealed and or fire stopped.*

#### External wall conclusion.

- 12) *The materials used within the construction of the internal walls to the enclosed balconies consist of standard 9.5mm gypsum plasterboard, with a 10mm polystyrene thermal board bonded to the rear. The plasterboard is unlikely to provide sufficient fire resistance and therefore could potentially lead to combustible materials within this cavity igniting should there be a fire within this room. It is recommended that the internal wall to all enclosed balconies is upgraded with a suitable product that will provide a minimum of 30 minutes fire resistance.*

- 13) *The fire rating of the MDF strips covering the small cavities between the party walls and external blockwork return to the stairwells on each floor are unknown however it has been confirmed that these cavities have been closed off at the window position by the return of the blockwork. The mineral wool effectively provides additional fire stopping.*
- 14) *The cavities to the remaining external wall system also contain PUR foam boards for insulating purposes and some provisions for horizontal & vertical cavity barriers have certainly been identified.*

*However, it is recommended that as a precautionary measure further technical advice is sought from a competent fire safety professional or qualified engineer with adequate experience and knowledge in external wall systems. This will confirm if the appropriate level of safety through the correct design and installation of external wall system has been achieved.*

*It should be noted that it may not always be necessary to replace combustible materials such as these that make up the components of an external wall system.*

---

## Section

# 7

## Means of Escape from Fire

---

The means of escape within the building are protected to limit the spread of fire and smoke through the provision of nominal flat entrance doors and nominal communal FD30s fire doors. Walls and floors that are assumed to provide a minimum 60-minute fire resistance and adequate fire stopping. This combined with suitable travel distances, two staircases serving all floors, and ventilation by way of AOV system and louvre vents, with sufficient detection to both stairwells, all lobby floors, roof space, lift shaft and a heat detector within each flat hallway as well.

It is deemed that the combination of these measures facilitates a suitable and sufficient means of escape. **The strategy for the block is Simultaneous Evacuation.**

- 1) Individual flat doors are predominantly nominal self-closing 30-minute timber fire door sets with intumescent strips, cold smoke seals. Flat 18 has a replacement FD30s composite, not all doors have an intumescent lined letterbox which is acceptable because the doors were installed at a time prior to current standards.



- 2) Access was not gained to a sample of properties as part of the fire risk assessment due to the Fire Rapid Response team conducting a full non-invasive fire door inspection on the 21/01/2026, however condition of the external leaf of each door was assessed to ensure no damage or faults, the fire risk assessment draws on information taken from the previous fire risk assessment, information kept on file (JM) and previous fire door inspections to include the most recent and the door survey conducted by Firntec on 10/02/2025. All actions created from the fire door inspections will be dealt without outside of this fire risk assessment.
- 3) Individual floor mats were noted outside some flat entrance doors. The fire rating of the individual mats is unknown however; they are deemed to be of low risk.
- 4) All corridors and communal landing areas are of adequate width and will be maintained clear. There are no dead-end scenarios within communal areas.
- 5) The communal landing / staircases are protected by use of self-closing 44mm nominal timber 30-minute fire doors with vision panels with Georgian wired glazing, intumescent strips / cold smoke seals. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).
- 6) All communal fire doors are subject to a 12-week check by the Fire Safety Rapid Response Team.


The means of escape are ventilated by the way of natural ventilation and automatic smoke ventilation. Automatic smoke ventilation is employed. This is tested, inspected, and maintained by a competent procured contractor in accordance with BS7346. The frequency for the maintenance checks is twice per year (April and October) of each calendar year. AOV's are located on the half landings between 1-2, 3-4, 5-6, 7-8 within the protected staircase. Detection for the AOV's and communal fire alarm panel are within the communal areas. Each stairwell has a ventilation grill to the 8<sup>th</sup> floor. **The AOV's in each staircase will operate upon detection of smoke in each respective stairwell. The AOV override switch in each stairwell have not been affected by the new fire alarm installation and operates as originally designed to do. The new L1 fire alarm system was installed 5<sup>th</sup> – 8<sup>th</sup> May 2026.**

---

- 7) The firefighters control switch for the AOV has been installed to the wall of the front stairwell from ground to 1<sup>st</sup> floor.



- 8) Communal windows are not openable other than those that are controlled by AOV's.
- 9) Communal areas are kept free of flammable items. The communal areas are checked on a regular basis by Caretaking / Cleaning teams 365 days per year, and all items of rubbish are immediately removed. There is also an out of hour's service that allows combustible items of furniture / rubbish to be removed.
- 10) Emergency lighting is provided to communal landings and stairs. Checks are done on a monthly basis by Sandwell MBC in house electrical team or approved contractor.
- 11) The surface coatings to the communal areas are Class 0 rated.
- 12) The site has two staircases which provide an adequate means of escape. Both of which are 1000mm in width. The maximum travel distance from the furthest flats to the protected stair is 3 metres.



- 13) There is a chute room with a nominal FD30s timber door with vision panel (Georgian wired) on each floor lobby from 1<sup>st</sup> to 8<sup>th</sup>. All refuse hoppers are 1.5 hrs fire rated to BS 476 : 8 – 1972.



- 14) The refuse hopper to the ground floor is wall mounted beneath the ground to 1<sup>st</sup> floor rear stairs. This is deemed an acceptable location because the hopper is 1.5 hrs fire rated and tested to BS 7386: 1990 for smoke containment.



- 15) The final exit doors have door entry systems installed. These systems are designed to fail safe i.e. door unlocked in the event of a power failure. This prevents residents being locked in or out of the building.



Section

8

---

## Fire Detection and Alarm Systems

---

- 1) Early warning consists of hard wired smoke alarms within each of the resident's flats. In addition to the system there is a heat detector within the hall of each flat that is monitored by the building's automatic fire alarm panel. The equipment is subjected to a cyclical test.
- 2) Access was not gained to resident's flats to sample smoke detection. Based on the samples taken in previous FRA's and information collated from in house teams (JM) the smoke alarms within resident's flats are installed to a minimum of an LD3 Standard.

Flats accessed during previous FRA.

Flat 2

Flat 3

Flat 16

Flat 26

Flat 30

On 5<sup>th</sup> May 2026 work began to upgrade all flats to LD1 standard. It is anticipated that all works will be completed by the 22<sup>nd</sup> May 2026 subject to access to residents flats.

*For information*

*LD1 all rooms except wet rooms*

*LD2 all-risk rooms e.g. Living Room, Kitchens, and Hallway.*

*LD3 Hallway only*

- 3) There's a communal fire alarm system installed at Bowater House. The panel and zone plan can be found within the ground floor entrance lobby. The system is checked and tested weekly and bi-annually by the in-house electrical team or procured contractor. ~~Fault recognised on the control panel states "ADDR FAULT PNL 1 LOOP 2 ADDR 122 ZONE SOUNDER EIGHTH FLOOR BACK LANDING".~~
-

## Fire Risk Assessment

---



5th to 8th May 2026 the communal fire alarm was replaced with a new L1 system. Work is ongoing to connect the new fire alarm system to an alarm receiving centre at SMBC CCTV control room. The new system includes the same functions as the previous with additional smoke detectors outside the chute room door on each floor, a lift interface that will send the lift to ground floor upon alarm activation and the removal of the sounder silence function within all flats. For clarity all detector heads have been replaced including, those linked heat detector heads within the hallway of each flat, lift shaft and roof void. The AOV's in each staircase will operate upon detection of smoke in each respective stairwell. The AOV override switch in each stairwell has not been affected by the new fire alarm installation and works as originally designed to do.



- 4) The communal fire alarm system shall remain as a temporary measure until the results of the FRAEW from the specialist contractor have been received, and any identified remedials have been satisfactorily completed to lower any identified risks. The system shall then be decommissioned.
  - 5) The system is addressable so will identify the floor number with the relevant zone number and will state landing / stairs in text on the display.
  - 6) The system provides detection to the communal areas which includes stairs, landings, mains cupboards, lift shaft, internal roof space and is also linked to heat detectors within resident's hallways.
-



7) A deluge system is provided to the refuse chute bin store. An approved contractor maintains the system. The frequency for the maintenance checks are twice per year (April and October) of each calendar year.



8) Automatic smoke ventilation is employed to each stairwell between floors 1-2, 3-4, 5-6, 7-8.

---

**Section**

**9**

**Emergency Lighting**

---

- 1) The premises has a sufficient emergency / escape lighting system in accordance with BS 5266 and has test points strategically located.



- 2) The self-contained units are provided to the communal landings, stairs, and lift motor room.
  - 3) All installed equipment is checked and tested on a monthly basis by Sandwell MBC in house electrical team or approved contractor, in accordance with current standards.
-

## Section 10

# Compartmentation

The high degree of fire separation between flats and the common parts is achieved by making each flat a fire-resisting enclosure. This is known as compartmentation. A compartment is simply a part of a building bounded by walls and floors that will resist the passage of fire for a specified period of time. The fire resistance of this construction is such that, normally, a fire will burn itself out before spreading to other parts of the building. A visual inspection of the accessible areas was undertaken as part of the assessment, but areas with restricted access, i.e., false ceilings and void areas, were only inspected where readily accessible. The survey undertaken as part of this risk assessment should not be construed as a full compartmentation survey of the building. From a visual inspection carried out at the time of the inspection, there were no breaches in compartmentation evident between the communal areas and the residential accommodation.

- 1) The building is designed to provide as a minimum 1-hour vertical fire resistance and 1-hour horizontal fire resistance around flats stairwells and lift shafts. All doors are nominal 30-minute fire resistant, including those in 1-hour rated walls.
- 2) The premise has sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire. Whilst the existing fire stopping is fit for purpose, there is a cyclical programme to ensure fire stopping as not been compromised by third parties and where applicable enhance the fire stopping.
- 3) All communal doors are fitted with automatic closing devices that are checked on a regular basis by Caretaking Teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).
- 4) Dry riser cupboards are secured by use of locked nominal FD30s timber doors.



- 5) Service cupboards are secured by use of locked nominal FD30s timber doors.



- 6) Chute rooms have nominal FD30s timber doors with Georgian wired vision panel. All refuse hoppers are 1.5 hrs fire rated to BS 476: 8 – 1972.



- 7) All communal fire doors are subject to a 12-week check by the Fire Safety Rapid Response Team.
- 8) The lobbies & staircases are protected by use of timber nominal FD30s fire doors with vision panels.
- 9) Individual flat doors are nominal timber FD30s fire doors. Flat 18 has a replacement FD30s composite door set and flat 3 has a nominal timber flush FD30s.
- 10) Individual flat entrance doors were inspected in January 2026 by SMBC's Fire Rapid Response team. A total of 27 doors passed the inspection and 3 failed. Access was gained to a total of 30 flats. The occupiers of the remaining 6 flats that require door inspections have been written to, requesting access. Repairs will be completed by the Fire Rapid Response. An approved contractor will install any replacement FD30s doors that are required.

The inspections have been completed on a best endeavour basis in line with The Fire Safety England Regulations 2022.

---

The outstanding 6 annual flat entrance door checks were completed during the fire alarm and LD1 upgrade works 5<sup>th</sup> – 8<sup>th</sup> May 2026. Minor repairs have been scheduled to replace a damaged bat wing seal to flat 5 and replace a defective self-closing device to flat 34.

*Definitions Fire Doors.*

*Nominal fire door - A fire door that is thought to have been installed at the time of construction. This door may not meet current building regulation requirements however is still acceptable if performing as originally intended.*

*Upgraded nominal fire door - A nominal fire door that has been upgraded. For example, with intumescent strips and cold smoke seals.*

*Nominal fire door – A fire door that may meet the standards specified within the building regulations but has not been awarded the official certification of doors manufactured and tested by an accredited, third-party testing unit and approved formally with the relevant certificates and documentation.*

*Certified fire door – A fire door and frame that have been approved and certified by the manufacturer. The door assembly must be installed by a competent person.*

- 11) The fire stopping / compartmentation is subject to a 12-week check by the Fire Safety Rapid Response Team.
  - 12) Any remedial works arising from the fire stopping / compartmentation check(s) will be actioned immediately by the Fire Safety Rapid Response Team.
  - 13) A variety of methods / materials have been used to achieve fire-stopping including intumescent coated slabs & fire rated sponge.
  - 14) Access panels to stop taps are fire resistant board and are fixed to a timber rebated frame on intumescent material. **Cover to stop taps to be fixed back in place outside flat 13.**
-



15) The enclosed roof space is compartmentalised by fire curtains and doors. The roof space is accessed via a fixed steel ladder within the lift motor room.



Section

11

Fire Fighting Equipment

- 1) The dry riser inlet is located in the ground floor lobby opposite the lift car. The cupboard is secured with a budget lock / key.



- 2) Dry riser outlets are in cupboards on the communal landing of each floor. All cupboards are secured with a budget lock / key.



- 3) The dry riser is checked regularly as part of the Caretakers duties.
- 4) Maintenance contracts in place to service the valves twice per year (April and October) with a hydraulic test undertaken annually (October) to comply with the requirements of BS9990.
- 5) Portable fire extinguisher (CO2) is provided to the lift motor room. Service contracts are in place for maintenance of the extinguisher. The frequency for the maintenance checks are once (October) of each calendar year.



- 6) Bin room is protected by Deluge/sprinkler system and serviced 6-monthly. The control panel is in the ground floor service cupboard opposite the lift car.



- 7) There is also a closer plate with fusible link to the bin store chute.



- 8) There is a fire hydrant adjacent the rear entrance.



Section  
**12**

**Fire Signage**

- 1) All fire doors display “Fire Door Keep Shut” where appropriate. Additional signage will be provided within the roof space.



- 2) Fire Action Notices are displayed throughout the building depicting the escape strategy **Simultaneous Evacuation**. This evacuation strategy was introduced at Bowater House on 8<sup>th</sup> May 2026.



3) Yellow LPG warning signs are displayed within the lift cars.



4) Signage depicting the floor location of each flat is fitted to the ground floor lobby wall.



5) Photoluminescent wayfinding signage depicting floor level and flat numbers are fitted to the walls on all floors adjacent the lift car's and to the wall of each landing on the communal staircase. Signage that meets the requirement of ADB and Fire Safety (England) Regulations 2022.



6) The fire escape routes generally do not use directional fire signage in accordance due to simplicity of layout.

---

**Section  
13**

**Employee & Resident  
Training/Provision of Information**

- 1) All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- 2) All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking Teams are not currently trained in the effective use of fire extinguishers. The only extinguisher is located within the lift motor room. Caretaking Teams are not expected to tackle fires in this area.
- 4) Staff undertaking fire risk assessments are qualified to Level 4 Diploma in Fire Risk Assessment.
- 5) Fire safety information has been provided as part of tenancy pack.
- 6) Building safety and evacuation notices are displayed in common areas and lift cars.























- 7) Information regarding use of fire doors is provided to residents.



## Fire Risk Assessment

- 8) Information regarding the **Simultaneous Evacuation** strategy has been provided to residents.
- 9) Information regarding building safety is contained within a Building Safety Notice. This is affixed to the wall on the ground floor lift lobby of high-rise blocks.

BUILDING SAFETY INFORMATION	 <b>BOWATER HOUSE</b>	FIRE SAFETY INFORMATION	
<p style="text-align: center;"><b>TO KEEP YOU SAFE WE DO THIS</b> <small>(green background)</small></p>	<p style="text-align: center;"><b>TO KEEP YOURSELF AND OTHERS SAFE, DO THIS</b></p>	<p style="text-align: center;"><b>SAVE LIVES, DON'T DO THIS</b> <small>(red background)</small></p>	
 <p>Mains electrical system is tested every 5 years</p>	<p>SMBC ARE AUTOMATICALLY NOTIFIED WHEN THE COMMUNAL FIRE ALARM ACTUATES. IN AN EMERGENCY RESIDENTS SHOULD DIAL 999 OR 112 AND ASK FOR POLICE, AMBULANCE OR FIRE SERVICE</p>	 <p>Fire Risk Assessments (FRAs) are undertaken in line with the Regulatory Reform (Fire Safety) Order 2005</p>	
 <p>Gas supply is tested annually</p>		 <p>Stairs and corridors are escape routes and <b>must</b> be kept clear</p>	
 <p>Water supplies checked in line with water hygiene regulations</p>		 <p>Emergency lighting comes on in the event of power failure and is checked monthly</p>	
 <p>There is 5 yearly check of the structural condition</p>		 <p>Walls, floors and ceilings around flats provide a minimum of 60 minutes fire resistance</p>	
 <p>An asbestos survey has been completed and available on request</p>		 <p>Flat doors are fire rated to protect the escape route. <b>DO NOT REMOVE THE DOOR CLOSERS</b></p>	
 <p>This building has protection against lightning strikes. The system is checked annually</p>		<p><b>THE ESCAPE STRATEGY FOR THIS BUILDING IS SIMULTANEOUS EVACUATION. IN THE EVENT OF A FIRE ANYWHERE IN THIS BUILDING THEN ALL PERSONS SHOULD IMMEDIATELY LEAVE USING ONE OF THE STAIRWELLS AND THEN DIAL 999 OR 112 AND ASK FOR THE FIRE SERVICE.</b></p>	 <p>Smoke and heat detector alarms are installed in all resident's flats.</p>
 <p>There is a 'dry riser' to assist fire-fighters in getting water to a floor level. This is checked 6 monthly.</p>		 <p>Smoke detectors in common parts (&amp; 1 heat detector in each flat hallway) are linked to a communal fire alarm system. Smoke detectors in stairs will also open the automatic opening smoke vents within the stairwells.</p>	
 <p>The external façade is brickwork, with 3mm solid aluminium panels (class A1) and solar PV panels to the south west gable end, PUR board has been used as cavity insulation (class F)</p>		<div style="display: flex; justify-content: space-between;"> <div style="text-align: center;">                       Fire safety advice                 </div> <div style="text-align: center;"> <p>Further information available at <a href="http://www.sandwell.gov.uk">www.sandwell.gov.uk</a>, your My Sandwell account or the Fire Safety Liaison Officer on 0121 569 6000  <a href="mailto:Abdulmonim.Khan@sandwell.gov.uk">Abdulmonim.Khan@sandwell.gov.uk</a>                      Resident Engagement Officer  <a href="mailto:carl_hill@sandwell.gov.uk">carl_hill@sandwell.gov.uk</a>                      Building Safety Manager</p> </div> <div style="text-align: center;">                       Sandwell FRAs                 </div> </div>	 <p>Bin rooms have sprinkler protection activated by smoke alarms</p>

Section  
**14**

**Sources of Ignition**

- 1) Smoking is prohibited within any communal parts of the building in line with Smoke Free England legislation.



- 2) Hot working is not normally carried out. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager Bryan Low.
- 4) The fixed electrical installation shall be tested every 5 years. It was noted that the last inspection was 02/01/22. The condition of the installation was marked as satisfactory.

ELECTRICAL INSTALLATION CONDITION REPORT	
Requirements for Electrical Installations - BS 7671:187 Wiring Regulations	
Report Reference: 17 CEICR / 012	
<b>DETAILS OF THE PERSON ORDERING THE REPORT</b>	
Client:	Sandwell Metropolitan Borough Council
Address:	Direct 2 Industrial Estate, Roway Lane, Oldbury, B69 3E5
<b>REASON FOR PRODUCING THIS REPORT</b>	
Reason for producing this report: To ensure compliance with BS7671 as amended 2020	
Date(s) on which inspection and testing was carried out:	02/01/2022
<b>DETAILS OF THE INSTALLATION WHICH IS THE SUBJECT OF THIS REPORT</b>	
Installation Address: Landlord Supply, Ground Floor Bowater House, West Bromwich, West Midlands, B70 7AZ	
Description of premises:	Domestic <input type="checkbox"/> N/A <input type="checkbox"/> Commercial <input type="checkbox"/> Industrial <input checked="" type="checkbox"/> N/A <input type="checkbox"/> Other <input type="checkbox"/> N/A <input type="checkbox"/>
Estimated age of wiring system:	13 years Evidence of additional alterations: Yes <input type="checkbox"/> No <input type="checkbox"/> If yes, estimated age: 5 years
Installation records available (Regulation 651.1):	No Date of last inspection: 13/12/2008
<b>EXTENT AND LIMITATIONS OF INSPECTION AND TESTING</b>	
Extent of the electrical installation covered by this report: The whole of the installation	
Agreed limitations including the reasons (see Regulation 653.2): 100% visual inspection carried out and 20% accessories removed.	
Agreed with: Sandwell Metropolitan Borough Council	
Operational limitations including the reasons: Floodlights that requires towers or scaffolding has not been tested.	
The inspection and testing detailed in this report and accompanying schedules have been carried out in accordance with BS 7671:2018 (Wiring Regulations) as amended to 2020. It should be noted that cables concealed within trunking and conduits, under floors, in roof spaces, and generally within the fabric of the building or underground, have not been inspected unless specifically agreed between the client and inspector prior to the inspection. An inspection should be made within an accessible roof space having other electrical equipment.	
<b>SUMMARY OF THE CONDITION OF THE INSTALLATION</b>	
See page 3 for a summary of the general condition of the installation in terms of electrical safety.	
Overall assessment of the installation in terms of its suitability for continued use*: <input type="checkbox"/> SATISFACTORY	
*An unsatisfactory assessment indicates that dangerous (Code C1) and/or potentially dangerous (Code C2) conditions have been identified.	
<b>RECOMMENDATIONS</b>	
Where the overall assessment of the suitability of the installation for continued use on page 3 is stated as 'UNSATISFACTORY', it is recommended that any observations classified as 'Code 1 - Danger Present' or 'Code 2 - Potentially dangerous' are acted upon as a matter of urgency. Investigation without delay is recommended for observations identified as '3' - Further Investigation Required. Observations classified as 'Code 3 - Improvement recommended' should be given due consideration. Subject to the necessary remedial action being taken, I will recommend that the installation is further inspected and tested by: 5 Years Note: The proposed date for the next inspection should take into consideration the frequency and quality of maintenance that the installation can reasonably be expected to receive during its intended life. The period should be agreed between relevant parties.	

- 5) The electrical installation i.e. risers are contained within dedicated service cupboards that are secure and protected by means of a nominal FD30S door.



- 6) There is lightning protection installed to the block. Maintenance contracts are in place for lightning conductor testing in accordance with BS 6651.
- 7) Portable heaters are not allowed in any common parts of the premises.
- 8) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the in-house Gas Team. Gas supply pipework is internal to the building.
-

**Section**  
**15**

---

**Waste Control**

---

- 1) There is a regular Cleaning Service to the premises.
  - 2) Refuse containers emptied regularly.
  - 3) Regular checks by Caretakers minimise risk of waste accumulation.
  - 4) 'Out of Hours' service for residents is in place to remove bulk items.
-

**Section  
16**

---

## **Control and Supervision of Contractors and Visitors**

---

- 1) Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
  - 2) Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
  - 3) Utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the Investments office @ Roway Lane. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
  - 4) Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
    - a) Pre-Contract Meetings – where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
      - Health and Safety.
      - Site Security.
      - Safety of working and impact on children/school business.
      - Fire risk, if any.
      - Site Emergency Plan.
    - b) Monthly Site Meetings – in order to monitor, review and share any new information including any new risks.
    - c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
    - d) Final Contractor review on completion of works undertaken.
-

**Section**  
**17**

---

## **Arson Prevention**

---

- 1) Regular checks are undertaken by Caretakers / Cleaning Team(s) 365 days per year which helps reduce the risk of arson.
  - 2) Restricted access to the premises by means of a door entry system.
  - 3) CCTV is not present.
  - 4) There is no current evidence of arson.
  - 5) The perimeter of the premises is well illuminated. The electrical compliance manager has confirmed that a job has been raised adjust the timer to the external lights.
  - 6) There have been no reported fire incidents since the last FRA.
-

## Section 18

### Storage Arrangements

- 1) Residents instructed not to bring L.P.G cylinders into block.  
(Notice displayed in lifts see point 9-3)



- 2) The tenancy conditions, Section 7 – Condition 5.6 stipulates “If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use.”
- 3) No Flammable liquids stored on site by Caretakers / cleaners.
- 4) All store cupboards are kept locked.
- 5) Residents have access to secure storage sheds detached from the building within the rear carpark.

**Section  
19**

**Additional Control Measures;  
Fire Risk Assessment - Level 2  
Action Plan**

---

Significant Findings

**Action Plan**

It is considered that the following recommendations should be implemented to reduce fire risk to, or maintain it at, the following level:

Trivial       Tolerable

Definition of priorities (where applicable):

**P1 Arrange and complete as urgent – Within 10 days**

**P2 Arrange and complete within 1-3 Months of assessment date**

**P3 Arrange and complete within 3-6 Months of assessment date**

**P4 Arrange and complete exceeding 6 months under programmed work**



# Fire Risk Assessment Level 2 Action Plan



Name of Premises or Location:


Bowater House

Date of Action Plan:

30/01/2026

Review Date:

<Insert date>

Question/ Ref No	Required Action	Supporting photograph	Priority	Timescale and Person Responsible	Date Completed
8/3	Fault on the communal fire alarm panel to be addressed and rectified		P2	Within 1-3 months Electrical	08/05/26

Fire Risk Assessment

---

10/18	Outside flat 13 Cover to stop taps to be fixed back in place.		P2	Within 1-3 months Fire Rapid Response JM18772401	12/02/2026
-------	--	--	----	--	------------

**Observations**

When undertaking future improvement program(s), it is advised that the observations listed below should be given consideration (noting that the safety of the residents is not jeopardised by these, and all steps to reduce any known risks have been taken).

Further meetings were held with Firntec Building Compliance to discuss the findings of the fire risk appraisal (PAS 9980, Steps 2–5). As a result of these discussions on 29/01/2026, it was concluded that Firntec Building Compliance would undertake a further site inspection to re-examine and provide additional clarification on elements identified within the building’s external envelope. On receipt of the revised & approved report, SMBC will consider the contents and the requirements of a capital project to carry out any suggested works.


The findings of the fire risk appraisal (PAS 9980, Steps 2–5) will not be included within this FRA. However, this FRA should be reviewed when the appraisal has concluded and been accepted then be updated with the relevant information.





## Fire Risk Assessment

---

Attached below is correspondence made between a member of Sandwell Council conducting the type 4 fire risk assessment in 2023 and an employee at Nestaan as they investigated the products found within the type 4 FRA.

  
FW\_ Nestaan  
Insulation Board from

**Signed**

	Building Safety Manager	Date: 30/01/2026
	Quality Assurance Check	Date: 30/01/2026



## Fire Risk Assessment

---

From: Pieter van Nes <[pieter@nhb.be](mailto:pieter@nhb.be)>  
Sent: 08 September 2023 10:18  
To: Carl Hill <[carl\\_hill@sandwell.gov.uk](mailto:carl_hill@sandwell.gov.uk)>  
Subject: Netaan Insulation Board from 1999

**CAUTION:** This email originated from outside of the Council / Children's Trust. Do not click links or open attachments unless you recognise the sender and know the content is safe.

Dear Sir,

Further to your message earlier this week to our colleagues of Netaan Holland BV, regarding the fireclassification of a foil faced polyurethane board, very likely I

Undersigned was managing director of Netaan Belgium NV, company which was taken over by Belgian Recticel NV on the 1st of April 2000 already and which has been manufacturing these laminated polyurethane insulation boards within our group back in 1999.

Since then I have been running the mineral division in our group, where we manufacture Sprayed Limpet Vermiculite, A cement-vermiculite based spraymortar for passive fireprotection of structures in steel and concrete, With applications in building and construction (ETA's to EN13381p4), hydrocarbon installations like refineries (certified to UL1709) and road- and railway tunnels, since we have managed to get our mortarsystem also certified to the famous RWS-2020 standard by Efectis Netherlands.

Back to your question on the 1999 slabs. If indeed these are standard Netaan ALP, then their firerating would have been DIN4102-B3 class, Comparable to the French Epiradiateur class M4, which is quite a decent self-extinguishing fireclass but not more than that.

We have been supplying foil faced boards to the UK, which had an improved firebehaviour, very likely corresponding to DIN4102 class B2. But in order to be able to check that, you would need to find back a lot number and product reference, printed at the back of the boards,

And hopefully Recticel has been retaining the traceability records of Netaan, though after 24 years there is quite a risk That these have been discontinued. Since they acquired the entire liability over all previous productions, It also means that today, at Netaan we do not have access ourselves to such records.

Hope this may help you further in your assessment,

Kind regards,

on behalf of Netaan NV

---

## Significant Hazards on Site and Information to be Provided for the Fire Service

**Name of property: Bowater House**

**Updated: 20/06/2026**

**Premise Manager: Tony Thompson**

**Tel. No.: 0121 569 2975**


Hazard	Information/Comments
Insulation materials around balconies and within masonry cavity.	WMFS should be advised of the presence of combustible insulation materials.
An asbestos survey has been undertaken of the communal areas Survey held by Sandwell Housing	Report issued 08/07/2025.



**Report No.:** J421076  
**Nature of Work:** Management Survey  
**Issue Date:** 08/07/2025  
**Client Name:** Sandwell MBC (formerly Homes) Building Services, Direct 2 Trading Estate, Roway Lane, Oldbury, West Midlands, B69 3ES  
**UPRN:** BL33360BO23 8  
**Site Address:** 1-36 Bowater House, West Bromwich, B70 7AZ



**Order Placed By:** Jon Hemming  
**Site Contact:** Dean Harding  
**Date(s) of Work:** 20/06/2025  
**Technical Manager:** D Ely CCP (Asbestos)  
**Assistant Surveyor(s):** Not Applicable  
**Lead Surveyor:**

  
 Jack Baldwin  
 Asbestos Surveyor

**Authorised Signatory:**  
  
 Louise Farmer  
 Technical Review Officer and Asbestos Consultant  
 08/07/2025

Non-accredited activities are present within this report.

Head Office:  
 20 Stourbridge Road,  
 Halesowen, West Midlands  
 B63 3JY  
 Tel: 0121 550 0224  
 Email: [sales@bradley-environmental.co.uk](mailto:sales@bradley-environmental.co.uk)



## Fire Risk Assessment

---

---