Fire Risk Assessment

Boulton House



Spon Lane, West Bromwich, B70 6BJ

Date Completed: 28/11/2024. Review Period: 12 months. Officer: L. Conway Fire Risk Assessor Checked By: C. Hill Fire Risk Assessor

Current Risk Rating = Tolerable



Subsequent reviews

Review date	Officer	<u>Comments</u>

Contents

Section 0	Introduction	
Section 1	Significant Findings (executive summary)	
Section 2	People at Significant Risk of Fire	
Section 3	Contact Details	
Section 4	Description of Premises	
Section 5	Building Plan	
Section 6	External Envelope	
Section 7	Means of Escape from Fire	
Section 8	Fire Detection and Alarm Systems	
Section 9	Emergency Lighting	
Section 10	Compartmentation	
Section 11	Fire Fighting Equipment	
Section 12	Fire Signage	
Section 13	Employee Training	
Section 14	Sources of Ignition	
Section 15	Waste Control	
Section 16	Control and Supervision of Contractors and Visitors	
Section 17	Arson Prevention	
Section 18	Storage Arrangements	
Section 19	Additional Control Measures; Fire Risk Assessment – Action Plan	
Appendix 1	Significant Hazards on Site and Information to be provided for the Fire Service Risk Rating of Block	

Section

Introduction

The <u>Regulatory Reform (Fire Safety) Order 2005 (RR(FS)O)</u> places a legal duty on landlords to complete a fire risk assessment (FRA). Specifically, RR(FS)O article 9. — (1) "The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order".

This fire risk assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on <u>https://www.wmfs.net/our-services/fire-safety/#reportfiresafety</u>. In the first instance however, we would be grateful if you could contact us directly via <u>https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedb</u> ack_and_complaints_or by phone on 0121 569 6000.

The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation, but the Council will as a minimum review:

- High Risk Residential Buildings annually
- Other Buildings every 3 years


The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment. If the review suggests the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.

The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.



The above processes and procedures are overseen by the Fire Safety, Manager who reports to the Head of Building Safety

These managers attend the Building Safety and Compliance Group for scrutiny which is part of the governance structure below.



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire. This is recorded here in <u>section 1</u>. Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring and review of the preventative and protective measures. The information shown above is part of this requirement.



Significant findings

The significant findings (executive summary) of the fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005. Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors and contractors unfamiliar with the building layout as well as those with physical, sensory or mental health issues.

A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring and review of the preventive and protective measures. These are shown in the introduction.

Significant findings

Include a brief summary of protective and preventative measures where relevant along with any issues found;

The escape strategy is '**Stay Put Unless'**. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire, smoke or you have been advised by the emergency services to leave.

Section number	Section Area	Individual Risk Level
Section 6	External Envelope External façade of the building consists predominantly of traditional concrete masonry construction, last refurbished 2008. Balconies are constructed using a cantilevered concrete slab as a base with a steel and Georgian wired glass balustrade. Window units are double glazed with a UPVc frame.	Trivial
Section 7	Means of Escape from Fire The site has two sets of staircases that provides a means of escape located at the	Trivial

	Front and the rear of the building The means of escape are protected to prevent the spread of fire and smoke by means of nominal doors to flats and notional fire doors along escape stairs fire doors and good compartmentation between lobby areas, staircases, and dwellings. Ventilation by the means of a natural louver vent in the rear elevation staircase and AOV's within the front elevation staircase.	
Section 8	Fire Detection and Alarm Systems Early warning is limited to hard wire or battery smoke alarms within each of the resident's flats. The equipment is subjected to a cyclical test.	Trivial
Section 9	Emergency Lighting The premises have a sufficient emergency lighting system in accordance with BS 5266.	Trivial
Section 10	Compartmentation The building is designed to provide as a minimum 1-hour vertical fire resistance and 1- hour horizontal fire resistance around flats stairwells and lift shafts. All doors are a minimum nominal/notional 30-minute fire resistant with intumescent strips & cold smoke seals, including those in 1-hour rated walls, the premise has sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire. Ground floor communal door doesn't reliably self-close from all angles. Door leaf binds on floor during movement.	Tolerable
Section 11	Fire Fighting Equipment The dry riser inlet cupboard is located in the ground floor lift lobby and is appropriately signed, riser outlets are available on each floor of the block, Portable fire extinguisher (CO2) is provided to the lift motor room,	Trivial

	Hydrant can be located at the front of the	
	building with adequate signage, bin room is protected by a deluge/sprinkler system.	
Section 12	Fire Signage Appropriate signage has been placed within the block including fire action notices, and fire door keep shut signs. The block has Wayfinding Signage depicting floor level and flat numbers are fitted to the wall adjacent to lift. Signage depicting the floor location of each flat is fitted to the ground floor lobby wall	Trivial
Section 13	Employee Training All employees are encouraged to complete 'In the line of fire' training on an annual basis	Trivial
Section 14	Sources of Ignition The fixed electrical installation shall be tested every 5 years. It was noted that the last inspection was 18/12/2021. Gas is installed within the block, smoking is prohibited in any communal areas.	Trivial
Section 15	Waste Control There is a regular Cleaning Service to the premise. Refuse hoppers are accessed on each floor of the rear staircase. Regular checks by Caretakers minimise risk of waste accumulation.	Trivial
Section 16	Control and Supervision of Contractors and Visitors Contractors are controlled centrally, and hot works permits are required where necessary.	Trivial
Section 17	Arson Prevention Restricted access to the premises by means of a door entry system, there has been no reported fire incidents since the last FRA	Trivial

Section 18	Storage Arrangements	Trivial
	There are no storage facilities for residents	
	other than in their own flats within the block.	

Risk Level Indicator

The following simple risk level estimator is based on commonly used risk level estimator:

Likelihood of fire	Pc	Potential consequences of fire		
	Slight harm	Moderate harm	Extreme harm	
Low	Trivial risk	Tolerable risk	Moderate risk	
Medium	Tolerable risk	Moderate risk	Substantial risk	
High	Moderate risk	Substantial risk	Intolerable risk	

Considering the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Low
Medium
High

In this context, a definition of the above terms is as follows:

Low	Unusually low likelihood of fire because of negligible potential sources of ignition.
Medium	Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).
High	Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

Considering the nature of the premises and the occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:

Slight Harm \square Moderate Harm \square Extreme Harm \square In this context, a definition of the above terms is as follows:

Slight harm	Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).
Moderate harm	Outbreak of fire could foreseeably result in injury including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.

Extreme harm Significant potential for serious injury or death of one or more occupants.

Accordingly, it is considered that the risk to life from fire at these premises is:

Trivial \Box Tolerable \boxtimes Moderate \Box Substantial \Box Intolerable \Box

Comments

In conclusion, the likelihood of a fire is at a medium level of risk prior to the implementation of the action plan because of the potential fire hazards that have been highlighted within the risk assessment.

After considering the use of the premise and the occupants within the block, the consequences for life safety in the event of a fire would be slight harm. This is due to there being sufficient compartmentation to include 30-minute fire doors to flat entrances, communal corridors / landings, and service cupboards alongside, suitable smoke detection to a minimum of LD3 standard within flats, automatic smoke ventilation to the front elevation staircase and, a stay put unless policy for the premise.

Overall, the level of risk at the time of this FRA is tolerable, this will be lowered to trivial once recommended actions have been completed.

A suitable risk-based control plan should involve effort and urgency that is proportional to risk. The following risk-based control plan is based on one that has been advocated for general health and safety risks:

Risk level	Action and timescale
Trivial	No action is required, and no detailed records need to be kept.
Tolerable	No major additional fire precautions required. However, there might be a need for reasonably practicable improvements that involve minor or limited cost.
Moderate	It is essential that efforts are made to reduce the risk. Risk reduction measures, which should take cost into account, should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
Substantial	Considerable resources might have to be allocated to reduce the risk. If the premises are unoccupied, it should not be occupied until the risk has been reduced. If the premises are occupied, urgent action should be taken.
Intolerable	Premises (or relevant area) should not be occupied until the risk is reduced.

(Note that, although the purpose of this section is to place the fire risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)

Section

People at Significant Risk of Fire

Persons at significant risk of fire does not just refer to those people with physical, sensory or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council takes the health, safety and wellbeing of its colleagues, contractors, residents and leaseholders seriously. It is our policy to exceed, where possible, the minimum health and safety requirements of the law.

Residents are responsible for letting us know whether they might need a Personal Emergency Evacuation Plan (PEEP). The Resident Engagement Officers (Fire Safety) will conduct an assessment visit upon request. Any risk-reduction measures that are found where a PEEP is necessary and completed will be documented and taken quickly. With the consent of the resident, we will make a referral for West Midlands Fire Service to conduct a Safe and Well visit.

When a PEEP is in place, the relevant information will be kept in the secure Premise Information Box (High Rise Buildings only), which is set up to help WMFS in an emergency. The data is classified as level 1, which means it complies with the General Data Protection Regulations.



Contact Details

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.

The Chief Executive has put a structure in place to support the management of the site.

This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

Chief Executive Shokat Lal

Director of place

Assistant Director Building Compliance Sarah Agar

Fire & Building Safety Manager Tony Thompson


Team Lead Fire Safety Jason Blewitt

Fire Risk Assessor(s) Carl Hill Louis Conway Adrian Jones Anthony Smith

Resident Engagement Officer - Fire Safety Abdul Monim Khan

Housing Office Manager Lisa Ellis

Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change



Description of Premises

Boulton House Spon Lane West Bromwich B70 6BJ

Description of the Property

The high-rise block was constructed in 1964 out of concreate with masonry infill cladding materials consisting of concrete brick and glass, the block consists of 9 storeys including the ground floor with each floor containing 4 number dwellings coming off a lift lobby with two was travel in the form of two protected staircases at the front and rear of the building.



There is an entrance/ exit to the front elevation to the block with an additional rear entrance/exit to the rear elevation. Front entrance acts as the main access point to the block.





Front and rear entrances have a fob reader installed giving access to the block with the front entrance also utilising a override switch in the form of a drop latch giving access to the fire service.



There residents have access to an external car park at the rear of the building, garages and outhouses are on the premise but not attached to the block and not covered in this risk assessment.



Bin store is located to the right of the rear entrance/exit to the block and is secured using a bin store padlock with natural ventilation in the form of louver vents.



The block has 2 protected staircasses that can be accessed from the ground floor to the 8th sperated from the lift/flat lobby areas. These areas containg AOV, louvre vents and opening windows allowing for adequate ventilation.



The block has a lift car that serves 7 floors from ground to 7th with the 8th accessed via the staircases. The maximum capacity of the lift is 1200lbs.



Lift motor room is located on the 8th floor behind a notional fire door.



Firefighters white box Is located to the left of the main access point of the building.



There is a Secure Premise Information Box (PIB) located in the ground floor front entrance lobby under the staircase. It is a Gerda box that utilises a standard WMFS suited key held on each fire appliance. The PIB contains floor plans, vertical plans, orientation plans, information for WMFS and a plan to indicate the location of those with vulnerabilities who may require additional consideration if there is a fire incident (PEEP).



Fire hydrant can be located at the front of the building and is identified with adequate signage.



The dry riser inlet cupboard is in the ground floor lift lobby. It is accessed utilising a suited 54 key and has adequate signage.



Dry riser outlets are available on each floor lobby $(1^{st} - 8^{th})$ also secured within cupboards by suited 54 key & mortice locks and has adequate signage.



Automatic opening vents are installed to the front staircase only. The information panel is located on the ground floor main entrance lobby.



The lift car has an override facility located on the ground floor opposite the lift opening doors.



The building has a flat roof with access via the lift motor room. The roof was not accessible during this risk assessment.



Address: Boulton House, Spon Lane, V Bromwich, B70 6BJ	Vest Survey date: 01/03/2023	ON ARRIVAL INFORMATION	
BUILDING LAYOUT			
Size: Width, breadth and height			
Construction	Wates, refurbished 2007/2008, concrete bric	k construction to all 4 elevations of the block.	
Number of floors	9 including ground floor		
Layout	The block consists of 9 storeys (inclusive of the ground floor). Each of the floors contains 4 number dwellings,		
	Lift granting access up to the 7 th floor then us also located on this floor.	se staircase to access the 8^{th} floor and the lift motor room that is	
	2 sets of staircases granting access to all 8 flo	pors of the block located at the front and rear of the block.	
	3 smoke extraction vents located on both sta lobby area nearest the main access point.	3 smoke extraction vents located on both staircases on floors 1, 4 and 7 with the control panel located within the lobby area nearest the main access point.	
Lifts	1		
Types of entrance doors	Individual flat doors are FD30s rated Premdo timber FD30s	rs of composite construction. Communal doors within the block are	
Rubbish chutes/ bin rooms	Yes		
Common voids	No		
Access to roof/ service rooms	The motor room is located on the 8th floor; access to motor room via full height door (secured with a suited 54 mortice lock) from 8th floor landing, with further fixed steel ladder's leading up to the FD30s rated fire door into the roof area.		
Occupants	Approx. 72 based on an average of 2 occupants per flats (36 flats)		
Evacuation strategy	Stay Put Unless- The escape strategy is 'Stay Put Unless'. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire or smoke		
Fire alarm/ evacuation alarm	Early warning is limited to hard wire or battery smoke alarms within each of the resident's flats.		
Caretaker/ concierge	Caretaking/cleaning service that conducts regular checks of the building		
FIREFIGHTING SYSTEM	1S		
Water supplies	Fire hydrant is located at the entrance of the building, fire hydrant location/ water isolation points located on the orientation plan, there is a dry riser that serves the building outlet located on the floor plans.		
Fire mains	The dry riser inlet is located within the groun mortice lock.	The dry riser inlet is located within the ground floor dry riser cupboard (twin valve) secured with a type 54 suited mortice lock.	
Firefighting shafts	No firefighting lifts/shafts however there is the ability to take control of the common lift A Firefighter control switch is located within the ground floor lobby		
Smoke control vents	Automatic smoke ventilation is employed on both sets of staircases on floors 1, 4 and 7 with the control panel located within the lobby area nearest the main access point. Lover vents located atop the staircase on the 8 th floor		
Sprinkler system	A water suppression system is provided to the	ne refuse chute bin store	
DANGEROUS SUBSTA	NCES		
Location, type, and quantity	D.P.C. TO FRONT ELEVATION – BITUMEN – SI	EALED – CHRYSOTILE	
	FLOORS TO ALL LANDINGS - THERMOPLASTIC	C TILES – SEALED – PRESUMED – CHRYSOTILE	
SERVICES			
Electricity	Electric meter cupboards located on each floor of the block		
Gas	Gas isolation points located at nearest the main access point of the block and also on the orientation plan		

The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021.

The enforcing authority is West Midlands Fire Service.

High/Low Rise	High Rise
Number of Floors	9 Including ground floor
Date of Construction	1964
Construction Type	Wates concrete / brick
Last Refurbished	2007/2008
External Cladding	None
Number of Lifts	One
Number of Staircases	Тwo
Automatic Smoke Ventilation to	Yes
communal area	
Fire Alarm System	No
Refuse Chute	Yes
Access to Roof	Access is obtained via the lift motor room on 8 th floor. A vertical ladder leads to a full height door out on to the roof.
Equipment on roof (e.g. mobile phone station etc)	No

Persons at Risk


Residents / Occupants of 36 flats Visitors, Sandwell MBC employees, Contractors, Service providers (e.g. meter readers, delivery people etc) Statutory bodies (e.g. W.M.F.S, Police, and Ambulance)




An orientation plan of the outside of the block and its surrounding areas.


A typical floor layout showing horizontal lines of compartmentation, lift shafts, dry riser installation and AOVs etc.


The plans have been shared with WMFS electronically via their portal.





Below is the typical floor plan for floors 1-7.







External envelope

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.

Details of the external wall construction have been provided to the fire service via the WMFS portal in line with fire safety regulations 2022.

Regarding the external façade, the materials, construction, and their constituent properties have been taken from a database provided by Sandwell Metropolitan Borough Council. A third party approved contractor has been appointed to carry out External Wall Assessments of Sandwell Metropolitan Borough Councils Higher Risk Buildings.

Below is a breakdown of the materials used and whether these or their combination or application present an acceptable level of fire risk.

1) The building is predominantly a traditional concrete masonry construction, last refurbished 2008.



External facade is made up of four materials, concrete 2%, Brick 63%, Glass(main Building) 25%, and Glass to balconies 25% these materials are to an A1 rating and present an acceptable level of risk.

2) There is a ramp leading to the main entrance of the builidng



3) Front and rear entrance/exit is constructed of an aluminium door and frame with double glazing.





4) Bin store is located to the right of the rear entrance/exit to the block and is secured using a bin store padlock with natural ventilation in the form of louvre vents.



5) Residents have access to balconies; balconies are constructed using a cantilevered concrete slab as a base with a steel and Georgian wired glass balustrade.



6) Resident's individual flat windows and balcony doors are double glazed units within a UPVC frame.



7) Communal windows are double glazed units within a UPVC frame and louvre vents at the rear.



8) It was noted that some balconies may have had combustible materials in the form of hanging washing this is deemed acceptable risk due to the likelihood of a fire starting in this area being low and combined with the temporary nature of the activity.



Means of Escape from Fire

1) There are two protected staircases as part of the means of escape. The front and rear staircase measure 980mm - 1000mm in width.



- 2) All corridors are of adequate width (at least 1050mm) and will be maintained clear to that width as a minimum.
- 3) There are no dead end corridors that form part of the means of escape.
- 4) The means of escape are protected to prevent the spread of fire and smoke.
- 5) The communal landing / staircases are protected by use of selfclosing 44mm notional 30-minute timber fire doors with vision panels. All doors have been upgraded with combined intumescent strips / cold smoke seals.



6) All communal doors are fitted with automatic closing devices that are checked on a regular basis by Caretaking Teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).



- All communal fire doors are subject to a 12-week check by the Fire Safety Rapid Response Team.
- 8) The final exit doors have door entry systems installed. These systems are designed to fail safe i.e. door unlocked in the event of a power failure. This prevents residents being locked in or out of the building.



9) Automatic smoke ventilation is employed. This is tested, inspected, and maintained by a competent procured contractor in accordance with BS7346. The frequency for the maintenance checks is twice per year (April and October) of each calendar year. AOV's are located on the 1st,4th, and 7th floor front staircase. Detection for the AOV's is within the communal areas.



10) Louvre vents provide natural ventilation to the rear staircase.



11)Communal windows can only be opened with the use of a key or by operating the automatic smoke vents.



- 12)Communal areas should be kept free of flammable items. The communal areas are checked on a regular basis by Caretaking / Cleaning teams 365 days per year and all items of rubbish are immediately removed. There is also an out of hour's service that allows combustible items of furniture / rubbish to be removed.
- 13)Emergency lighting is provided to communal landings and stairs. Checks are done monthly by Sandwell MBC in house electrical team or approved contractor.



14) Dry riser cupboards are notional 44mm, 30-minute fire doors with combined intumescent strips & cold smoke seals throughout the block.



15) Service/electrical cupboards with lobby areas are notional 44mm 30-minute fire doors, secured with type 54 suited mortice locks through the majority of the block however, service cupboards on the ground floor are notional 54mm 60-minute fire doors.



16) Lift motor room is located on the 8th floor of the block and is protected with a notional 54mm 60-minute fire door secured with a type 54 suited mortice lock.



17) The surface coatings to the communal areas are Class 0 rated.

18) Noted that there are service cupboards housing some stop taps for individual flats protected behind are nominal 44mm 30-minute fire doors, secured with type 54 suited mortice locks.



- 19) The building has sufficient passive controls that provide effective compartmentation to support a Stay Put-Unless Policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them, or they are asked to leave by the emergency services.
- 20) Individual flat doors are predominantly nominal 44mm timber fire door sets with intumescent strips, cold smoke seals and self-closing devices.



21)Access is gained to a sample of properties as part of the fire risk assessment to ensure the flat entrance doors have not been tampered with by residents etc.

Access was gained to flats 34,32 and 13 and found no issues with doors.

- 22) Noted that due to the time of the year that some festive decorations had been displayed on front entrance doors e.g. Christmas wreaths, on the basis that these decorations remain minimal and do not obstruct the means of escape, as this is the case during the FRA, they can remain on a temporary basis. Due to the presence of daily cleaning and caretaking staff to the block the risk of these types of decorations is tolerable, note these are temporary and should be removed in sufficient time once the festive period is over.
- 23) It was noted that fire door keep shut signage had been displayed on the final exit doors, this signage is not required.



24) The refuse chute hoppers are fitted with intumescent strips along the means of escape within the rear stairwell.



25) Smoke control systems kept inside riser cupboards protected by 44mm 30-minute fire doors in the lobby areas of floors 1,4 and 7.





- 1) Early warning is limited to hard wire or battery smoke alarms within each of the resident's flats. The equipment is subjected to a cyclical test.
- 2) Access was granted into a sample of resident's flats. Based on the samples taken, information collated from in house teams (JM) and previous risk assessments the smoke alarms within resident's flats are installed to a minimum of an LD3 Standard.

Flat 32 – Hallway, lounge, kitchen LD2 Flat 22 – Hallway, lounge, kitchen LD2 Flat 14 – Hallway, lounge, kitchen LD2 Flat 34 – All rooms except wet rooms LD1 Flat 13 – Hallway Only – LD3

For information LD1 all rooms except wet rooms LD2 all-risk rooms e.g. Living Room, Kitchens, and Hallway. LD3 Hallway only

- 3) There is no effective means for detecting an outbreak of fire to communal areas. The reason for this are:
 - I. Such systems may get vandalised.
 - II. False alarms would occur.
 - III. A Stay Put Unless policy is in place.
- 4) A sprinkler or deluge system is provided to the refuse chute bin store. An approved contractor maintains the system. The frequency for the maintenance checks are twice per year (April and October) of each calendar year.





- 1) The premises has a sufficient emergency system in accordance with BS 5266 and has test points strategically located.
- 2) The self-contained units are provided to the communal landings, stairs, and lift motor room.



3) All installed equipment is checked and tested monthly by Sandwell MBC in house electrical team or approved contractor, in accordance with current standards. The test completion sheet is in the ground floor lift/flat lobby



Compartmentation

The high degree of fire separation between flats and the common parts is achieved by making each flat a fire-resisting enclosure. This is known as compartmentation. A compartment is simply a part of a building bounded by walls and floors that will resist the passage of fire for a specified period of time. The fire resistance of this construction is such that, normally, a fire will burn itself out before spreading to other parts of the building.

- The building is designed to provide as a minimum 1-hour vertical fire resistance and 1-hour horizontal fire resistance around flats stairwells and lift shafts. All doors are a minimum nominal 30minute fire resistant with intumescent strips & cold smoke seals, including those in 1-hour rated walls.
- 2) The premise has sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire. Whilst the existing fire stopping is fit for purpose, there is a cyclical programme to ensure fire stopping as not been compromised by third parties and where applicable enhance the fire stopping.
- 3) All communal doors are fitted with automatic closing devices that are checked on a regular basis by Caretaking Teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).
- 4) All communal fire doors are subject to a 12-week check by the Fire Safety Rapid Response Team.
- 5) All service cupboards to communal landings have notional fire doors with a minimum of 30 minutes fire resistance upgraded with cold smoke seals ad intumescent strips, locked with suited cylinder or mortice locks.

- 6) A variety of methods / materials have been used to achieve firestopping including Rockwool, fire rated sponge and intumescent pillows.
- 7) The fire stopping / compartmentation is subject to a 12-week check by the Fire Safety Rapid Response Team.
- Any remedial works arising from the fire stopping / compartmentation check(s) will be actioned immediately by the Fire Safety Rapid Response Team.
- 9) Individual flat doors are predominantly nominal 44mm timber fire door sets with intumescent strips, cold smoke seals and selfclosing devices.



 The communal landing & staircases are protected by use of notional self-closing 44mm 30-minute timber fire doors with vision panels & 25mm stops upgraded to have intumescent strips and cold smoke seals.



Definitions Fire Doors.

Notional fire door - A fire door that is thought to have been installed at the time of construction. This door may not meet current building regulation requirements however is still acceptable if performing as originally intended.

Upgraded notional fire door - A notional fire door that has been upgraded. For example, with intumescent strips and cold smoke seals.

Nominal fire door – A fire door that may meet the standards specified within the building regulations but has not been awarded the official certification of doors manufactured and tested by an accredited, third-party testing unit and approved formally with the relevant certificates and documentation.

Certified fire door – A fire door and frame that have been approved and certified by the manufacturer. The door assembly must be installed by a competent person.

11) Access panels to stop taps are fixed to masonry and bedded on Intumescent material. However, in some cases stop taps are housed behind 44mm, 30-minute nominal doors.



- 12) It was noted that metal trunking had been used within the communal areas to house cabling.
- 13) Ground floor communal door nearest flat 4 does not selfclose correctly and door rubs along the bottom of the floor. This was also addressed in the previous FRA.





Fire Fighting Equipment

1) The dry riser inlet cupboard is located in the ground floor lift lobby and is appropriately signed. Access is granted utilising a suited 54 key.



 The riser outlets are available on each floor lobby (1st – 8th) also secured within cupboards by suited 54 key & mortice locks.



- 3) The dry riser is checked regularly as part of the Caretakers duties.
- Maintenance contracts in place to service the valves twice per year (April and October) with a hydraulic test undertaken annually (October) to comply with the requirements of BS9990.
- 5) Portable fire extinguisher (CO2) is provided to the lift motor room. Maintenance contracts in place for maintenance of the extinguisher. The frequency for the maintenance checks are once (October) of each calendar year.



6) Fire hydrant can be located at the front of the building with adequate signage.



7) Bin room is protected by Deluge/sprinkler system and serviced 6monthly.





1) All fire doors display "Fire Door Keep Shut" where appropriate.



2) Fire Action Notices are displayed throughout the building.



3) <u>Yellow LPG warning signs are displayed within the lift cars.</u>



4) Signage depicting the floor location of each flat is fitted to the ground floor lobby wall.



5) Wayfinding Signage depicting floor level and flat numbers are fitted to the wall adjacent to lift. They meet the requirements set out in the Fire Safety (England) Regulations 2022



6) Directional escape signage is displayed within the block.



Employee & Resident Training/Provision of Information


- All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- 2) All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking teams are not currently trained in the effective use of fire extinguishers. The only extinguishers are located within the lift motor room. Caretaking Teams are not expected to tackle fires in this area.
- 4) Staff undertaking fire risk assessments are qualified to Level 4 Diploma in Fire Safety.
- 5) Fire safety information has been provided as part of tenancy pack.
- 6) Building safety and evacuation notices are displayed in common areas and lift cars.



7) Information regarding use of fire doors and the Stay Put Unless fire evacuation strategy is provided to residents.



8) Information regarding building safety is contained within a Building Safety Notice. This is displayed in the ground floor lift lobby.





Sources of Ignition

1) Smoking is prohibited within any communal parts of the building in line with Smoke Free England legislation.



- 2) Hot working is not normally conducted. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager Bryan Low.
- 4) The fixed electrical installation shall be tested every 5 years. It was noted that the last inspection was 18/12/2021.
- 5) The electrical installation i.e. risers are contained within dedicated service cupboards that are secure and protected by means of a notional 44mm 30-minute fire door to majority of the building apart from the ground floor which utilises 54mm 60-minute notional fire doors both have been upgraded to have intumescent strips and cold smoke seals.
- 6) There is lightening protection installed to the block. Maintenance contracts are in place for lightning conductor testing in accordance with BS 6651.
- 7) Portable heaters are not allowed in any common parts of the premises.

8) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the in-house Gas Team. Gas is installed within the block.



1) There is a regular Cleaning Service to the premises.



- 2) Refuse hoppers are accessed on each floor of the rear staircase.
- 3) Refuse containers regularly emptied bin store located at the rear elevation of the block.



- 4) Regular checks by Caretakers minimise risk of waste accumulation.
- 5) 'Out of Hours' service in place to remove bulk items.

Control and Supervision of Contractors and Visitors

- Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
- 2) Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
- 3) Utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the Investments office @ Roway Lane. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
- 4) Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
 - a) Pre-Contract Meetings where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
 - Health and Safety.
 - Site security.
 - Safety of working and impact on children/school business.
 - Fire risk, if any.
 - Site Emergency Plan.
 - b) Monthly Site Meetings in order to monitor, review and share any new information including any new risks.
 - c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
 - d) Final Contractor review on completion of works undertaken.



- Regular checks are undertaken by Caretakers / Cleaning Team(s) 365 days per year which helps reduce the risk of arson.
- 2) Restricted access to the premises by means of a door entry system.



- 3) There are no provisions for CCTV within the block.
- 4) There is no current evidence of arson within the block. Noted slight damage to a combination frame on the 6th floor front elevation stairwell. This was highlighted in the previous FRA and has had no further damage.



- 5) The perimeter of the premises is well illuminated with external lighting and street lighting.
- 6) There have been no reported fire incidents since the last FRA.



- Residents instructed not to bring L.P.G cylinders into block. (Notice displayed in lifts)
- 2) The tenancy conditions, Section 7 Condition 5.6 stipulates "If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use."
- 3) No Flammable liquids stored on site by Caretakers / cleaners.
- 4) All store cupboards are kept locked.
- 5) There are no flammable liquids or gas cylinders stored on site.

Additional Control Measures; Fire Risk Assessment - Action Plan

Significant Findings

Action Plan

It is considered that the following recommendations should be implemented to reduce fire risk to, or maintain it at, the following level:

Trivial \boxtimes Tolerable \square

Definition of priorities (where applicable):

P1 Arrange and complete as urgent – Within 10 days

P2 Arrange and complete within 1-3 Months of assessment date

P3 Arrange and complete within 3-6 Months of assessment date

P4 Arrange and complete exceeding 6 months under programmed work



Fire Risk Assessment Action Plan



Name of Premises or Location:

Boulton House

Date of Action Plan:

04/12/2024

Review Date:

<Insert date>

Question/ Ref No	Required Action	Supporting photograph	Priority	Timescale and Person Responsible	Date Completed
10/13	Ground floor communal door nearest main entrance, make good door so it self–closes correctly.		P2	1-3 months Fire Rapid Response	

When undertaking future improvement program(s), it is advised that the observations listed below should be given consideration (noting that the safety of the residents is not jeopardised by these, and all steps to reduce any known risks have been taken).

Observations

Some notional communal landing doors are starting to show signs of general wear and tear due to age. Consideration should be given to upgrade with certified FD30s door sets & combination frames with future improvement works. It was noted that the doors have had no significant change since the previous FRA was completed.



Signed

Hermany	Fire Risk Assessor	Date: 04/12/2024				
Chill	Quality Assurance Check	Date: 16/12/2024				

Appendix 1

Significant Hazards on Site and Information to be Provided for the Fire Service

Name of property: Boulton House

Updated: 20/10/2023

Premise Manager: Tony Thompson

Tel. No.: 0121 569 2975

Hazard	Information/Comments
Asbestos	An asbestos survey has been undertaken of the communal areas. Survey held by Sandwell Housing (Derek Still <u>Tel:-</u> 0121 569 5077). <i>Include survey</i>

Asbestos Survey	Property Address 1-36 Boulto	on He	ouse, Spon Lane, West Bromwich			√ Office use
Surveyed by JOHN DAVIS Date 04/03/14			Checked by DEREK STILL	Desktop Cheo	:k √	Site Check
Reason for request	HSG 264 - Survey Report Typ	pe	Date 29/12/2014	010		
Investment Void	Refurbishment Survey		Property Description			
Investment Tenanted	Management Survey	\checkmark		liter.		
R & M Void	SHAPE Interrogated.	\checkmark				
R & M Tenanted	No Existing SHAPE Data.		9 STOREY HIGH RISE BLOCK			
Medical / Emergency - Heating Works	Existing SHAPE Data.	<				
Communal Area 🗸	Refurb Surveys Interrogated ?			Year B	uilt	1962
The Edit Options Help EL448065021 Buildon House 1:38 (ok Survey Date 24/05/2006 Difficer (PAR) Kit Loc Consonent Tasc Cond From Coned From Coned From Cone DECIT NAD COM DECI N	Condition Risk Level Historical C Al Condition Risk Level Historical A GGDD NONE no GGDD NONE no GGDD NONE no LOW NONE no LOW NONE no GGDD NONE no GGDD NONE no GGDD NONE no GGDD NONE no GGDD NONE no		UPDATED 04/03/14 – JOHN DAVIS ***SAMPLES TAKEN TO GENERIC TEXTUR AND 8 TH FLOORS – PRESUME ALL NEGATIV Reviewed by G.Carrington – 10/06/2022 REVISED DEREK STILL 20/10/2023 ALL FRO Building Surveyors 0121 569 5077	Asset Teal Operatio	EALANT	

Sample Locations		roperty ddress	1-36 Boulton House, Spon Lane, West Bromwich										
LOCATION		MATERIAL		QTY	SURFACE TREATMEN	T SAMPLE REF		RESULT	HSE NOTIF Y	C AC		TON TAKEN CONTRACT	ON
IF DURING THE COURSE OF WOR	K SUSPECTE	D ACM'S A	ARE ID	DENTIFIE	D THAT ARE NO	T CONTAINED	WIT	HIN THIS REP	ORT ST	OP W	ORK & S	EEK ADVIC	E
8 [™] FLOOR COMMUNAL WALLS	TEX	TEXTURED COATING		-	PAINT SEALED	PA 451 / 002	N	ONE DETECTED	NO	NO			
4TH FLOOR COMMUNAL WALLS	TEX	FURED COAT	FING	-	PAINT SEALED	PA 451 / 003	N	ONE DETECTED	NO	NO			
1 ST FLOOR COMMUNAL WALLS	TEX	FURED COAT	FING	-	PAINT SEALED	PA 451 / 004	N	ONE DETECTED	NO	NO			
D.P.C. TO FRONT ELEVATION		BITUMEN		-	SEALED	PA 451 / 005		CHRYSOTILE	NO	NO			
FLOORS TO ALL LANDINGS	THER	THERMOPLASTIC TILES		-	SEALED	PRESUMED		CHRYSOTILE	NO	NO			
ITEMS SHOWN BELOW HAVE BEEN ASSESSED ON SITE BY THE ASBESTOS SURVEYOR & ARE CONFIRMED NOT TO BE ACM'S.													
LOCATION DESCRIPTION MATERIAL LOCAT		TION DESCRIPTION		MATERIAL		LOCATION DESCRIPTION		MATERI	AL				
LIFT MOTOR ROOM EXTERNAL SOFFIT	PLASTIC	8™ F	LOOR	LANDING CEILING PANELS		SUPALUX		EXTERNAL PANELS ABOVE FRONT AND REAR ENTRANCE DOORS		MAN MADE M FIBRE			
PANEL BELOW ROOF ACCESS DOOR SUPA		8 TH	8 TH FLOOR ELECTRI CEILING			SUPALUX		MAIN ROOF PARAPET		STEEL			
LIFT MOTOR ROOM CEILING PANELS	MAN MADE MINERAL FIB			RIC CUPBOARDS WALL BLANKING PLATES		SUPALUX		ALL FRONT DOOR SEALANTS		SILICO	N		
LIFT MOTOR ROOM FLOOR TRAP PANEL	SUPALUX	E			RDS CEILING _ATES	SUPALUX							
LIFT MOTOR ROOM COVERING	MINERAL FEI	.T GR	OUND	FLOOR REAR ENTRANCE CEILING		SUPALUX							
STOP TAP COVER PANELS TO LANDING WALLS BY FLAT FRONT DOORS	SUPALUX	GRO			NT ENTRANCE	SUPALUX							

ABOUT THE REPORT - PLEASE READ

All Survey Methodology is based upon HSE document HSG 264 - Asbestos: The Survey Guide. All surveyors are experienced British Occupational Hygiene Society (BOHS) P402 qualified surveyors with extensive Surveying & Refurbishment Project experience specific to Sandwell MBC's managed housing stock.

The person or persons using this report to programme refurbishment work on site are assumed to be competent & experienced in the field of domestic refurbishment projects & have suitable & sufficient asbestos awareness to understand the scope of this report & apply it to the project. All trade operatives working on site are also expected to have relevant asbestos awareness training & experience. IF IN DOUBT STOP & ASKI Please ensure the report covers the areas that you need to work on. SHAPE: Sandwell MBC's Integrated ICT solution holds the Company Asbestos Register. The Asbestos Register is the thereograted when completing the asbestos survey report to ensure that ACMS in similar properties are considered where relevant. The Register holds cleals of all suspected or confirmed ACMS is identified during Refurbishment & Demolition programmes as well as Preparis activities for the past 11 years. If potential ACMS have been identified within difficult to survey areas such as Cavity Walls, Floor Voids etc these will be highlighted within the report. The interogation of the Company Asbestos Register compliances it does not substitute the Refurbishment & Demolition Survey.

Void Properties – The Building Surveying team who undertake Refurbishment & Demolition Asbestos Surveys also undertake Domestic Energy Assessment Surveys, Boroscope Surveys for Thermal Insulation & Fire Integrity Assessments to a representative percentage of the void turn over.

Site Overview Page 2 – This section is included to aid surveying & to ensure comprehensive survey information is detailed.

Term	Explanation	Term	Explanation			
Property Address	Specific Property to which survey relates.	Photo's	These will usually be provided for the front elevation of the property to aid identification.			
Surveyed by	Relates to P402 trained surveyor.	Sampled by	P402 trained surveyor.			
Action taken on Project	Record what action may have been undertaken to the Asbestos in question. E.g. Nothing, Repair, replace, Manage.	Checked by	P402 trained surveyor who checks report prior to issuing.			
Type of Work to be undertaken	Relates to the envisaged type of work that the Asbestos Survey Report will be used to aid. This assists the asbestos surveyor to guide his survey methodology & will help the users of this report decide if it is suitable for the work activity being undertaken.	Survey Report Type	Report type is determined by the type of work to be undertaken. The reader of this report must satisfy themselves that the scope of the survey is sufficient for the purpose of work being undertaken.			
ACM	Asbestos Containing Material.		HSG 264 - Refurbishment & Demolition Survey. Surveying undertaken to all parts of the property presuming full decent homes refurbishment, which may include. New Kitchen, New Bathroom.			
HSE Notify	This highlights if a material normally requires notification to the Health & Safety Executive prior to removal. GUIDANCE ONLY.	Refurbishment Survey	Electrical Rewire, Re-roof, Full Heating System. Taking account of the complete structure of the property & archetype information available. This survey has been carried out without detailed knowledge of the works to be undertaken during refurbishment. Anyone using this report to suppor building works being undertaken to the property should ensure that the report is sufficient for the survey has the super survey of the super structure of the survey has the survey of the			
Bulk Sample	Sample of potential ACM that is representative of the whole.		purposes of the building work being undertaken. The reader should be confident that the areas that are to be disturbed by the proposed work are included.			
Request Sample	The item described has not been tested for Asbestos content. The item must be presumed to contain asbestos until sampling confirms. If work is going to be undertaken in this area sample should be requested prior to work starting.	Management Survey	A management survey is the standard survey. Its purpose is to locate, as far as reasonably practicable, the presence and extent of any suspect ACMs in the building which could be damaged or disturbed during normal occupancy, including foreseeable maintenance and installation, and to assess their condition.			
Awaiting Results	If no results have been detailed then you must not work on these items until you receive further confirmation.	Refurb & Management Survey	Both Survey Report Types are ticked due to works identified at survey stage the surveyor has completed Retrubishment Survey for the works required & may have undertaken a management survey on remaining areas of the property. The report should not be used for works outside the scope stated, unless the reader assures themselves that it is suitable & sufficient.			
Extent	An estimate of quantity will be given where possible to aid work planning & valuation.	Cavity Walls / Floor Voids or similar.	Will be assessed at survey stage & desktop assessment of similar archetypes.			
Labels	Materials will be labelled where practical. Labelling will be not be undertaken to low risk materials e.g. floor tiles, Textured Coatings etc or where labelling could easily be removed or would cause potential exposure if removed. All presumed ACMs will be labelled as "Asbestos" where practical. All sampled materials will be labelled with an "Asbestos Sampled" label.	Photo's	Where practical & to aid the identification of ambiguous material locations photos will be included within the report to ensure that materials are identified on-site correctly. Photos will be annotated where necessary.			

IF IN DOUBT CONTACT THE BUILDING SURVEYING TEAM

Version 2.0 – 8th January 2013 © Sandwell MBC