


# Fire Risk Assessment

## Harry Price House

Hartlebury Rd, Oldbury,  
B69 1EQ



**Date Completed:** 15/05/2025.

**Review Period:** 12 months

**Officer:** A.Froggatt. **Building Safety Manager.**

**Checked By:** Anthony Smith **Team Lead Building Safety**

**Current Risk Rating = Tolerable**

**Subsequent reviews**

<b><u>Review date</u></b>	<b><u>Officer</u></b>	<b><u>Comments</u></b>

---

## Contents

<a href="#">Section 0</a>	<b>Introduction</b>	
<a href="#">Section 1</a>	<b>Significant Findings (executive summary)</b>	
<a href="#">Section 2</a>	<b>People at Significant Risk of Fire</b>	
<a href="#">Section 3</a>	<b>Contact Details</b>	
<a href="#">Section 4</a>	<b>Description of Premises</b>	
<a href="#">Section 5</a>	<b>Building Plan</b>	
<a href="#">Section 6</a>	<b>External Envelope</b>	
<a href="#">Section 7</a>	<b>Means of Escape from Fire</b>	
<a href="#">Section 8</a>	<b>Fire Detection and Alarm Systems</b>	
<a href="#">Section 9</a>	<b>Emergency Lighting</b>	
<a href="#">Section 10</a>	<b>Compartmentation</b>	
<a href="#">Section 11</a>	<b>Fire Fighting Equipment</b>	
<a href="#">Section 12</a>	<b>Fire Signage</b>	
<a href="#">Section 13</a>	<b>Employee Training</b>	
<a href="#">Section 14</a>	<b>Sources of Ignition</b>	
<a href="#">Section 15</a>	<b>Waste Control</b>	
<a href="#">Section 16</a>	<b>Control and Supervision of Contractors and Visitors</b>	
<a href="#">Section 17</a>	<b>Arson Prevention</b>	
<a href="#">Section 18</a>	<b>Storage Arrangements</b>	
<a href="#">Section 19</a>	<b>Additional Control Measures. Fire Risk Assessment – Action Plan</b>	
<a href="#">Appendix 1</a>	<b>Significant Hazards on Site and Information to be provided for the Fire Service Risk Rating of Block</b>	

---

## Section

# 0

## Introduction

---

The [Regulatory Reform \(Fire Safety\) Order 2005 \(RR\(FS\)O\)](#) places a legal duty on landlords to complete a fire risk assessment (FRA). Specifically, RR(FS)O article 9. — (1) *“The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order”*.

This type 1 fire risk assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on <https://www.wmfs.net/our-services/fire-safety/#reportfiresafety>. In the first instance however, we would be grateful if you could contact us directly via [https://www.sandwell.gov.uk/info/200195/contact\\_the\\_council/283/feedb](https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedback_and_complaints)  
[ack and complaints](https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedb) or by phone on 0121 569 6000.

The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation, but the Council will as a minimum review:

- High Risk Residential Buildings annually
- Other Buildings every 3 years

The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment. If the review suggests the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.

The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.


---



The above processes and procedures are overseen by the Fire Safety, Manager who reports to the Head of Building Safety

These managers attend the Building Safety and Compliance Group for scrutiny which is part of the governance structure below.

Governance Structure



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire. This is recorded here in [section 1](#). Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring and review of the preventative and protective measures. The information shown above is part of this requirement.

---

## Section

# 1

## Significant findings

---

The significant findings (executive summary) of this Type 1 fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005.

Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors and contractors unfamiliar with the building layout as well as those with physical, sensory or mental health issues.

A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring and review of the preventive and protective measures. These are shown in the introduction.

### **Significant findings**

*Include a brief summary of protective and preventative measures where relevant along with any issues found;*

The escape strategy is '**Stay Put Unless**'. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire, smoke or you have been advised by the emergency services to leave.

---

Section number	Section Area	Individual Risk Level
<a href="#">Section 6</a>	<b>External Envelope</b>  Brickwork up to 1 <sup>st</sup> floor – Ibstock Rockshield brick slips. Above 1 <sup>st</sup> floor mixture of insulated Alsecco mineral wool render (Fire Classification A2) and high density Stonewool Panels by Rockwool (Fire Classification A2-s1,d0). Vertically aligned balconies of steel and concrete construction with high density stonewool panels.	Trivial



<a href="#">Section 7</a>	<p><b>Means of Escape from Fire</b></p> <p>There is a single protected staircase that provides a sufficient means of escape.</p> <p>AOVs are present on all floors above a ground floor. At the time of the assessment a red fault light was indicated. Email sent to Jason Blewitt 15-05-25. Visit by Prestige Protect Systems 15-05-25. System checked and re-set, system recorded as 'healthy'.</p> <p>The escape routes from both rear fire exits are covered in pigeon excrement creating a potential slip hazard. These areas should be cleaned. Email sent to Estates Manager. 20.05.25.</p> <p>Flat 10 has a damaged frame.</p> <p>Flat 16 has a damaged frame and door leaf and an excessive leaf side gap requiring repair</p> <p>Flat 25 has an excessive leaf side gap.</p>	<p>Tolerable</p>
<a href="#">Section 8</a>	<p><b>Fire Detection and Alarm Systems</b></p> <p>Fire detection within flats is installed to LD2 standard.</p> <p>There is an automatic fire alarm panel for the server room. No test certification was available.</p> <p>The bin room is provided with a suppression system.</p>	<p>Tolerable</p>

<a href="#">Section 9</a>	<p><b>Emergency Lighting</b></p> <p>The premises have a sufficient central fed supply emergency lighting system.</p>	<p>Trivial</p>
<a href="#">Section 10</a>	<p><b>Compartmentation</b></p> <p>The building is designed to provide as a minimum 1-hour vertical fire resistance and 1-hour horizontal fire resistance around flats stairwells and lift shafts.</p> <p>Communal &amp; flat entrance doors are 30-minute nominal fire doors with intumescent strips &amp; cold smoke seals, including those in 1-hour rated walls.</p> <p>Compartmentation in the main incoming electrical supply plant room is insufficient.</p> <p>There is light timber panelling in the storeroom off the main entrance and the caretaker's room, requiring investigation.</p> <p>There is panelling in a corridor ceiling on floor 11 requiring investigation.</p> <p>There are gaps around panelled ducting in the far ground floor corridor at high level.</p> <p>The door to the caretaker's room requires a self-closing device to be fitted.</p> <p>There is a damaged fire door in the caretaker's office requiring repair.</p>	<p>Tolerable</p>

<a href="#">Section 11</a>	<b>Fire Fighting Equipment</b>  There is a fire hydrant adjacent the front main entrance.  The dry riser inlet is in the main entrance foyer.  The dry riser serves all floors above ground.  There is a C02 fire extinguisher within the lift motor room and server room.  There is a fire suppression system in the bin store.  Maintenance contracts are in place to service the dry riser, chute closure plate & suppression system twice yearly and the fire extinguishers annually.	Trivial
<a href="#">Section 12</a>	<b>Fire Signage</b>  Sufficient signage is displayed throughout the building.	Trivial
<a href="#">Section 13</a>	<b>Employee Training</b>  All staff receive basic fire safety awareness training.	Trivial

---

<a href="#">Section 14</a>	<b>Sources of Ignition</b>  <p>The fixed electric tests should be carried out every 5 years. Last inspection was within 5 years, dated as 24-07-24 marked as Satisfactory.</p> <p>There are exposed electrical wires in the top floor electrical cupboard.</p>	Tolerable
<a href="#">Section 15</a>	<b>Waste Control</b>  <p>Regular checks by Caretakers minimise risk of waste accumulation.</p> <p>Refuse containers are secured within the bin store at lower ground level.</p>	Trivial
<a href="#">Section 16</a>	<b>Control and Supervision of Contractors and Visitors</b>  <p>Contractors are controlled centrally, and hot works permits are required where necessary.</p>	Trivial
<a href="#">Section 17</a>	<b>Arson Prevention</b>  <p>A door entry system prevents unauthorised access.</p> <p>Perimeter lighting is in place.</p> <p>CCTV is in operation.</p>	Trivial

<a href="#">Section 18</a>	<b>Storage Arrangements</b>  There is a caretaker's store located on the ground floor.  Residents instructed not to bring L.P.G cylinders into block.	Trivial
----------------------------	---	---------

### Risk Level Indicator

The following simple risk level estimator is based on commonly used risk level estimator:

Likelihood of fire	Potential consequences of fire		
	Slight harm	Moderate harm	Extreme harm
Low	Trivial risk	Tolerable risk	Moderate risk
Medium	Tolerable risk	Moderate risk	Substantial risk
High	Moderate risk	Substantial risk	Intolerable risk

Considering the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Low ☐      Medium ☒      High ☐

In this context, a definition of the above terms is as follows:

**Low**                      Unusually low likelihood of fire because of negligible potential sources of ignition.

**Medium**                Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).

**High**                    Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

---

Considering the nature of the premises and the occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:

Slight Harm ☒    Moderate Harm ☐    Extreme Harm ☐

In this context, a definition of the above terms is as follows:

<b>Slight harm</b>	Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).
<b>Moderate harm</b>	Outbreak of fire could foreseeably result in injury including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.
<b>Extreme harm</b>	Significant potential for serious injury or death of one or more occupants.

Accordingly, it is considered that the risk to life from fire at these premises is:

Trivial ☐    Tolerable ☒    Moderate ☐    Substantial ☐    Intolerable ☐

---

## Comments

In conclusion, the likelihood of a fire is at a medium level of risk prior to the implementation of the action plan because of the potential fire hazards that have been highlighted within the risk assessment. Notably poor fire stopping in the main incoming electrical plant room.

After considering the use of the premise and the occupants within the block, the consequences for life safety in the event of a fire would be slight harm. This is due to there being sufficient compartmentation to include nominal FD30s doors to flat entrances & communal corridors / landings, alongside suitable smoke detection to a minimum of LD2 standard within flats and a Stay Put – Unless policy.

Overall, the level of risk at the time of this FRA is tolerable, this will be lowered to trivial once recommended actions have been completed.

A suitable risk-based control plan should involve effort and urgency that is proportional to risk. The following risk- based control plan is based on one that has been advocated for general health and safety risks:



Risk level	Action and timescale
Trivial	No action is required, and no detailed records need to be kept.
Tolerable	No major additional fire precautions are required. However, there might be a need for reasonably practicable improvements that involve minor or limited cost.
Moderate	It is essential that efforts are made to reduce the risk. Risk reduction measures, which should take cost into account, should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
Substantial	Considerable resources might have to be allocated to reduce the risk. If the premises are unoccupied, it should not be occupied until the risk has been reduced. If the premises are occupied, urgent action should be taken.
Intolerable	Premises (or relevant area) should not be occupied until the risk is reduced.

***(Note that, although the purpose of this section is to place the fire risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)***

## Section

# 2

## People at Significant Risk of Fire

---

Persons at significant risk of fire does not just refer to those people with physical, sensory or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council takes the health, safety and wellbeing of its colleagues, contractors, residents and leaseholders seriously. It is our policy to exceed, where possible, the minimum health and safety requirements of the law.

Residents are responsible for letting us know whether they might need a Personal Emergency Evacuation Plan (PEEP). The Resident Engagement Officers (Fire Safety) will conduct an assessment visit upon request. Any risk-reduction measures that are found where a PEEP is necessary and completed will be documented and taken quickly. With the consent of the resident, we will make a referral for West Midlands Fire Service to conduct a Safe and Well visit.

When a PEEP is in place, the relevant information will be kept in the secure Premise Information Box (High Rise Buildings only), which is set up to help WMFS in an emergency. The data is classified as level 1, which means it complies with the General Data Protection Regulations.

---

## Section 3

### Contact Details

---

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.

The Chief Executive has put a structure in place to support the management of the site.

This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

**Chief Executive**

Shokat Lal

**Executive Director of Place**

Alan Lunt

**Assistant Director Asset Management & Improvement**

Sarah Agar

**Building and Fire Safety Manager**

Tony Thompson

**Team Lead Fire Safety**

Jason Blewitt

**Team Lead Building Safety**

Anthony Smith

**Building Safety Managers**

Adrian Jones

Andrew Froggatt

Carl Hill

Louis Conway

**Resident Engagement Officer - Fire Safety**

Abdul Monim Khan

Ethan Somaiya

Hannah Russon

**Housing Office Manager**

Rachel Price

*Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change*

---

## Section 4

### Description of Premises

Harry Price House,  
Hartlebury Rd, Oldbury,  
B69 1EQ

#### Description of the Property

This high-rise block was designed & constructed in approximately 1961 for general needs housing, utilising a concrete frame with Wimpey no fines / brick infill along with a flat roof construction. A steel framed pitched roof with aluminium standing seam boards was added during 2018 refurbishment works.



The block consists of 13 storeys (inclusive of the ground floor). The ground floor has a total of five number dwellings all of which are left void, incomplete and unoccupied. Each of the floors from the first to 11<sup>th</sup> floors contain 6 number dwellings (3 each side). The 12<sup>th</sup> floor has 2 number dwellings and access to the roof. The total number of dwellings is 68 not including the 5 void flats.



Harry Price House	
12th Floor	69-70
11th Floor	63-68
10th Floor	57-62
9th Floor	51-56
8th Floor	45-50
7th Floor	39-44
6th Floor	33-38
5th Floor	27-32
4th Floor	21-26
3rd Floor	15-20
2nd Floor	9-14
1st Floor	3-8
Ground Floor	1, 2, 71-73

There is a single staircase which provides a sufficient means of escape.



The block has a main entrance/exit to the front and a further two entrances / exits located on the rear elevation which includes one from the stairwell.



Each entrance is accessed using a door entry system with a fob reader. Additionally, there is a firefighter override switch to the front entrance only that is operated by use of a drop latch key.




There are two lift cars both of which serve alternate floors, but travel is limited to floor 11. The 12<sup>th</sup> floor is accessed via the internal staircase. The capacity for each lift is 8 persons or 600kg.

---



There is a Caretakers / Cleaners Welfare Office and general storage room located on the ground floor; access is obtained utilising the suited 54 lock key.






There is a server room which is accessed internally from the caretaker's welfare room. Access is gained to the room via the Fire Control switch or by contacting the concierge. The server room has its own fire alarm panel / system.



The incoming electrical supply and battery system for the emergency lighting are housed in a service cupboard accessed externally left of the main entrance to the building.



## On arrival Information (for WMFS)



There is a firefighter's white box externally to the left-hand side of the main entrance to the front of the building. The box contains all keys for the building and is secured with a bridge-door padlock.






Access to the building is gained via the firefighter's door override switch utilising the drop latch key from the white box.



There is a Secure Premise Information Box (PIB) located in the ground floor front entrance lobby. It is a Gerda box that utilises a standard WMFS suited key held on each fire appliance. The PIB contains floor plans, vertical plans, orientation plans, information for WMFS and a plan to indicate the location of those with vulnerabilities who may require additional consideration if there is a fire incident (PEEP).




The fire hydrant is left of the main entrance in the grass.




There is a dry riser system at Harry Price House. The riser inlet is to the right-hand side in the main entrance foyer and is secured with a fire service bridge door padlock.



Dry riser outlets are available on each floor above ground opposite the stairwell door / in lift the lobby. The outlets are contained within a dry riser cupboard that is secured with a type 54 suited mortice lock.



The bin store is located to the side of the main entrance and is installed with a fire suppression system, with flashing beacon and an automatic closer plate.




Automatic Opening Vents (AOV) have been installed to the head of protected staircase and in each corridor above the ground floor. The status panel is in the entrance foyer whilst override controls are in a service cupboard on each floor above ground.



There is a firefighter's lift override switch for each lift between the ground floor lift cars. This is operated by the drop latch key.



The lift motor room is accessed via a full height door on the 12<sup>th</sup> floor. The key is contained in the firefighter's white box.





Access to the roof void is gained on the 12<sup>th</sup> floor (from either wing) via a full height timber door secured with a suited 54 mortice lock.



There are access panels in each void (secured with tower bolts) in the glazed section of the roof loft cladding to facilitate access to the abseil points.



The roof void adjacent the lift motor room has a photovoltaic system installed. The solar PV system panels are directly above on the outer roof.



The void adjacent to the lift motor room facilitates access via a looped ladder up to the elevated upper roof void. Access is restricted by a further timber door secured with a suited 54 mortice lock.



## Fire Risk Assessment

Address: Harry Price House Hardbury, Road B69 1EQ	Survey date: 25/05/2023	ON ARRIVAL INFORMATION
<b>BUILDING LAYOUT</b>		
Size: Height	32.2 metres – 13 Storeys	
Construction	Locally concrete frame with Wimpey no fines concrete / brick infill. Brickwork to the 1 <sup>st</sup> floor (Ibstock Backfield Brick Slips). Above 1 <sup>st</sup> floor there is a mixture of insulated <del>Alsecco</del> mineral wool render (fire classification A2) and high density <del>Stonwool</del> Panels by Rockwool (fire classification A2).	
Number of floors	13 floors	
Layout	The block consists of 13 storeys (inclusive of the ground floor). Each of the floors from the 1 <sup>st</sup> to 11 <sup>th</sup> floors inclusive contain 6 number dwellings (3 each side). The 12 <sup>th</sup> floor has 2 number dwellings and provides access to the roof. Roof void is accessed via full height timber doors on the 12 <sup>th</sup> floor. The ground floor consists of an entrance lobby, lift lobby, voids, and caretaker areas. The ground floor has a total of five number dwellings all of which are incomplete and unoccupied. The block has 3 entrance/exits. Main access point at the front elevation and a further 2 access point at the rear of the block. Main access point has a drop latch system granting access to the building. Server room that is accessed externally from the side elevation of the block. 2 lifts and 1 staircase serve the building. The lifts serve alternate floors serving till the 11 <sup>th</sup> floor and the staircase serves all floors. Stairwell is of concrete construction and is protected with good compartmentation provided. The block is split in the middle via the lift lobby areas with 3 flats to the left and right-hand sides of the lobby compartmented via a FD30S timber door.	
Lifts	2 lifts serve alternate floors. Both lifts can be accessed from the ground floor lift lobby. Lift override switch located on the ground floor.	
Types of entrance doors	Flat doors are predominantly FD30s composite doors sets with the exception of some timber flush FD30s doors.	
Rubbish chutes/ bin rooms	Yes, secured behind nominal timber fire doors and with natural ventilation coming by means of louver vents and ventilation system.	
Common voids	Yes in roof accessed from 12 <sup>th</sup> floor.	
Access to roof/ service rooms	Access to roof is via full height timber doors secured with suited 54 lock on the 12th floor leading out on to the roof. The roof is split into two halves with a separate door to each. The upper roof can be accessed via the vertical looped ladder and through full height timber door secured with a suited 54 mortice lock. The lift motor room is located on the 12 <sup>th</sup> floor; access is obtained via a full height door (secured with a suited mortice lock) from the communal landing.	
Occupants	Approx. 132 based on an average of 2 occupants per flats (68 flats)	
Evacuation strategy	Stay Put Unless- The escape strategy is "Stay Put Unless". This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building, you should stay put unless you are affected by fire or smoke	
Fire alarm/ evacuation alarm	The building consisting of early warning limited to hard wire or battery smoke alarms within each of the resident's flats.	
Caretaker/ concierge	Caretaking/cleaning service that conducts regular checks of the building	
<b>FIREFIGHTING SYSTEMS</b>		
Water supplies	Fire hydrant is located at the main entry/ exit to the building, fire hydrant / water isolation points located on the orientation plan, there is a dry riser that serves the building outlet located on the floor plans provided.	
Fire mains	The dry riser inlet (twin valve) is located on the ground floor of the block and can be located on the floor plans.	
Firefighting shafts	No firefighting lifts/shafts however there are two lifts serving adjacent floors of the block that can be controlled.	
Smoke control vents	Automatic smoke ventilation is employed with the controls to each smoke vent located in the service cupboards on each floor. With a repeater panel on the ground floor showing the status of each vent and a master control switch located adjacent this.	
Sprinkler system	A drenching system is provided to the refuse chute bin store.	
<b>DANGEROUS SUBSTANCES</b>		
Location, type, and quantity	LIFT MOTOR ROOM 300mm DIA PIPE - CEMENT - SEALED - PRESUMED - CHRY30TILE	
<b>SERVICES</b>		
Electricity	Server room that is accessed externally from the side elevation of the block, service cupboards located on each floor of the block. Solar PV system in roof void.	
Gas	Gas service risers are external to the building. Isolation points can be located via the orientation plan.	

The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021.

The enforcing authority is West Midlands Fire Service

High/Low Rise	High
Number of Floors	13
Date of Construction	1961
Construction Type	Concrete frame, Wimpey no fines / brick infill.
Last Refurbished	2018/19
External Cladding	Brickwork up to 1 <sup>st</sup> floor – Ibstock Rockshield brick slips Above 1 <sup>st</sup> floor mixture of insulated Alsecco mineral wool render (Fire Classification A2) and high density Stonewool Panels by Rockwool (Fire Classification A2-s1,d0), Balcony balustrades are also Rockwool Stonewool panels.
Number of Lifts	2
Number of Staircases	1
Automatic Smoke Ventilation to communal area	Yes
Fire Alarm System	Server room only.
Refuse Chute	Yes
Access to Roof	Access to roof is via full height timber doors on the 12 <sup>th</sup> floor leading on to the lower roof voids. The roof is split into two halves with a separate door to each. The upper roof can be accessed via the vertical looped ladder and through full height timber door.
Equipment on roof (e.g. mobile phone station etc)	Solar PV panels

---

**Persons at Risk**

Residents / Occupants of 68 flats (5 flats to ground floor are void incomplete / unoccupied),

Visitors,

Sandwell MBC employees,

Contractors,

Service providers (e.g. meter readers, delivery people etc)

Statutory bodies (e.g. W.M.F.S, Police, and Ambulance)




## Section 5

### Building Plan


A typical floor layout showing horizontal lines of compartmentation, lift shafts, dry riser installation and AOVs etc.

The plans have been shared with WMFS electronically via their portal.

#### Ground Floor



#### Typical Upper Floor





## Section

# 6

## External envelope

---

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.

Details of the known external wall construction have been provided to the fire service via the WMFS portal in line with fire safety regulations 2022.

An appraisal of the external wall construction including balconies, windows and doors has been undertaken in accordance with the flow chart detailed in PAS 9980:2022 – Fire Risk Appraisals of External Walls (FRAEW) for existing multi-story, multi-occupied residential buildings. This FRAEW was undertaken by Firntec Building Compliance in November 2024, review date recommended for November 2029. The outcome of the appraisal was low risk.

The combination of the materials to the external wall system (listed below) that were installed during the 2018 refurbishment of the building in conjunction with a non-combustible mineral wool insulation present an acceptable level of fire risk.



1) Harry Price House has three separate areas of cladding consisting of;

- Ibstock Brick-slips up to 1<sup>st</sup> floor level.
  - Alsecco EWI Mineral Wool Render (Class A2)
  - High Density Stone Wool Panels (Class A2-s1, d0) including to balconies.
-

- 2) The steel framed pitched roof with aluminium standing seam core panels was constructed over the original flat roof during the 2018/19 refurbishment works.



- 3) Windows & balcony doors to flats are double glazed powder coated aluminium externally and timber internally. Communal windows are double glazed powder coated aluminium.



- 4) Each flat within the block has access to an individual balcony. The balconies are constructed utilising a cantilevered concrete with steel and high density Stonewool Panels.

## Section 7

### Means of Escape from Fire

---

- 1) The site has a protected staircases that provides a sufficient means of escape which is 1020mm in width from balustrade to wall.



- 2) All corridors are of adequate width (at least 1050mm) and will be maintained clear to that width as a minimum.



- 3) None of the corridors that form part of the means of escape are dead ends.
  - 4) The means of escape are protected to prevent the spread of fire and smoke.
  - 5) The communal landing / staircase is protected by use of nominal FD30s timber fire doors with vision panels.
-



- 6) All communal doors are fitted with automatic closing devices that are checked on a regular basis by Caretaking Teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).
- 7) All communal fire doors are subject to a 12-week check by the Fire Safety Rapid Response Team.
- 8) The final exit door has a door entry system installed. These systems are designed to fail safe i.e. door unlocked in the event of a power failure. This prevents residents being locked in or out of the building.





- 9) The escape routes from both rear fire exits are covered in pigeon excrement creating a potential slip hazard. These areas should be cleaned. Email sent to Estates Services manager. 20.05.25.



- 10) Automatic smoke ventilation is employed. This is tested, inspected and maintained by a competent procured contractor in accordance with BS7346. The frequency for the maintenance checks is twice per year (April and October) of each calendar year. Communal windows can only be opened by operating the automatic smoke vents.
- 11) Automatic opening vents have been installed to the head of protected staircase and in each corridor above the ground floor. It was noted that the opening vents in the 12<sup>th</sup> floor corridors are of a different design to other corridors within the building.





- 12) There is a repeater panel located on the wall of the ground floor lobby that provides the status of the system. At the time of the FRA, the AOV control panel was showing a red fault light. Email sent to Jason Blewitt 15-05-25. Visit by Prestige Protect Systems 15-05-24 System checked and re-set, system recorded as 'healthy'



- 13) The manual override and master reset for the entire system is located next to the repeater panel.



- 14) Individual override / reset controls for each corridor AOV are in service cupboards on each floor (single door secured with a 54 lock). It should be noted that the system installed is fully automated and each vent is independently controlled by a localised smoke detector. Once smoke has cleared the system will automatically reset.



- 15) Communal areas are kept free of flammable items. The communal areas are checked on a regular basis by Caretaking / Cleaning teams 365 days per year and all items of rubbish are immediately removed. There is also an out of hour's service that allows combustible items of furniture / rubbish to be removed.
- 16) Individual floor mats were noted outside some flats. Fire rating of the mats is unknown but deemed to be of low risk.



- 17) Emergency lighting is provided to communal landings and stairs. Checks are done monthly by Sandwell MBC in house electrical team or an approved contractor.



- 18) The building has sufficient passive controls that provide effective compartmentation in order to support a Stay Put-Unless Policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them, or they are asked to leave by the emergency services.



Harry Price House 1-73 (o&e)	Harry Price House 1-70 (o&e);Hartlebury Road;Oldbury;West Midlands;		
Harry Price House 1-73 (O&E)	1 Harry Price House;Hartlebury Road;Oldbury;West Midl	IG Doors	Not glazed

[illegible]

## Fire Risk Assessment

Harry Price House 1-73 (O&E)	56 Harry Price House;Hartlebury Road;Oldbury;West Mic	Timber door	Not glazed
Harry Price House 1-73 (O&E)	57 Harry Price House;Hartlebury Road;Oldbury;West Mic	IG Doors	Not glazed
Harry Price House 1-73 (O&E)	58 Harry Price House;Hartlebury Road;Oldbury;West Mic	IG Doors	Not glazed
Harry Price House 1-73 (O&E)	59 Harry Price House;Hartlebury Road;Oldbury;West Mic	IG Doors	Not glazed
Harry Price House 1-73 (O&E)	60 Harry Price House;Hartlebury Road;Oldbury;West Mic	IG Doors	Not glazed
Harry Price House 1-73 (O&E)	61 Harry Price House;Hartlebury Road;Oldbury;West Mic	IG Doors	Not glazed
Harry Price House 1-73 (O&E)	62 Harry Price House;Hartlebury Road;Oldbury;West Mic	IG Doors	Not glazed
Harry Price House 1-73 (O&E)	63 Harry Price House;Hartlebury Road;Oldbury;West Mic	IG Doors	Not glazed
Harry Price House 1-73 (O&E)	64 Harry Price House;Hartlebury Road;Oldbury;West Mic	Timber door	Not glazed
Harry Price House 1-73 (O&E)	65 Harry Price House;Hartlebury Road;Oldbury;West Mic	IG Doors	Not glazed
Harry Price House 1-73 (O&E)	66 Harry Price House;Hartlebury Road;Oldbury;West Mic	Timber door	Not glazed
Harry Price House 1-73 (O&E)	67 Harry Price House;Hartlebury Road;Oldbury;West Mic	IG Doors	Not glazed
Harry Price House 1-73 (O&E)	68 Harry Price House;Hartlebury Road;Oldbury;West Mic	IG Doors	Not glazed
Harry Price House 1-73 (O&E)	69 Harry Price House;Hartlebury Road;Oldbury;West Mic	IG Doors	Not glazed
Harry Price House 1-73 (O&E)	70 Harry Price House;Hartlebury Road;Oldbury;West Mic	IG Doors	Not glazed
Harry Price House 1-73 (O&E)	71 Harry Price House;Hartlebury Road;Oldbury;West Midlands;		
Harry Price House 1-73 (O&E)	72 Harry Price House;Hartlebury Road;Oldbury;West Midlands;		
Harry Price House 1-73 (O&E)	73 Harry Price House;Hartlebury Road;Oldbury;West Midlands;		

20) Access is gained to a sample of properties as part of the fire risk assessment to ensure the doors have not been tampered with by residents etc. A 10% sample were inspected, a total of 7 doors, during the FRA.

a) Flat 6 – Door was correct.



b) Flat 7 – Door was correct.



c) Flat 9 – Door was correct.



d) Flat 15 – Door was correct.




e) **Flat 16 - Entrance door is a nominal 30-minute fire door with combined intumescent strips / cold smoke seals and a self-closing device. However, there is damage to the door leaf and door frame, requiring repair. See Action 7/20/e.**





- f) **Flat 25 - Entrance door is a timber 30-minute fire door with combined intumescent strips / cold smoke seals and self-closing device. This door has an excessive leaf side gap requiring adjustment. See Action 7/20 (f)**



- g) **Flat 10 (not accessed) - Entrance door is a nominal 30-minute fire door with combined intumescent strips / cold smoke seals and a self-closing device. However, there is damage to the door frame, requiring repair. See Action 7/20(g).**



*Good housekeeping is fundamental to reducing risk in blocks of flats. Controlling the presence of combustible materials and ignition sources not only reduces the potential for accidental fires to start and develop in the common parts, it also significantly reduces the scope for deliberate fires. It also ensures escape routes are free of obstructions that might hinder the evacuation of people from the building and access for fire-fighters.*


## Section 8

# Fire Detection and Alarm Systems

---

- 1) Early warning within flats is limited to hard wire or battery smoke alarms. The equipment is subjected to a cyclical test.
- 2) Based on the sample of properties accessed during the fire risk assessment the smoke alarms within resident's flats are installed to an LD2 Standard.

Flats sampled were 6, 7, 9, 15, 16, 25 and 43.



*LD1 all rooms except wet rooms*

*LD2 all-risk rooms e.g. Living Room, Kitchens and Hallway.*

*LD3 Hallway only*

- 3) There is no effective means for detecting an outbreak of fire to communal corridors, lobbies, landings and stairs. The reason for this are:
  - I. Such systems may get vandalised.
  - II. False alarms would occur.
  - III. A Stay Put - Unless policy is in place.



- 4) Smoke detectors linked to the Automatic Opening Vents have been installed to the common parts of the building. The vents will automatically open when smoke has been detected.



- 5) The server room is equipped with an automatic fire alarm system. The system protects the server room only and incorporates smoke detection and a break glass call point. The system sounds locally only however, there's a separate room temperature monitoring system that is remotely monitored and therefore will raise the alarm in the event of a fire. No evidence of routine testing and maintenance of the fire alarm system was available. Email sent to Jodie Howell, response, waiting for confirmation from Orton Electrical.



6) Server room temperature monitoring system.



7) A fire suppression system is provided to the refuse chute bin store. An approved contractor maintains the systems. The frequency for the maintenance checks is twice per year (April and October) of each calendar year.





## Section 10

# Compartmentation

---

*This section should be read in conjunction with Section 4.*

*A visual inspection of the accessible areas was undertaken as part of the assessment, but areas with restricted access, i.e., false ceilings and void areas, were only inspected where readily accessible. The survey undertaken as part of this risk assessment should not be construed as a full compartmentation survey of the building. From a visual inspection carried out at the time of the inspection, there were no breaches in compartmentation evident between the communal areas and the residential accommodation.*

- 1) The building is designed to provide as a minimum 1-hour vertical fire resistance and 1-hour horizontal fire resistance around flats stairwells and lift shafts. All doors are a minimum 30-minute fire resistant with intumescent strips & cold smoke seals, including those in 1-hour rated walls.
  - 2) The premise has sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire. Whilst the existing fire stopping is fit for purpose, there is a cyclical programme to ensure fire stopping as not been compromised by third parties and where applicable enhance the fire stopping.
  - 3) All communal doors are fitted with automatic closing devices that are checked on a regular basis by Caretaking Teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).
-

- 4) All communal fire doors are subject to a 12-week check by the Fire Safety Rapid Response Team. **At the time of the FRA the fire door in the caretaker's room was found to have a damaged door leaf requiring repair. See action 10/4.**



- 5) The caretaker's door opening onto the main entrance foyer requires a self-closing device to be fitted. This door leads to the caretaker's room with a microwave and is used every weekday. See action 10/5.



- 6) All service cupboards to communal corridors are nominal timber FD60s, locked with suited keys. It was noted that cabling is run through metal trunking protected by intumescent pads or pillows.



- 7) A variety of methods / materials have been used to achieve fire-stopping including Rockwool, fire rated sponge and Supalux boards.



- 8) The fire stopping / compartmentation is subject to a 12-week check by the Fire Safety Rapid Response Team.
- 9) **There is timber panelling requiring removal to check for compartment breaches and reinstating with materials offering 60 mins of fire resistance in the following areas: Storeroom off main entrance lobby, Caretakers room, corridor to ground floor void flats and the ceiling of the corridor near flats 66,67 and 68 on floor 11. See action 10/9.**





- 10) Fire stopping is inadequate in the main incoming electrical plant room (also containing the emergency lighting back up power supply) around cable penetrations, the ceiling and where the walls met the ceiling. This area requires adequate fire stopping to be fitted by a competent provider. See action 10/10.



- 10) Any remedial works arising from the fire stopping / compartmentation check(s) will be actioned immediately by the Fire Safety Rapid Response Team.
- 11) Individual flat doors are predominantly nominal FD30s composite fire door sets manufactured by IG doors. Flats 25, 43, 56, 64 & 66 were noted as timber flush fire doors. See section 7 for further details regarding flat entrance doors.



- 12) The communal corridor and staircase doors are nominal FD30s timber fire doors with vision panels.



- 13) All cupboard doors to the dry riser, roof voids & cleaner's / caretakers' rooms & cupboards are nominal 44mm timber FD30s fire doors.



- 14) Doors to chute rooms are nominal FD30s with vision panels and ventilation grill with intumescent baffle.



- 15) Refuse hoppers on all floors are Dartford Metalcrafts type LC conforming to BS1703: 2005 with 4 ¼ hours fire rating to BS476 part 22 and smoke containment to BS476 part 31.1. The hoppers were installed 23/02/23.



- 16) Access panels to stop taps are fixed to walls via timber rebate strips and found outside the flats of every floor.



## Section

# 11


## Fire Fighting Equipment

---

- 1) The riser inlet is located within the ground floor lobby, inside a dry riser cabinet and is secured with a firefighter's suited bridge door padlock.



- 2) The Dry riser outlets are available in cupboards on each floor above ground adjacent the stairwell door. The cupboards are secured with a suited type 54 key mortice lock.



- 3) The dry riser is checked regularly as part of the Caretakers duties.
- 4) Maintenance contracts in place to service the valves twice per year (April and October) with a hydraulic test undertaken annually (October) to comply with the requirements of BS9990.

- 5) Portable fire extinguisher (CO2) is provided to the lift motor room & server room. Maintenance contracts in place for maintenance of the extinguisher. The frequency for the maintenance checks is once (October) of each calendar year. Last test October 2024.



- 6) There is an empty, out of date foam extinguisher in the caretaker's room, this extinguisher is required to be removed. Email sent to Estate Services Manager. 20.05.25.



- 7) The bin store is protected by fire suppression system and serviced 6- monthly.



- 8) There's an automatic closure plate installed to the refuse chute. The system can also be manually operated and is serviced 6-monthly.



## Section 12

### Fire Signage

- 1) All fire doors and dry riser outlets display appropriate signage.



- 2) Fire Action Notices are displayed throughout the building.



- 3) Yellow LPG warning signs are displayed within the lift car.





- 4) Signage depicting the floor location of each flat is fitted to the ground floor lobby wall.



Harry Price House		
12th	Floor	69-70
11th	Floor	63-68
10th	Floor	57-62
9th	Floor	51-56
8th	Floor	45-50
7th	Floor	39-44
6th	Floor	33-38
5th	Floor	27-32
4th	Floor	21-26
3rd	Floor	15-20
2nd	Floor	9-14
1st	Floor	3-8
Ground	Floor	1, 2, 71-73

- 5) Photoluminescent wayfinding signage depicting floor level and flat numbers are fitted to the walls on all floors adjacent the lift car's and to the wall of each landing on the communal staircase. Signage that meets the requirement of ADB and Fire Safety (England) Regulations 2022



- 6) Directional fire escape signage has been installed in the building.





## Section 13

## Employee & Resident Training/Provision of Information

- 1) All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- 2) All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking Teams are not currently trained in the effective use of fire extinguishers.
- 4) Housing Directorate employees assigned to undertake Fire Safety Inspections have received IFE approved training via West Midlands Fire Service.
- 5) Staff undertaking fire risk assessments are qualified to or working towards Level 4 Diploma in Fire Risk Assessment.
- 6) Fire safety information has been provided as part of tenancy pack.
- 7) Building safety and evacuation notices are displayed in common areas and lift cars.























- 8) Information regarding use of fire doors is provided to residents.



- 9) Information regarding the Stay Put unless fire evacuation strategy is provided to residents.



- 10) Information regarding building safety is contained within a Building Safety Notice. This is affixed to the wall on the ground floor lift lobby of high-rise blocks.

BUILDING SAFETY INFORMATION	 <b>HARRY PRICE HOUSE</b>	FIRE SAFETY INFORMATION
<b>TO KEEP YOU SAFE WE DO THIS</b> <small>(green background)</small>	<b>TO KEEP YOURSELF AND OTHERS SAFE, DO THIS</b> <small>(blue background)</small>	<b>SAVE LIVES, DON'T DO THIS</b> <small>(red background)</small>
 Mains electrical system is tested every 5 years	<b>FIRE ALARMS DO NOT CONNECT TO THE FIRE SERVICE, IN AN EMERGENCY DIAL 999 OR 112 AND ASK FOR POLICE, AMBULANCE OR FIRE SERVICE</b>	 Fire Risk Assessments (FRAs) are undertaken in line with the Regulatory Reform (Fire Safety) Order 2005
 Gas supply tested annually		 Stairs and corridors are escape routes and <u>must</u> be kept clear
 Water supplies checked in line with water hygiene regulations		 Emergency lighting comes on in the event of power failure and is checked monthly
 There is a yearly <u>check</u> of the structural condition		 Walls, floors and ceilings around flats provide a minimum of 60 minutes fire resistance
 An asbestos survey has been completed and available on request		 Flat doors are fire rated to protect the escape route. <b>DO NOT REMOVE THE DOOR CLOSERS</b>
 This building has protection against lightning strikes. The system is checked annually		 Smoke and heat detector/alarms are in resident's flats only
 There is a 'dry riser' to assist fire-fighters in getting water to a floor level. This is checked 6 monthly.	<b>THIS BUILDING IS DESIGNED TO SUPPORT A <u>STAY PUT</u> POLICY. IN THE EVENT OF A FIRE ELSEWHERE, STAY IN YOUR FLAT <u>UNLESS</u> AFFECTED BY FIRE OR SMOKE.</b>	 Smoke detectors in common are to open automatic vents and not to raise the alarm.
 The external façade is brick slips up to 1st floor. Above 1st floor mixture of insulated render (Fire Classification A2) and Rockwool Stonewool Panels (Fire Classification A2 s1 d0)	<div>  Fire safety advice             <div>                 Further information available at:  <a href="http://www.Sandwell.gov.uk">www.Sandwell.gov.uk</a> your My Sandwell account or the Fire Safety Liaison Officer on 0121 569 6000  <a href="mailto:Ethan_Somiya@sandwell.gov.uk">Ethan_Somiya@sandwell.gov.uk</a>  <a href="mailto:Abdulmonim_Khan@sandwell.gov.uk">Abdulmonim_Khan@sandwell.gov.uk</a>  <a href="mailto:Hannah_Russon@sandwell.gov.uk">Hannah_Russon@sandwell.gov.uk</a> </div>  Sandwell FRAs             </div>	 Bin rooms have sprinkler protection activated by smoke alarms

## Section 14

### Sources of Ignition

- 1) Smoking is prohibited within any communal parts of the building in line with Smoke Free England legislation.



- 2) Hot work is not normally carried out. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager. However, the caretakers room contains a microwave, kettle and refrigerator. No evidence of in date PAT was present. Message sent to Team Lead Fire safety. Missed items to be picked up by caretaking supervisor in the round of tests in June 2025.



- 4) There are exposed electrical cables in the 12th floor electrical cupboard. These cables are required to be capped and secured. See Action 14/4.



- 5) The fixed electrical installation shall be tested every 5 years. The last inspection was noted 24-07-2024 and recorded as satisfactory.



- 6) No test certification was available for the PV system. An email was sent to Jodie Howell and the response stated that no test certification was available. Email sent to Team Lead Building Safety.

- 7) The electrical installation i.e. risers are contained within dedicated service cupboards that are secure and protected by means of a notional 54mm FD60 timber fire doors.



- 8) There is lightening protection installed to the block. Maintenance contracts are in place for lightning conductor testing in accordance with BS 6651. Labelled test dated 11-2024 by Central High Rise Ltd.



- 9) Portable heaters are not allowed in any common parts of the premises.

- 10) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the in-house Gas Team.





## Section 15

### Waste Control

---

- 1) There is a regular Cleaning Service to the premises.
- 2) Refuse hoppers are accessed in each floor within the chute rooms.



- 3) Refuse containers are in the bin store at ground level.



- 4) Regular checks by Caretakers minimise risk of waste accumulation.
  - 5) 'Out of Hours' service in place to remove bulk items.
-

## Section 16

### Control and Supervision of Contractors and Visitors

---

- 1) Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
  - 2) Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
  - 3) Utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the Investments office @ Roway Lane. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
  - 4) Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
    - a) Pre-Contract Meetings – where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
      - Health and Safety.
      - Site security.
      - Safety of working and impact on children/school business.
      - Fire risk, if any.
      - Site Emergency Plan.
    - b) Monthly Site Meetings – in order to monitor, review and share any new information including any new risks.
    - c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
    - d) Final Contractor review on completion of works undertaken.
-

## Section 17

### Arson Prevention

---

- 1) Regular checks are undertaken by Caretakers / Cleaning Team(s) 365 days per year which helps reduce the risk of arson.
- 2) Restricted access to the premises by means of a door entry system.



- 3) CCTV is in operation covering the ground floors, lifts and external areas and surrounding areas. The system is monitored 365 days per year by the centralised CCTV control room located at the Sandwell MBC Operations and Development Centre, Roway Lane, Oldbury, B693ES.
- 4) The perimeter of the premises is well illuminated.
- 5) There have been no reported fire incidents since the last FRA (05-06-2024)

## Section 18

### Storage Arrangements

---

- 1) Residents instructed not to bring L.P.G cylinders into block (Notice displayed in lifts).
  - 2) The tenancy conditions, Section 7 – Condition 5.6 stipulates “If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use.”
  - 3) No Flammable liquids stored on site by Caretakers / cleaners.
  - 4) All store cupboards are kept locked.
  - 5) There are no flammable liquids or gas cylinders stored on site.
-

## Section 19

# Additional Control Measures; Fire Risk Assessment - Action Plan

---

Significant Findings

### Action Plan

It is considered that the following recommendations should be implemented to reduce fire risk to, or maintain it at, the following level:

Trivial ☒      Tolerable ☐

Definition of priorities (where applicable):

P1 Arrange and complete as urgent – Within 10 days

P2 Arrange and complete within 1-3 Months of assessment date

P3 Arrange and complete within 3-6 Months of assessment date

P4 Arrange and complete exceeding 6 months under programmed work



# Fire Risk Assessment Action Plan



Name of Premises or Location:

Harry Price House

Date of Action Plan:

15-05-25

Review Date:




<Insert date>

When undertaking future improvement program(s), it is advised that the observations listed below should be given consideration (noting that the safety of the residents is not jeopardised by these, and all steps to reduce any known risks have been taken).

Question/ Ref No	Required Action	Supporting photograph	Priority	Timescale and Person Responsible	Date Completed
7/20/e	Flat 16 - Entrance door. There is damage to the door leaf and door frame, requiring repair.		P2	Within 1-3 months Fire Rapid Response	

---






## Fire Risk Assessment

7/20/f	Flat 25 – entrance door. This door has an excessive leaf side gap requiring adjustment.		P2	Within 1-3 months Fire Rapid Response	
7/20/g	Flat 10 - Entrance door. There is damage to the door frame, requiring repair. This flat was not accessed at the time of the FRA,		P2	Within 1-3 months Fire Rapid Response	
10/4	The fire door in the caretaker's room was found to have a damaged door leaf requiring repair.		P2	Within 1-3 months Fire Rapid Response	



---



## Fire Risk Assessment

10/5	The fire door from the entrance foyer to the caretaker's room requires a self-closing device to be fitted.		P2	Within 1-3 months Fire Rapid Response	
10/9	The timber panelling in the following areas: Storeroom off main entrance lobby, Caretakers room, corridor to ground floor void flats and the ceiling of the corridor near flats 66,67 and 68 on floor 11. Requires removal to check for compartment breaches and then reinstating with materials offering 60 mins of fire resistance.	   	P3	Within 3-6 months Fire Rapid Response	

## Fire Risk Assessment

10/10	Fire stopping is required in the main incoming electrical plant room around cable penetrations, the ceiling and where the walls met the ceiling. This area requires adequate fire stopping to be fitted by a competent person.		P3	Within 3-6 months Fire Rapid Response	
14/4	There are exposed electrical cables in the 12th floor electrical cupboard. These cables are required to be capped and secured.		P3	Electrical. 3-6 months.	



When undertaking future improvement program(s), it is advised that the observations listed below should be given consideration (noting that the safety of the residents is not jeopardised by these, and all steps to reduce any known risks have been taken).

## Observations

PU pink fire foam filler was noted around the void flat entrance door frames to the ground floor. Removing and replacing this foam with a more suitable product should be considered during door replacements or future refurbishment works.



## Signed

	Building Safety Manager	Date: 21.05.25.
	Quality Assurance Check Team Lead Building Safety	Date: 21.05.25.

## Appendix 1

## Significant Hazards on Site and Information to be Provided for the Fire Service




Name of property: Harry Price House

Updated: 24/05/2022

Premise Manager: Tony Thompson

Tel. No.: 0121 569 2975

Hazard	Information/Comments
Asbestos	An asbestos survey has been undertaken of the communal areas. Survey held by Sandwell Housing (Derek Still <a href="tel:01215695077">Tel:- 0121 569 5077</a> ). <i>Include survey</i>

<b>Asbestos Survey</b>		Property Address		Harry Price House 1 – 70, Hartlebury Road, Oldbury, B69 1EQ		Office use	
Surveyed by		J.Davis/G.Carrington		Date		28/01/13	
Checked by		Paul Arundel		Desktop Check		✓	
Date		29/07/16		Site Check		✓	
Reason for request		HSG 264 - Survey Report Type		Property Description			
Investment Void		Refurbishment Survey		13 STOREY HIGH RISE BLOCK WIMPEY CONSTRUCTION	Year Built	1962	
Investment Tenanted		Management Survey	✓				
R & M Void		SHAPE Interrogated.	✓				
R & M Tenanted		No Existing SHAPE Data.	✓				
Medical / Emergency - Heating Works		Existing SHAPE Data.					
Communal Areas	✓	Refurb Surveys Interrogated ?					
				Notes / including details of similar property surveys completed.  <b>REVISED BY STEVE HARRISON AND DON WEBB 06/03/14</b>  <b>Revised By Don Webb 06/12/16</b>  <b>**Survey revised by John Davis 24/05/22**</b>			
Building Surveyors 0121 569 5077				Asset Team – Investment Division Operations & Development Centre Roway Lane Oldbury B69 3ES  			

## Fire Risk Assessment

Sample Locations		Property Address Harry Price House 1 – 70, Hartlebury Road, Oldbury, B69 1EQ						
LOCATION	MATERIAL	QTY	SURFACE TREATMENT	SAMPLE REF	RESULT	HSE NOTIFY	Labels?	ACTION TAKEN ON CONTRACT
IF DURING THE COURSE OF WORK SUSPECTED ACM'S ARE IDENTIFIED THAT ARE NOT CONTAINED WITHIN THIS REPORT STOP WORK & SEEK ADVICE								
LIFT MOTOR ROOM 300mm DIA PIPE	CEMENT	4 lm	SEALED	PRESUMED	CHRYSTILE	NO	NO	
LIFT MOTOR ROOM 300mm DIA PIPE	CEMENT	2 lm	SEALED	PRESUMED	CHRYSTILE	NO	NO	
BOARD ON ROOF OUTSIDE FAN HOUSE (ROOF DOOR) ADJACENT TO No 70	CEMENT	0.5 m2	UNSEALED	PRESUMED	CHRYSTILE	NO	NO	
COMMUNAL WALLS – ALL FLOORS	TEXTURED COATING	-	SEALED-PAINT	DS 6614	NONE DETECTED	NO	NO	-
SIDE WALLS TO DRY RISER CUPBOARDS	BOARD	2 m²	UNSEALED	DS6614	NONE DETECTED	-	-	-
FLOOR TILES TO ALL LANDINGS	THERMOPLASTIC	-	SEALED	PRESUMED	CHRYSTILE	NO	NO	
MAIN ROOF	ASPHALT	-	SEALED	DW824/001	NO ASBESTOS DETECTED	NO	NO	-
ROOF EDGEING	FIBRE GLASS	-	SEALED	DW824/002	NO ASBESTOS DETECTED	NO	NO	-
ITEMS SHOWN BELOW HAVE BEEN ASSESSED ON SITE BY THE ASBESTOS SURVEYOR & ARE CONFIRMED NOT TO BE ACM'S.								
LOCATION DESCRIPTION	MATERIAL	LOCATION DESCRIPTION	MATERIAL	LOCATION DESCRIPTION	MATERIAL			
ROOF TOP FAN ROOMS PIPES	METAL	CANOPY ROOF COVERING	MINERAL FELT					
ROOF TOP FAN ROOMS ROOF COVERING	MINERAL FELT	NOTICE BOARD ON LEFT HAND SIDE WALL BY FRONT ENTRANCE DOOR	PLYWOOD					
CANOPY TO ROOF ACCESS DOOR	PLYWOOD	SOFFIT TO FRONT ENTRANCE	PLASTIC					
LANDING STOP TAP BOX COVERS TO INDIVIDUAL FLATS	SUPALUX							
11 <sup>TH</sup> FLOOR CEILING PANEL BY CHUTE ROOM	TIMBER							

### About the Report

All Survey Methodology is based upon HSE document HSG 264 - Asbestos: The Survey Guide. All surveyors are experienced British Occupational Hygiene Society (BOHS) P402 qualified surveyors with extensive Surveying & Refurbishment Project experience specific to Sandwell Homes' managed housing stock.

The person or persons using this report to programme refurbishment work on site are assumed to be competent & experienced in the field of domestic refurbishment projects & have suitable & sufficient asbestos awareness to understand the scope of this report & apply it to the project. All trade operatives working on site are also expected to have relevant asbestos awareness training & experience. IF IN DOUBT STOP & ASK!

SHAPE: Sandwell Homes' Integrated ICT solution holds the Company Asbestos Register. The Asbestos Register is interrogated when completing the asbestos survey report to ensure that ACM's in similar properties are considered where relevant. The Register holds details of all suspected or confirmed ACM's identified during Refurbishment & Demolition programmes as well as Repairs activities for the past 11 years. If potential ACM's have been identified within difficult to survey areas such as Cavity Walls, Floor Voids etc these will be highlighted within the report. The interrogation of the Company Asbestos Register compliments the survey & report process it does not substitute the Refurbishment & Demolition Survey.

Void Properties – The Building Surveying team who undertake Refurbishment & Demolition Asbestos Surveys also undertake Domestic Energy Assessment Surveys, Boroscope Surveys for Thermal Insulation & Fire Integrity Assessments to a representative percentage of the void turn over.

Site Overview Page 2 – This section is included to aid surveying & to ensure comprehensive survey information is detailed.

Term	Explanation	Term	Explanation
Property Address	Specific Property to which survey relates.	Photo's	These will usually be provided for the front elevation of the property to aid identification.
Surveyed by	Relates to P402 trained surveyor.	Sampled by	P402 trained surveyor.
Blank	Blank	Checked by	P402 trained surveyor who checks report prior to issuing.
Type of Work to be undertaken	Relates to the envisaged type of work that the Asbestos Survey Report will be used to aid. This assists the asbestos surveyor to guide his survey methodology & will help the users of this report decide if it is suitable for the work activity being undertaken.	Survey Report Type	Report type is determined by the type of work to be undertaken. The reader of this report must satisfy themselves that the scope of the survey is sufficient for the purpose of work being undertaken.
ACM	Asbestos Containing Material.	Refurbishment Survey	HSG 264 – Refurbishment & Demolition Survey. Surveying undertaken to all parts of the property presuming full decent homes refurbishment, which may include, New Kitchen, New Bathroom, Electrical Rewire, Re-roof, Full Heating System. Taking account of the complete structure of the property & archetype information available. This survey has been carried out without detailed knowledge of the works to be undertaken during refurbishment.
HSE Notify	This highlights if a material normally requires notification to the Health & Safety Executive prior to removal. GUIDANCE ONLY.	Management Survey	A management survey is the standard survey. Its purpose is to locate, as far as reasonably practicable, the presence and extent of any suspect ACMs in the building which could be damaged or disturbed during normal occupancy, including foreseeable maintenance and installation, and to assess their condition.
Bulk Sample	Sample of potential ACM that is representative of the whole.	Cavity Walls / Floor Voids or similar.	Will be assessed at survey stage & desktop assessment of similar archetypes.
Request Sample	The item described has not been tested for Asbestos content. The item must be presumed to contain asbestos until sampling confirms. If work is going to be undertaken in this area sample should be requested prior to work starting.	SP	Strong Presumption that material contains asbestos. Used to qualify possible false negative laboratory results.
Awaiting Results	If no results have been detailed then you must not work on these items until you receive further confirmation.	Photo's	Where practical & to aid the identification of ambiguous material locations photos will be included within the report to ensure that materials are identified on-site correctly. Photos will be annotated where necessary.
Extent	An estimate of quantity will be given where possible to aid work planning & valuation.		
Labels	Materials <u>will be</u> labelled where practical. Labelling will be not be undertaken to low risk materials e.g. floor tiles, Textured Coatings etc or where labelling could easily be removed or would cause potential exposure if removed. All presumed ACM's will be labelled as "Asbestos" where possible. All sampled materials will be labelled with an "Asbestos Sampled" label.		