

# Fire Risk Assessment

**Flats 45 - 50**

**Salop Drive**



**Salop Drive, Oldbury,  
B68 9AG**

**Date Completed: 27/05/2025.**

**Review Period: 3 years.**

**Officer: A. Jones Building Safety Manager**

**Checked By: C. Hill Building Safety Manager**

**Current Risk Rating = Trivial**

### Subsequent reviews

<u>Review date</u>	<u>Officer</u>	<u>Comments</u>

## Contents

<a href="#">Section 0</a>	<b>Introduction</b>	
<a href="#">Section 1</a>	<b>Significant Findings (executive summary)</b>	
<a href="#">Section 2</a>	<b>People at Significant Risk of Fire</b>	
<a href="#">Section 3</a>	<b>Contact Details</b>	
<a href="#">Section 4</a>	<b>Description of Premises</b>	
<a href="#">Section 5</a>	<b>Building Plan</b>	
<a href="#">Section 6</a>	<b>External Envelope</b>	
<a href="#">Section 7</a>	<b>Means of Escape from Fire</b>	
<a href="#">Section 8</a>	<b>Fire Detection and Alarm Systems</b>	
<a href="#">Section 9</a>	<b>Emergency Lighting</b>	
<a href="#">Section 10</a>	<b>Compartmentation</b>	
<a href="#">Section 11</a>	<b>Fire Fighting Equipment</b>	
<a href="#">Section 12</a>	<b>Fire Signage</b>	
<a href="#">Section 13</a>	<b>Employee Training</b>	
<a href="#">Section 14</a>	<b>Sources of Ignition</b>	
<a href="#">Section 15</a>	<b>Waste Control</b>	
<a href="#">Section 16</a>	<b>Control and Supervision of Contractors and Visitors</b>	
<a href="#">Section 17</a>	<b>Arson Prevention</b>	
<a href="#">Section 18</a>	<b>Storage Arrangements</b>	
<a href="#">Section 19</a>	<b>Additional Control Measures. Fire Risk Assessment – Action Plan</b>	
<a href="#">Appendix 1</a>	<b>Significant Hazards on Site and Information to be provided for the Fire Service Risk Rating of Block</b>	

## Section

# 0

## Introduction

The [Regulatory Reform \(Fire Safety\) Order 2005 \(RR\(FS\)O\)](#) places a legal duty on landlords to complete a fire risk assessment (FRA). Specifically, RR(FS)O article 9. — (1)

*“The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order”.*


This type 1 fire risk assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on <https://www.wmfs.net/our-services/fire-safety/#reportfiresafety>. In the first instance however, we would be grateful if you could contact us directly via [https://www.sandwell.gov.uk/info/200195/contact\\_the\\_council/283/feedb ack\\_and\\_complaints](https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedback_and_complaints) or by phone on 0121 569 6000.

The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation, but the Council will as a minimum review:

- High Risk Residential Buildings annually
- Other Buildings every 3 years

The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment. If the review suggests the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.


The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring, and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.



The above processes and procedures are overseen by the Fire Safety, Manager who reports to the Head of Building Safety.

These managers attend the Building Safety and Compliance Group for scrutiny which is part of the governance structure below.

Governance Structure



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire.

This is recorded here in [section 1](#). Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring, and review of the preventative and protective measures. The information shown above is part of this requirement.

**Section****1****Significant findings**

The significant findings (executive summary) of this type 1 fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005.

Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors, and contractors unfamiliar with the building layout as well as those with physical, sensory, or mental health issues.

A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring, and review of the preventive and protective measures. These are shown in the introduction.

**Significant findings**

*Include a brief summary of protective and preventative measures where relevant along with any issues found.*

The escape strategy is '**Stay Put Unless**'. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire, smoke or you have been advised by the emergency services to leave.

Section number	Section Area	Individual Risk Level
<a href="#">Section 6</a>	<b>External Envelope</b> The building is predominantly of brick construction with concrete tiles installed above and below UPVC windows. There are spandrel panels in staircase and the access walkway leading to flat 55.	Trivial

<a href="#">Section 7</a>	<b>Means of Escape from Fire</b> Each block has a single staircase that provides a sufficient means of escape.	Trivial
<a href="#">Section 8</a>	<b>Fire Detection and Alarm Systems</b> Early warning is limited to hard wired or battery smoke alarms within each of the resident's flats.	Trivial
<a href="#">Section 9</a>	<b>Emergency Lighting</b> Each block has emergency lighting to communal landings & stairs.	Trivial
<a href="#">Section 10</a>	<b>Compartmentation</b> The building is designed to provide as a minimum 1-hour vertical fire resistance and 1-hour horizontal fire resistance around flats.  Doors are 30-minute notional and nominal fire doors.	Trivial
<a href="#">Section 11</a>	<b>Fire Fighting Equipment</b> No firefighting provisions are provided within the premise.	Trivial
<a href="#">Section 12</a>	<b>Fire Signage</b> Appropriate signage is in place, no further action required.	Trivial
<a href="#">Section 13</a>	<b>Employee Training</b> All staff receive basic fire safety awareness training.	Trivial



<a href="#">Section 14</a>	<b>Sources of Ignition</b> The fixed electrical installation should be tested every 5 years. At the time of the assessment The EICR inspection reports for flats 45-50 had been recorded as Satisfactory.	Trivial
<a href="#">Section 15</a>	<b>Waste Control</b> Regular cleaning services take place at the block and regular checks from caretakers help with waste control at the block.	Trivial
<a href="#">Section 16</a>	<b>Control and Supervision of Contractors and Visitors</b> Contractors are controlled centrally, and hot works permits are required where necessary.	Trivial
<a href="#">Section 17</a>	<b>Arson Prevention</b> The final exit doors have door entry systems installed. These systems are designed to fail safe i.e., door unlocked in the event of a power failure.	Trivial
<a href="#">Section 18</a>	<b>Storage Arrangements</b> Residents should not store fuel or LPG Cylinders in their home or storage facilities. This documented in the tenancy agreement.	Trivial

## Risk Level Indicator

The following simple risk level estimator is based on commonly used risk level estimator:

Likelihood of fire	Potential consequences of fire		
	Slight harm	Moderate harm	Extreme harm
Low	Trivial risk	Tolerable risk	Moderate risk
Medium	Tolerable risk	Moderate risk	Substantial risk
High	Moderate risk	Substantial risk	Intolerable risk

Considering the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Low ☒ Medium ☐ High ☐

In this context, a definition of the above terms is as follows:

<b>Low</b>	Unusually low likelihood of fire because of negligible potential sources of ignition.
<b>Medium</b>	Normal fire hazards (e.g., potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).
<b>High</b>	Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

Considering the nature of the premises and the occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:

Slight Harm ☒    Moderate Harm ☐    Extreme Harm ☐

In this context, a definition of the above terms is as follows:

<b>Slight harm</b>	Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).
<b>Moderate harm</b>	Outbreak of fire could foreseeably result in injury including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.
<b>Extreme harm</b>	Significant potential for serious injury or death of one or more occupants.

Accordingly, it is considered that the risk to life from fire at these premises is:

Trivial ☒    Tolerable ☒    Moderate ☐    Substantial ☐    Intolerable ☐

**Comments:**

In conclusion, the likelihood of a fire is at a low level of risk prior to the implementation of the action plan because of the negligible potential sources of ignition.

When future refurbishments are carried out, there are a number of observations that would improve the building. These observations can be found at the end of this document.

After considering the use of the premise and the occupants within the block, the consequences for life safety in the event of a fire would be slight harm.

A suitable risk-based control plan should involve effort and urgency that is proportional to risk. The following risk-based control plan is based on one that has been advocated for general health and safety risks:

Risk level	Action and timescale
<b>Trivial</b>	No action is required, and no detailed records need to be kept.
<b>Tolerable</b>	No major additional fire precautions are required. However, there might be a need for reasonably practicable improvements that involve minor or limited cost.
<b>Moderate</b>	It is essential that efforts are made to reduce the risk. Risk reduction measures, which should take cost into account, should be implemented within a defined time. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
<b>Substantial</b>	Considerable resources might have to be allocated to reduce the risk. If the premises are unoccupied, it should not be occupied until the risk has been reduced. If the premises are occupied, urgent action should be taken.
<b>Intolerable</b>	Premises (or relevant area) should not be occupied until the risk is reduced.

***(Note that, although the purpose of this section is to place the fire risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)***

## Section

# 2

## People at Significant Risk of Fire

---

Persons at significant risk of fire does not just refer to those people with physical, sensory, or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council takes the health, safety and wellbeing of its colleagues, contractors, residents, and leaseholders seriously. It is our policy to exceed, where possible, the minimum health and safety requirements of the law.

Residents are responsible for letting us know whether they might need a Personal Emergency Evacuation Plan (PEEP). The Resident Engagement Officers (Fire Safety) will conduct an assessment visit upon request. Any risk-reduction measures that are found where a PEEP is necessary and completed will be documented and taken quickly.

With the consent of the resident, we will make a referral for West Midlands Fire Service to conduct a Safe and Well visit.

When a PEEP is in place, the relevant information will be kept in the secure Premise Information Box (High Rise Buildings only), which is set up to help WMFS in an emergency. The data is classified as level 1, which means it complies with the General Data Protection Regulations.

## Section 3

### Contact Details

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.

The Chief Executive has put a structure in place to support the management of the site.

This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

#### **Chief Executive**

Shokat Lal

#### **Executive Director of Place**

Alan Lunt

#### **Assistant Director Asset Management & Improvement**

Sarah Agar

#### **Building and Fire Safety Manager**

Tony Thompson

#### **Team Lead Fire Safety**

Jason Blewitt

#### **Team Lead Building Safety**

Anthony Smith

#### **Building Safety Managers**

Adrian Jones

Andrew Froggatt

Carl Hill

Louis Conway

#### **Resident Engagement Officer - Fire Safety**

Abdul Monim Khan

Ethan Somaiya

Hannah Russon

#### **Housing Office Manager**

Rachel Price

*Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change.*

## Section 4

### Description of Premises

Flats 45 - 50  
Salop Drive  
Oldbury,  
B68 9AG

#### Description of the Property:

The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021.

The enforcing authority is West Midlands Fire Service.

This type 1 fire risk assessment covers Salop Drive flats 45 – 50, this covers three individual flats. This block is built into a slope, creating a lower ground floor for one flat only, flat 50. This flat has its own front door, is accessed from fresh air and is not connected to the common area.

Flat 45 also has its own front door and is accessed from fresh air. Flat 55 is accessed internally from block 51 – 55 using the internal staircase.

The building is of traditional construction, circa 1964, with brick walls concrete floors and stairs. The block has double glazed UPVC window frames with a small amount of hung tile cladding and spandrel panels in the stairwells.





The block is surmounted by a pitched roof with bitumen felt covering. The roof space is inaccessible from the common area. The only common area is the staircase and first floor area where access to flat 55 can be gained.

The electrical cupboard that services flats 51-55, is located on the ground floor by the main access door. Flats 45 and 50 have their own electrical installations. These installations have been tested and all recorded as satisfactory.

There are UPVC double glazed windows in the common area with openable windows for ventilation.



There is a dedicated external bin storage area.

Gas is supplied & piped externally to each flat.



The area surrounding the flats is landscaped with maintained, lawned gardens around the perimeter.

High/Low Rise	Low Rise
Number of Floors	2
Date of Construction	circa 1964
Construction Type	Solid Brick Construction
Last Refurbished	Unknown
External Cladding	Small amount hung tile cladding and spandrel panels.
Number of Lifts	None
Number of Staircases	One, to access flat 55.
Automatic Smoke Ventilation to communal area	None
Fire Alarm System	None in common area
Refuse Chute	None
Access to Roof	None from common area.
Equipment on roof (e.g. mobile phone station etc)	None

## **Persons at Risk**

Residents / Occupants of 3 number of flats,  
 Visitors,  
 Sandwell MBC employees,  
 Contractors,  
 Service providers (e.g. meter readers, delivery people etc)  
 Statutory bodies (e.g. W.M.F.S, Police, and Ambulance)

## Section 5

### Building Plan

A general plan showing the building location.



## Section 6

### External envelope

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.

Below is a breakdown of the materials used within the external envelope and, as part of the external wall system.

It is deemed that the combination and application of these materials presents an acceptable level of fire risk.


- 1) The external envelope of the premises is predominantly traditional brick construction, with an amount of hung tile cladding, surmounted pitched roof.



- 2) Individual flat windows are UPVC double glazed window frames. The windows in the communal staircases are UPVC window frames with openable vents. Communal staircases window frames are fitted with spandrel panels.



- 3) Access is gained to flats 45 & 50 using their own front doors located in fresh air. Flat 55 is accessed from the communal staircase of block 51 – 55.



- 4) Gas risers are to the external front elevation of each block.



## Section 7

### Means of Escape from Fire

- 1) Flat 55 has a single staircase that provides a means of escape and is 880mm in width.



- 2) All corridors are of adequate width (at least 1050mm) and will be maintained clear to that width as a minimum.
- 3) None of the corridors that form part of the means of escape are dead ends.
- 4) The only communal door within the block is the final exit door which is fitted with an automatic closing device that is checked on a regular basis by Caretaking Teams as part of their daily checks. Defective closing devices are reported to an external contractor.
- 5) The final exit door has a door entry systems installed. These systems are designed to fail safe i.e., door unlocked in the event of a power failure. This prevents residents being locked in or out of the building.
- 6) Communal areas are kept free of flammable items. The communal areas should be checked on a regular basis by Caretaking / Cleaning teams and all items of rubbish removed.
- 7) Ventilation of the common area is facilitated by openable windows in the stairwell.
- 8) Surface coatings to the walls in the staircases appear to be Class 0 rated.



- 9) The building has sufficient passive controls that provide effective compartmentation to support a Stay Put Policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them.
- 10) Flat entrance doors are a combination of nominal timber and composite type doors. These should be upgraded to certified FD30s entrance doors as part of any future refurbishments.



- 11) The premises has emergency lighting installed.



- 12) There is no chute room or dry riser within this building.
- 13) The electrical service cupboard that supplies flat 55 is a nominal FD30s rated door, secured with type 138 suited locks.
- 14) The block have landlords' electrical distribution boards at high level on the ground floor of the common area. When any refurbishment of the building takes place consideration should be given to enclosing these electrical distribution boards in fire resistant cabinets.



- 15) At the time of the assessment, it was noted that the landing floor to access flat 55 was fitted with carpet. It is understood that carpets have been procured in accordance with BS 5287: 1988 specification for assessment and labelling of textile floor coverings and & BS 4790 Fire Test to Textile Floor Coverings.

These carpets have been procured by SMBC utilising third party approved contractors. Therefore, it is understood that carpets fitted meet the approved standard.



- 16) The building has sufficient passive controls that provide effective compartmentation to support a Stay Put-Unless Policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them.



## Section

# 8

## Fire Detection and Alarm Systems

- 1) Early warning is limited to hard wired or battery smoke alarms within each of the resident's flats. The equipment is subjected to a cyclical test.
- 2) Based on the sample of properties accessed during the fire risk assessment the smoke alarms within resident's flats are installed to an LD3 Standard. The resident at flat 50 confirmed that smoke detection is located in the hallway and lounge.
- 3) There is no other effective means for detecting an outbreak of fire to communal areas. The reason for this is: -
  - I. Such systems may get vandalised.
  - II. False alarms would occur.
  - III. A Stay Put - Unless policy is in place.

## Section 9

### Emergency Lighting

- 1) The premises has a sufficient emergency / escape lighting system in accordance with BS 5266 and has test points strategically located.



- 2) The self-contained units are provided to the communal landing, stairs.
- 3) All installed equipment is checked and tested on a monthly basis by Sandwell MBC in house electrical team or approved contractor, in accordance with current standards.



## Section 10

# Compartmentation

*The high degree of fire separation between flats and the common parts is achieved by making each flat a fire-resisting enclosure. This is known as compartmentation. A compartment is simply a part of a building bounded by walls and floors that will resist the passage of fire for a specified period of time. The fire resistance of this construction is such that, normally, a fire will burn itself out before spreading to other parts of the building.*

- 1) The building is designed to provide as a minimum 1-hour vertical fire resistance and 1-hour horizontal fire resistance around flats. All flat entrance doors are 30-minute nominal doors, including those in 1-hour rated walls.
- 2) The premise has sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire. Whilst the existing fire stopping is fit for purpose, there is a cyclical programme to ensure fire stopping as not been compromised by third parties and where applicable enhance the fire stopping.
- 3) Generally, the means of escape is protected from flats with the use of nominal timber doors, with no communal doors to the blocks other than a final exit door. These doors should be upgraded to FD30s when any future upgrades of the building take place.
- 4) There are no communal doors other than the final exit door for flat 55, which is fitted with automatic closing device. These are checked on a regular basis by Caretaking Teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).
- 5) All service cupboards to communal landings are lockable. Keys are held centrally, and keys have been issued to residents as these service cupboards contain resident's meters.
- 6) A variety of methods / materials have been used to achieve fire-stopping including fire rated batt materials.
- 7) The fire stopping / compartmentation is subject to an annual check by the Fire Safety Rapid Response Team.

- 8) Any remedial works arising from the fire stopping / compartmentation check(s) will be actioned immediately by the Fire Safety Rapid Response Team.
- 9) The building has sufficient passive controls that provide effective compartmentation to support a Stay Put -Unless policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them or if they are advised to evacuate by the emergency services.
- 10) The block is fitted with a pitched roof, not accessible from the common area.
- 16) All front doors are a combination of notional and composite type doors. These should be upgraded to certified FD30s entrance doors as part of any future refurbishments. Refer to the sheet below.

Block Name	Place-Re	Address	Front Door Type	Glazed / Not Glazed
Salop Drive 45-50 (O&E)	BL42380SA08	45-50 Salop Drive (O&E);Oldbury;West Midlands;;	Intentionally Blank	
Salop Drive 45-50 (O&E)	BL42380SA08	45 Salop Drive;Oldbury;West Midlands;;	Timber Door	Glazed
Salop Drive 45-50 (O&E)	BL42380SA08	46 Salop Drive;Oldbury;West Midlands;;	Timber 2G door	Glazed
Salop Drive 45-50 (O&E)	BL42380SA08	47 Salop Drive;Oldbury;West Midlands;;	Timber flush door	Non glazed
Salop Drive 45-50 (O&E)	BL42380SA08	48 Salop Drive;Oldbury;West Midlands;;	Timber 2G door	Glazed
Salop Drive 45-50 (O&E)	BL42380SA08	49 Salop Drive;Oldbury;West Midlands;;	Timber 2G door	Glazed
Salop Drive 45-50 (O&E)	BL42380SA08	50 Salop Drive;Oldbury;West Midlands;;	Composite Type Door	Glazed
Salop Drive 51-59 (O&E)	BL42380SA50	51-59 Salop Drive (O&E);Oldbury;West Midlands;;	Intentionally Blank	
Salop Drive 51-59 (O&E)	BL42380SA50	51 Salop Drive;Oldbury;West Midlands;;	Timber 2G door	Glazed
Salop Drive 51-59 (O&E)	BL42380SA50	52 Salop Drive;Oldbury;West Midlands;;	Timber 2G door	Glazed
Salop Drive 51-59 (O&E)	BL42380SA50	53 Salop Drive;Oldbury;West Midlands;;	Timber flush door	Non glazed
Salop Drive 51-59 (O&E)	BL42380SA50	54 Salop Drive;Oldbury;West Midlands;;	Timber 2G door	Glazed
Salop Drive 51-59 (O&E)	BL42380SA50	55 Salop Drive;Oldbury;West Midlands;;	Timber flush door	Non glazed
Salop Drive 51-59 (O&E)	BL42380SA50	56 Salop Drive;Oldbury;West Midlands;;	Timber flush door	Non glazed
Salop Drive 51-59 (O&E)	BL42380SA50	57 Salop Drive;Oldbury;West Midlands;;	Timber 2G door	Glazed
Salop Drive 51-59 (O&E)	BL42380SA50	58 Salop Drive;Oldbury;West Midlands;;	Timber 2G door	Glazed
Salop Drive 51-59 (O&E)	BL42380SA50	59 Salop Drive;Oldbury;West Midlands;;	Timber 2G door	Glazed

It is accepted that, in older blocks, fire doors, particularly flat entrance doors, do not meet current test standards for FD30S doors. However, these doors may still be acceptable if the doors remain in good condition, and they met the relevant standards at the time of construction of the block.

### **Definitions Fire Doors.**

Notional fire door - A fire door that is thought to have been installed at the time of construction. This door may not meet current building regulation requirements however is still acceptable if performing as originally intended.

Upgraded notional fire door - A notional fire door that has been upgraded. For example, with intumescent strips and cold smoke seals.

Nominal fire door – A fire door that may meet the standards specified within the building regulations but has not been awarded the official certification of doors manufactured and evaluated by an accredited, third-party testing unit and approved formally with the relevant certificates and documentation.

Certified fire door – A fire door and frame that have been approved and certified by the manufacturer. A competent person must install the door assembly.

## Section 11

### Fire Fighting Equipment

- 1) No firefighting provisions are provided within the premise.
- 2) The nearest Fire Hydrant is adjacent to flat 45, Salop Drive.



## Section 12

### Fire Signage

- 1) All fire doors display “Fire Door Keep Shut” where appropriate.
- 2) No smoking (Smoke Free England) signage is displayed at the front entrance to the premises.



## Section 13

## Employee & Resident Training/Provision of Information

- 1) All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- 2) All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking Teams are not currently trained in the effective use of fire extinguishers. Caretaking Teams are not expected to tackle fires in this area.
- 4) Staff undertaking fire risk assessments are qualified to Level 4 Diploma in Fire Risk Assessment.
- 5) Fire safety information has been provided as part of tenancy pack. Information regarding the Stay Put Unless fire evacuation strategy is provided to tenants.



### IMPORTANT NOTICE

#### FIRE DOORS

Fire doors are crucial life safety devices, designed to restrict the spread of smoke and fire for a substantial period of time.

**You must ensure:**

- Fire doors are kept shut when not in use.
- Residents and visitors do not tamper with doors or self-closing devices.
- Any faults or damage is reported immediately to the Contact Centre using the details below.

**You must NOT:**

- Alter or change your flat front door or internal doors without prior consent from Sandwell Council.

**We will:**

- Ensure residents check communal fire doors.
- Carry out an audit of communal fire doors every 12 weeks.
- Check your flat entrance fire door every year.

**ANY UNAUTHORISED MODIFICATIONS MAY PUT LIVES AT RISK**

This information is provided in line with the Fire Safety (England) Regulations 2022 to ensure the safety of residents and building users is not negatively impacted by the modification / misuse of the doors.

PLEASE REPORT ANY DEFECTS OR CONCERNS WITH FIRE DOORS TO:

Name: Contact Centre  
Phone: 0121 559 9000  
Email: customer\_services@sandwell.gov.uk  
On-line: My Sandwell Account

Use QR Code to access Fire Safety Advice

### Fire safety advice

We are committed to educating residents about fire safety and what you should do in the event of a fire in your own home or another part of the building.

#### What to do if a fire breaks out in your flat

1. Leave the room where the fire is and close the door.
2. Alert anyone else in the property that there is a fire and leave the flat, closing all doors behind you. Do not stay to put out the fire.
3. Use the staircase to exit the building. Do not use the lift.
4. Do not wait for the fire service to arrive. Do not re-enter the building.

#### What to do if you see or hear a fire in another flat or part of the building

1. It will normally be safest for you to remain in your flat and stay put unless the heat or smoke from the fire is affecting you.
2. If your safety is compromised, then you should leave the building following the guidance as if the fire was in your flat. If you are instructed to leave by a member of the emergency services, you should do so immediately.
3. In other cases, use the staircase to exit the building. Do not use the lift.

'Stay Put/Leave' is an evacuation strategy used in purpose built blocks of flats. It is in place to keep people safe when they are not in an area directly affected by fire.

If you notice any fire doors within the building that are damaged or wedged open, or have any other concerns, please call us on 0121 559 9000.



## Section 14

### Sources of Ignition

- 1) Smoking is prohibited within any communal parts of the building in line with Smoke Free England legislation.
- 2) Hot works are not normally conducted. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) The fixed electrical installation should be tested every 5 years. At the time of the assessment, it was confirmed that the last electrical installation conditioning report(s) (EICR) were carried out on: -  
  
45 - EICR inspection carried out on 16/05/2023  
55 – EICR inspection carried out on 23/09/2023  
50 - EICR inspection carried out on 22/03/2024
- 4) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager.
- 5) Portable heaters are not allowed in any common parts of the premises.
- 6) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the in-house Gas Team. The gas is supplied externally.
- 7) As per tenancy agreements, flammable liquids or gas cylinders should not be stored on site.

## Section 15

### Waste Control

- 1) Refuse containers are emptied at regular intervals.
- 2) There is an 'Out of Hours' service in place to remove bulk items.
- 3) Refuse containers are emptied at regular intervals.
- 4) Refuse bins are situated too close to the fabric of the building and should be moved to the designated bin store area. An email has been sent to the Housing manager to address this situation



## Section 16

## Control and Supervision of Contractors and Visitors

- 1) Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
- 2) Owing to the nature of low-rise flatted accommodation it is difficult to manage/control individual contractors/utility companies.
- 3) Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
- 4) Utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the local housing office. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
- 5) Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
  - a) Pre-Contract Meetings – where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
    - Health and Safety.
    - Site security.
    - Safety of working and impact on children/school business.
    - Fire risk, if any.
    - Site Emergency plan.
  - b) Monthly Site Meetings – to monitor, review and share any new information including any new risks.
  - c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
  - d) Final Contractor review on completion of works undertaken.

**Section**  
**17**

---

## **Arson Prevention**

---

- 1) Regular checks are undertaken by Caretakers / Cleaning Team(s) 365 days per year which helps reduce the risk of arson.
- 2) There have been no reported fire incidents since the last FRA.

## Section 18

### Storage Arrangements

- 1) Residents are instructed not to bring L.P.G cylinders into block. This information is contained within the tenants' handbook.
- 2) The tenancy conditions, Section 7 – Condition 5.6 stipulates “If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE, or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use.”
- 3) No Flammable liquids stored on site by Caretakers / Cleaners.
- 4) Most store/service cupboards are kept locked, these doors were in good condition at the time of the assessment.
- 5) As per tenancy agreements, flammable liquids or gas cylinders should not be stored on site.

## Section 19

### Additional Control Measures. Fire Risk Assessment - Action Plan

Significant Findings

#### Action Plan.

It is considered that the following recommendations should be implemented to reduce fire risk to, or maintain it at, the following level:

Trivial ☒      Tolerable ☐

Definition of priorities (where applicable):

P1 Arrange and complete as urgent – Within 10 days.

P2 Arrange and complete within 1-3 Months of assessment date.

P3 Arrange and complete within 3-6 Months of assessment date.

P4 Arrange and complete exceeding 6 months under programmed work.



# Fire Risk Assessment Action Plan



Name of Premises or Location:

Flats 45 - 50 Salop Drive, Oldbury.

Date of Action Plan:



29/05/2025

Review Date:

<Insert date>

Question/ Ref No	Required Action	Supporting photograph	Priority	Timescale and Person Responsible	Date Completed
	No actions recorded.				

When undertaking future improvement program(s), it is advised that the observations listed below should be given consideration (noting that the safety of the residents is not jeopardised by these, and all steps to reduce any known risks have been taken).



<b>Observations</b>	
<p>At the time of the assessment, it was noted that landing floors were fitted with carpet. It is understood that carpets have been procured in accordance with BS 5287: 1988 specification for assessment and labelling of textile floor coverings and &amp; BS 4790 Fire Test to Textile Floor Coverings.</p> <p>When any refurbishment of the building takes place consideration should be given to replace existing flooring for an approved floor covering that has appropriate combustibility rates.</p>	
<p>Both blocks have landlords' electrical distribution boards at high level on the ground floor of the common area. When any refurbishment of the building takes place consideration should be given to enclosing these electrical distribution boards in fire resistant cabinets.</p>	



When any refurbishment of the building takes place consideration should be given to upgrading resident's front doors to certified FD30s door sets. A refurbishment program was confirmed by email on 16/06/2022.



**Signed**

 Adrian Jones	Building Safety Manager.	Date: 30/05/2025
 Chris	Quality Assurance Check	Date: 30/05/2025

## Appendix 1




## Significant Hazards on Site and Information to be Provided for the Fire Service

**Name of property:** 45-50, Salop Drive. Oldbury.

**Updated:** 24/09/2019.

**Premise Manager:** Tony Thompson. **Tel. No.:** 0121 569 2975

Hazard	Information/Comments
Asbestos	An asbestos survey has been undertaken of the communal areas. Survey held by Sandwell Housing (Derek Still <a href="tel:01215695077">Tel:- 0121 569 5077</a> ).

<b>Asbestos Survey</b>		Property Address 45-59 Salop Drive, Oldbury. B68 9AG.		Office use <input checked="" type="checkbox"/>	
Surveyed by	Tudor Evans	Date	13/03/2014	Checked by	DEREK STILL
Reason for request		HSG 264 - Survey Report Type		Date	24/09/2019
Investment Void		Refurbishment Survey			
Investment Tenanted		Management Survey	<input checked="" type="checkbox"/>		
R & M Void		SHAPE Interrogated.	<input checked="" type="checkbox"/>		
R & M Tenanted		No Existing SHAPE Data.	<input checked="" type="checkbox"/>		
Medical / Emergency - Heating Works		Existing SHAPE Data.			
Communal Areas	<input checked="" type="checkbox"/>	Refurb Surveys Interrogated ?		Property Description	Low Rise Flats
				Year Built	1963
				Notes / including details of similar property surveys completed.	
Building Surveyors 0121 569 5077				Asset Team – Investment Division Operations & Development Centre Roway Lane Oldbury B69 3ES	
					

**ABOUT THE REPORT – PLEASE READ**

All Survey Methodology is based upon HSE document HSG 264 - Asbestos: The Survey Guide. All surveyors are experienced British Occupational Hygiene Society (BOHS) P402 qualified surveyors with extensive Surveying & Refurbishment Project experience specific to Sandwell MBC's managed housing stock.

The person or persons using this report to programme refurbishment work on site are assumed to be competent & experienced in the field of domestic refurbishment projects & have suitable & sufficient asbestos awareness to understand the scope of this report & apply it to the project. All trade operatives working on site are also expected to have relevant asbestos awareness training & experience. IF IN DOUBT STOP & ASK! Please ensure the report covers the areas that you need to work on.

**SHAPE:** Sandwell MBC's Integrated ICT solution holds the Company Asbestos Register. The Asbestos Register is interrogated when completing the asbestos survey report to ensure that ACM's in similar properties are considered where relevant. The Register holds details of all suspected or confirmed ACM's identified during Refurbishment & Demolition programmes as well as Repairs activities for the past 11 years. If potential ACM's have been identified within difficult to survey areas such as Cavity Walls, Floor voids etc these will be highlighted within the report. The interrogation of the Company Asbestos Register complements the survey & report process & does not substitute the Refurbishment & Demolition Survey.

**Void Properties –** The Building Surveying team who undertake Refurbishment & Demolition Asbestos Surveys also undertake Domestic Energy Assessment Surveys, Borescope Surveys for Thermal Insulation & Fire Integrity Assessments to a representative percentage of the void turn over.

**Site Overview Page 2 –** This section is included to aid surveying & to ensure comprehensive survey information is detailed.

43