1-9 Keswick House Lovett Avenue, Oldbury, B69 1BP



Date Completed: 08/07/2025 Review Period: 3 years.

Officer: S. Henley Fire Risk Assessor Checked by: J Blewitt Team Lead Fire Safety

Current Risk Rating = Tolerable



Subsequent reviews

Review date	Officer	<u>Comments</u>

Contents

Section 0	Introduction	
Section 1	Significant Findings (executive summary)	
Section 2	People at Significant Risk of Fire	
Section 3	Contact Details	
Section 4	Description of Premises	
Section 5	Building Plan	
Section 6	External Envelope	
Section 7	Means of Escape from Fire	
Section 8	Fire Detection and Alarm Systems	
Section 9	Emergency Lighting	
Section 10	Compartmentation	
Section 11	Fire Fighting Equipment	
Section 12	Fire Signage	
Section 13	Employee Training	
Section 14	Sources of Ignition	
Section 15	Waste Control	
Section 16	Control and Supervision of Contractors and Visitors	
Section 17	Arson Prevention	
Section 18	Storage Arrangements	
Section 19	Additional Control Measures. Fire Risk Assessment – Level 2 Action Plan	
Appendix 1	Significant Hazards on Site and Information to be provided for the Fire Service	

Section

Introduction

The <u>Regulatory Reform (Fire Safety) Order 2005 (RR(FS)O)</u> places a legal duty on landlords to complete a fire risk assessment (FRA). Specifically, RR(FS)O article 9. — (1) "The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order".

This fire risk assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on https://www.wmfs.net/our-services/fire-safety/#reportfiresafety. In the first instance however, we would be grateful if you could contact us directly via https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedba ck and complaints or by phone on 0121 569 6000.

The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation. The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment. If the review suggests the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.

The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.



The above processes and procedures are overseen by the Fire Safety, Facilities and Premises Manager who reports to the Business Manager -Surveying and Fire Safety.

These managers attend the Fire Safety Core Group for scrutiny which is part of the governance structure below.



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire. This is recorded here in <u>section 1</u>. Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring and review of the preventative and protective measures. The information shown above is part of this requirement.



Significant findings

The significant findings (executive summary) of the fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005.

Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors and contractors unfamiliar with the building layout as well as those with physical, sensory or mental health issues.

A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring and review of the preventive and protective measures. These are shown in the introduction.

Significant findings

Include a brief summary of protective and preventative measures where relevant along with any issues found;

The escape strategy is '**Stay Put Unless'.** This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire or smoke.

Section number	Section Area	Individual Risk Level
<u>Section 6</u>	External Envelope The block is brick cavity construction, with felt roofing and UPVC facia. There is a small amount of spandrel panels fitted below windows in the common area stairwell. Property windows are UPVC double glazed units. There are vertically aligned concrete balconies with steel balustrades. A number of external lights are fitted for safety and security around the premises. Doors are fitted with self-closers and access is via fob or buzzer.	Trivial

Section 7	Means of Escape from Fire	Trivial
	The block has a protected staircase with 2 final exit doors that provide a suitable means of escape. 2 emergency lights installed near front entrance.	
	Front & Rear exit door frames are of aluminium construction.	
	Step ladders are being stored on the 2 nd floor communal landing	
	Metal Trunking installed across ceiling routing from residents' meter cupboard and supplying flats within the block.	
	All communal hallway floors are carpeted.	
	All floors have S.M.B.C fitted carpet. Due to the fact S.M.B.C specified and managed the installation of the carpets it has been presumed that it is class 0 fire rated.	
	Carpets BS 5287,1988 specification for assessment and labelling of textile floor coverings and BS 4790 Fire Test Method to textile Floor Coverings	
	A number of flats at their entrances have door mats, the fire rating is not known on the door mats.	
Section 8	Fire Detection and Alarm Systems	Trivial
	Flats have a fire detection system fitted to an LD3 standard.	
	Flat 6 & 7 checked at time of assessment being carried out.	
	No detection in communal areas.	

Section 9	Emergency Lighting	Trivial
	The premises have a sufficient emergency / escape lighting system in accordance with BS 5266. The last annual check was carried out on the 16/04/2025.	
Section 10	Compartmentation	Tolerable
	 Flat No 7 has an additional non-fire rated front door, also has removed the self-closer front the rated door. Individual flat doors are FD30s rated composite fire doors and fitted with self-closers. All service cupboards to communal landings are FD30s rated and lockable with budget locks and include a fire door Keep locked sticker. Ground floor and second floor electrical service cupboard has a few gaps/holes that are in need of fire stopping within the cupboard. Each flat has access to a storage cupboard adjacent the flat door. Cupboards do not have fire rated doors but are kept locked 	
Section 11	Fire Fighting Equipment	Trivial
	The premises have no provision for firefighting equipment.	
Section 12	Fire Signage	Tolerable
	There is sufficient Fire door keep shut signs & No Smoking signs in place. The signage on the outside, front and back is in need of replacement due to fading and damage.	

Section 13	Employee Training	Trivial
	All staff receive basic fire safety awareness training.	
Section 14	Sources of Ignition	Trivial
	The fixed electrical installation should be tested every 5 years. At the time of the assessment, it was determined that the last EICR inspection of electrical equipment was carried out on 21/02/2025	
Section 15	Waste Control	Tolerable
	Caretakers undertake regular checks and bins are stored away from the building.	
	Refuse bins are to the rear against brick wall, away from residential block.	
	Settee being stored in the rear courtyard by wooden fence	
Section 16	Control and Supervision of Contractors and Visitors	Trivial
	Contractors are controlled centrally, and hot works permits are required where necessary.	
Section 17	Arson Prevention	Trivial
	The final exit doors have door entry systems installed. These systems are designed to fail safe i.e., door unlocked in the event of a power failure.	

Section 18	Storage Arrangements	Trivial
	Residents have their own internal store cupboards next to their flat entrances which are kept secure with their own locks.	
	Theres are also external storage set within a compound away from the main block, these are secured by residents with their own locks.	
	Residents should not store fuel or LPG Cylinders in their home or storage facilities. This documented in the tenancy agreement. See observations.	

Risk Level Indicator

The following simple risk level estimator is based on commonly used risk level estimator:

Likelihood of fire	Po	Potential consequences of fire		
	Slight harm	Moderate harm	Extreme harm	
Low	Trivial risk	Tolerable risk	Moderate risk	
Medium	Tolerable risk	Moderate risk	Substantial risk	
High	Moderate risk	Substantial risk	Intolerable risk	

Considering the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Low 🗆 Medium	\bowtie	High	
--------------	-----------	------	--

In this context, a definition of the above terms is as follows:

Low

Unusually low likelihood of fire because of negligible potential sources of ignition.

Medium	Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).
High	Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

Considering the nature of the premises and the occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:

Slight Harm \boxtimes Moderate Harm \square Extreme Harm \square

In this context, a definition of the above terms is as follows:

Slight harm	Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).
Moderate harm	Outbreak of fire could foreseeably result in injury including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.

Extreme harm Significant potential for serious injury or death of one or more occupants.

Accordingly, it is considered that the risk to life from fire at these premises is:

Trivial \Box Tolerable \boxtimes Moderate \Box Substantial \Box Intolerable \Box

Comments

After conducting a Type 1 fire risk assessment at Keswick House, I conclude that the likelihood of a fire is of a medium risk level prior to the implementation of the action plan, owing to the standard fire hazards identified within the assessment.

These hazards include:

Considering the use of the premises and the occupants within the block, the potential consequences for life safety in the event of a fire would be minor harm. This is because all flats are fitted with FD30s composite entrance doors, smoke detection systems installed to a minimum of LD3 in all flats, two final exit doors, and a stay-put strategy unless a fire strategy is in place.

Once the recommended actions have been completed, the overall risk rating for the building will be reduced to trivial, subject to the implementation of the suggested measures outlined in this fire risk assessment.

Overall, the risk level at the time of this FRA is considered tolerable.

A suitable risk-based control plan (where applicable) should involve effort and urgency that is proportional to risk. The following risk- based control plan is based on one that has been advocated for general health and safety risks:

Risk level	Action and timescale
Trivial	No action is required, and no detailed records need be kept.
Tolerable	No major additional fire precautions are required. However, there might be a need for reasonably practicable improvements that involve minor or limited cost.
Moderate	It is essential that efforts are made to reduce the risk. Risk reduction measures, which should take cost into account, should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
Substantial	Considerable resources might have to be allocated to reduce the risk. If the premises are unoccupied, it should not be occupied until the risk has been reduced. If the premises are occupied, urgent action should be taken.
Intolerable	Premises (or relevant area) should not be occupied until the risk is reduced.

(Note that, although the purpose of this section is to place the fire risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)

Section

People at Significant Risk of Fire

Persons at significant risk of fire does not just refer to those people with physical, sensory or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council is currently writing a policy and procedures for Personal Emergency Evacuation Plans (PEEPs). This is based on tenants identifying themselves as requiring a PEEP. This will be reliant on the outcomes of the government consultation which is yet to be published.

Residents are responsible for letting us know whether they might need a Personal Emergency Evacuation Plan (PEEP). The Resident Engagement Officers (Fire Safety) will conduct an assessment visit upon request. Any risk-reduction measures that are found where a PEEP is necessary and completed will be documented and taken quickly. With the consent of the resident, we will make a referral for West Midlands Fire Service to conduct a Safe and Well visit.

When a PEEP is in place, the relevant information will be kept in the secure Premise Information Box (High Rise Buildings only), which is set up to help WMFS in an emergency. The data is classified as level 1, which means it complies with the General Data Protection Regulations.



Contact Details

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.

The Chief Executive has put a structure in place to support the management of the site.

This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

Chief Executive							
	Shokat Lal						
Executive Di	irector Asset Manager	* & Improvement					
	Alan Lunt						
	Fire Safety Manage	r					
	Tony Thompson						
	Team Lead Fire Safe	ety					
	Jason Blewitt						
1	Team Lead Building Safety						
	Anthony Smith						
	Housing Office Mana	ger					
	Rachel Price						
Building Safety	Fire Risk	Resident Engagement					
Managers							
Adrian Jones Mohammed Zafeer Abdulmonim Khan							
Carl Hill	Carl Hill Stuart Henley Ethan Somaiya						
Louis Conway	Craig Hudson	Hannah Russon					
Andrew Froggatt							

Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change



Description of Premises

The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021. The enforcing authority is West Midlands Fire Service.

1-9 Keswick House Lovett Avenue Oldbury B69 1BP

The low-rise block was constructed in 1965 of traditional brick cavity construction with a concrete slab separating each floor. The block consists of 3 storeys including the ground floor. All flats including the ground floor have access to a balcony with steal railings and a back-yard space. Each of the floors from the ground floor upwards contain 3 individual flats.

The block has a front entrance, that has a door entry system, and a fob reader installed. There is a rear access door, leading to a rear garden and courtyard area. Both escape routes lead to an ultimate place of safety. The Front and rear entrance points utilise a door entry system with a fob reader installed.

The block has 1 central staircase as the sole means of escape for all flats (above ground floor). There are electrical cupboards (Notional FD30s) located on each floor secured with a budget lock containing residents' meters.

There is a dedicated area within the rear yard area where bins are stored.

The building has been designed and constructed to provide reasonable facilities to assist fire fighters in the protection of life. Reasonable provisions have been made to enable fire appliances to gain access to the building.

The enforcing authority is West Midlands Fire Service Nearest Fire station is Oldbury fire station, which is 1.1miles

High/Low Rise	Low-Rise
Number of Floors	3
Date of Construction	1965
Construction Type	Traditional brick and concrete
Last Refurbished	Unknown
External Cladding	None
Number of Lifts	None
Number of Staircases	1
Automatic Smoke Ventilation to	None
communal area	
Fire Alarm System	None
Refuse Chute	None
Access to Roof	Flat roof – no internal access
Equipment on roof (e.g. mobile	None
phone station etc)	

Persons at Risk

Residents / Occupants of 9 number of flats, Visitors, Sandwell MBC employees, Contractors, Service providers (e.g. meter readers, delivery people etc) Statutory bodies (e.g. W.M.F.S, Police, and Ambulance) Section
5

Building Plan





Section 6 External envelope

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.

Provide a breakdown of the materials used and whether these or their combination or application present an acceptable level of fire risk.

1) The external surface of the building is predominantly brick structure with UPVC facia to the roof line with felt roof.



2) UPVC double glazed units have been installed to each flat, UPVC and aluminium units installed in the communal stairwell, with spandrel panels on lower sections of stairway units. There is a canopy situated over the entrance to the block.



3) Each flat has an individual balcony with steel railings



4) Access to the building: front entrance is via a call point/fob system, and firefighting override system. Rear entrance is a fob access only



Front door access

Rear door access

5) There is lighting installed to the front door for safety and security, however the rear elevation would also benefit from having lighting installed on a future programme.



Front access

Rear access



1) Each floor consists of a single staircase that provides a means of escape and has a width of 899mm.



2) All corridors are of adequate width (at least 1050mm) and will be maintained clear to that width as a minimum.



- 3) None of the corridors that form part of the means of escape are dead ends.
- 4) The means of escape are protected to prevent the spread of fire and smoke.
- 5) The only communal doors within the block are the final exit doors, which are fitted with automatic closing devices that are checked on a regular basis by caretaking teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).



6) All floors have S.M.B.C fitted carpet. Due to the fact S.M.B.C specified and managed the installation of the carpets it has been presumed that it is class 0 fire rated.

Carpets BS 5287,1988 specification for assessment and labelling of textile floor coverings and BS 4790 Fire Test Method to textile Floor Coverings

A number of flat entrances have door mats; the fire rating is not known on these door mats.



7) Windows on the front first floor fully open and can be used as a means of escape.



8) Communal areas are kept free of flammable items. The communal areas are checked on a regular basis by Caretaking / Cleaning teams 365 days per year and all items of rubbish are immediately removed. There is also

an out of hour's service that allows combustible items of furniture / rubbish to be removed.



9) Emergency lighting is provided to communal landings and stairs. Checks are done on a monthly basis by Sandwell MBC in house electrical team or approved contractor. (Refer to section 9)



10) On the 2nd floor there is a set of aluminium ladders. These are kept in an area out of the way and would not compromise safe exit from the block.



11) On the ground floor there is a heavy-duty steel storage cupboard used for cleaning products. This does not compromise safe exit from the premises





- 1) Early warning is limited to hard wire or battery smoke alarms within each of the resident's flats the equipment is subjected to a cyclical test.
- 2) Based on the sample of properties accessed during the fire risk assessment the smoke alarms within resident's flats are installed to an LD3 Standard.

Flat 7 & 6 was inspected at the time of inspection



For information LD1 all rooms except wet rooms LD2 all-risk rooms e.g. Living Room, Kitchens and Hallway. LD3 Hallway only

- 3) There is no effective means for detecting an outbreak of fire to communal areas. The reason for this is:
 - I. Such systems may get vandalised.
 - II. False alarms would occur.
 - III. A Stay Put Unless policy is in place



- 1) The premises have a sufficient emergency / escape lighting system in accordance with BS 5266.
- 2) Two units of emergency lighting is situated on each floor



 Emergency lights are also checked and tested monthly by City Fire & Electrical Services

		Job Deptile					Senit long	as 0.00	Brown Gr
	Monthly Fining ency Lighting Tisk Record	Adulti 152071 Sali Gran Sunder Salititi C., 10457527 Baulti 25 Baulti 2509	East: Group (Michaelis Limited Invalid Officer) East: Group List Startland Paris, 13 Film Presents	RESWICKI IDUSE 1-0 (OME) Ner Jahren	Apportance (Printy) Altory Determ Altory Determ Altory Develop Altoritation (Develop Altoritation (Develop) Altoritation (Develop) Altoritation (Develop)	C Normality of the second seco	na <u>koni</u>	11 IF I dente inter (Fr)* li	
	Star 2 Parts	Restored	Series (Pring)		The set of the second s		Property and a second	eh) refte	-
					in all of the build whether	Thirs also seems	(mesonal)		
The second secon		ECRETCY Electronic and a dynamic machine accession MAD Definition for how consists to many built constant and to be many built constant and to be many built or second analy in the many of	Increasing streament NCC A stream choice of the fract version and attacks from the transformed and These These are all produced to the fact they are all streaments and a fractaching and a streament and a fractaching and a streament and a fractaching	Y25 Explosite optical Y25 Formatic	The Minister on Participation of the Control of Control	the De Printin		_	òŝy Pe
		All houses has have been raise andly when it is considered			Nor-tena	Loofer	FERE Sealers	frequence	in the second
	1985 - the - States B								
		THE O LEADER	57						
		and the second se	-4		Calaborative		Patients'		
		Markets Non-American	~ /] Instance	Part Assessed	Calabanania Feroa		Danie Byrine C	and and a	



This section should be read in conjunction with Section 4

- 1) The building is designed to provide as a minimum 1-hour vertical fire resistance and 30 minutes horizontal fire resistance.
- 2) The premise does not have sufficient compartmentation to limit the travel and effect of smoke and flame in the event of a fire in communal areas due to having an open plan stairwell. Whilst the existing fire stopping is fit for purpose, there is a cyclical programme to ensure fire stopping as not been compromised by third parties and where applicable enhance the fire stopping.
- 3) There are no communal doors fitted with automatic closing devices other than the final exit doors. These are checked on a regular basis by Caretaking Teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).



4) All service cupboards to communal landings are FD30s rated and lockable with budget locks and include a fire door Keep locked sticker.



5) The electrical service cupboards on the ground floor and second floor are in need of fire stopping due to gaps in the structure





6) Each flat has access to a storage cupboard adjacent the flat door. Cupboards do not have fire rated doors but are kept locked



7) Individual flat doors are FD30s rated composite fire door construction. Flat 7 has an additional door fitted to the alcove in front of the rated door. 1-9 pictured





8) All doors would have been fitted with self-closers at the time of installation. Unable to inspect all these at the time of the inspection so can not say if they are working correctly and still in place. Flat 7 which was inspected had removed the self-closer.



1) There is no firefighting equipment on this premises.



1) Fire door keep shut signs are displayed where appropriate. All resident meter cupboards display" Fire Door Keep Shut" sign.



- Fire Action Notices are not displayed throughout the building. The signs are not necessarily due to the building not having a complex layout.
- 3) Yellow LPG warning signs are not displayed within the block. <u>refer</u> to section 18
- 4) Smoking is prohibited within any communal parts of the building in line with Smoke Free England legislation. **Signage at the front and rear of premise require changing due to fading and damage**.



Section 13

Employee & Resident Training/Provision of Information

- All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking teams are not currently trained in the effective use of fire extinguishers.
- 4) Fire safety has been provided as part of tenancy pack.
- 5) Staff undertaking fire risk assessments are qualified to or working towards Level 4 Diploma in Fire Risk Assessment.



Sources of Ignition

- 1) Smoking is prohibited on entrance and within any communal parts of the building in line with Smoke Free England legislation.
- Hot working is not normally carried out. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager Bryan Low.
- 4) Other portable electrical equipment as used by residents in communal areas is also subject to periodic PAT testing.
- 5) The fixed electrical installation shall be tested every 5 years. The date of the last test was 21/2/25 date of next inspection is 20/10/30

RPPROVED CONTRACTOR	Dodd Group	ELECTRICAL	ficate is not valid if the serial as been defined or altered INSTALLATION COND orderoe with BS 7871: 2019 (as amended) - Requir	
PART 1 : DETAILS O	F THE CONTRACTOR, CLIENT AN	DINSTALLATION		
	4 Branch No ⁴ 004	Contextor Relences Reader (CBB): N/A Name: Sandwed Council Addesar:	DETAILS OF THE INSTALLATION Outgine: Tenant URRE: IVA Adduce: 1-9 Kesnish House, Clidhu Mistands Postode: B60 10Rmer. N	
Paralase		POLICE STOLEN	Particle - Str. Str. Str. Str.	
Date(s) when inspectien and tast	nunal power to ensure safety for continued u	Records available (551.); (NA	apart available (652); (NIA Previous raport	edata ()
PART 3 : SUMMARY	OF THE CONDITION OF THE INS	TALLATION		
Senanal condition of the installation	en (in terms of electrical saleny) _ installation in gen	erally in good condition, install is of an age of an older version of	the regs(10th edition)	
Description of premises Dee	ding(✔) Commendiat(NIA) In	tantist (N/A) Other (include brief description): N/A		
		ations: [X. IFVes, estimated age NIAyeam) Overall assessment of the fieldy dangerous (Code C2) conditions have been identified (listed in INART		
PART 4 : DECLARAT	TION			
INSPECTION AND TESTING				
		n (ao indicated by my/our signatum beixe), perfoxulan of which am described in PRF hed Schedules, provides an accurate assessment of the condition of the electrical int		

- 6) Portable heaters are not allowed in any common parts of the premises.
- 7) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the inhouse Gas Team.

8) All Residents service cupboards on each floor are housed behind a FD30s fire rated doors. All cupboards are free from any combustibles.



9) 2nd floor has door entry system power supply unit installed on the wall, this is secure and away from resident's reach, all cabling is housed within boxed metal trunking above.





Waste Control

- 1) There is a regular Cleaning Service to the premises. In need of a cabinet fitting to show cleaning documents as this is not in place.
- 2) Refuse bins are stored to the rear of the building. Bins Are regularly emptied by site services.



3) Regular checks by Caretakers minimise risk of waste accumulation. Cleaning rota not on display due to missing cabinet, team notified.



- 4) 'Out of Hours' service is in place to remove bulk items.
- 5) Out by the bins at the rear of the premises there is a settee being stored. These need removing.



Section **16**

Control and Supervision of Contractors and Visitors

- 1) All visitors must sign in and out at reception.
- Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
- 3) Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
- 4) Utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the Investments office @ Roway Lane. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
- 5) Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
 - a) Pre-Contract Meetings where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
 Health and Safety.
 - Site Security.
 - Safety of working and impact on children/school business.
 - Fire risk, if any.
 - Site Emergency Plan.
 - b) Monthly Site Meetings in order to monitor, review and share any new information including any new risks.
 - c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
 - d) Final Contractor review on completion of works undertaken



- 1) Regular checks are undertaken by Caretakers / Cleaning Team(s) 365 days per year which helps reduce the risk of arson.
- 2) Restricted access to the premises by means of a door entry system to the front and the rear.



- 3) There is no current evidence of arson.
- 4) The perimeter of the premises is well illuminated. Lights required outside the rear exit door.



5) There have been no reported fire incidents since the last FRA.



Storage Arrangements

- 1) Residents instructed not to bring L.P.G cylinders into block.
- 2) The tenancy conditions, Section 7 Condition 5.6 stipulates "If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use."
- 3) No Flammable liquids stored on site by Caretakers / cleaners.
- 4) There are no flammable liquids or gas cylinders stored on site.
- 5) Residents have individual storage cupboard internally and externally which they keep secured by means of own keys.



Additional Control Measures. Fire Risk Assessment - Level 2 Action Plan

Significant Findings

Action Plan

Section

19

It is considered that the following recommendations should be implemented to reduce fire risk to, or maintain it at, the following level:

Trivial \boxtimes Tolerable \square

Definition of priorities (where applicable):

P1 Arrange and complete as urgent – Within 10 days

P2 Arrange and complete within 1-3 Months of assessment date

P3 Arrange and complete within 3-6 Months of assessment date

P4 Arrange and complete exceeding 6 months under programmed work

ļ		Risk Assess /el 2 Action			
Name of F	Premises or Location:	Keswick House			
Date of Ac	tion Plan:	10 th July 2025			
Review Da	ate:	<insert date=""></insert>			
Question/ Ref No	Required Action	Supporting photograph	Priority	Timescale and Person Responsible	Date Completed

10/5	The electrical service cupboards on the ground floor and second floor are in need of fire stopping due to gaps in the structure. Due to no access to 1 st floor cupboard can this be checked at time of works?		P2	1-3 Months Fire Rapid Response
10/8	Self-closer removed from flat 7 front door		P2	1-3 Months Fire Rapid Response
12/4	NO SMOKING signs need replacing at the front and rear doors due to fading and damage.	It is against the law to smoke in any communal area of these premises	P2	1-3 Months Fire Rapid Response

	e being stored of the premises.	P2	1-3 Months Housing Manager	
--	---------------------------------	----	----------------------------------	--

Observations

When undertaking future improvement program(s), it is advised that the observations listed below should be given consideration (noting that the safety of the residents is not jeopardised by these, and all steps to reduce any known risks have been taken).

Install security light by rear exit/entrance to the rear of the property for safety and security.

Signed

Haven	Fire Risk Assessor	Date: 10 th July 2025
Bleum	Team Lead Fire Safety	Date: 10 th July 2025

Appendix 1

Significant Hazards on Site and Information to be Provided for the Fire Service

Name of property: Keswick House

Updated:

Premise Manager: Rachel Price

Tel. No.: 0121 569 2975

Hazard	Location	Information/Comments
	rvey has been underta sion (Derek Still <u>Tel:-</u> 0	ken and is held by S.M.B.C. 121 569 5077).

Asbestos Survey	Property Address	Keswick H	louse	e 1-9, Oldbury, B	69 1DR		√ Office use
Surveyed by S.Harrison	Date 2	0/03/14		Checked by	DEREK STILL	Desktop Check 🧹 Sit	te Check
Reason for request	HSG 264 - Surv	ey Report Ty	pe	Date	19/05/2020	ANN THE	1 4
Investment Void	Refurbishment Sur	vey		Prope	erty Description		
Investment Tenanted	Management Surv	ey	~				
R & M Void	SHAPE Interrogate	ed.	~]		A STATISTICS OF A DESCRIPTION OF A DESCRIPANTE A DESCRIPANTE A DESCRIPANTE A DESCRIPTION OF A DESCRIPTION OF	
R & M Tenanted	No Existing SHAPE	E Data.		3 STOREY LOV	VRISE BLOCK OF FLATS		And a construction of the local division of
Medical / Emergency - Heating Works	Existing SHAPE D	ata.	1	1		- Contraction (1)	Barriston Brits
Communal Areas 🗸	Refurb Surveys Int	errogated ?				Year Built	
CS Addention Register Managementer (1992) File Edit Options Help UD0005 Help UD0005 Help UD0005 Help UD0005 UD0005 Help HA BDXHS NAVA HA BDX HA BDXHS NAVA HA B	In Lovet Avenue, Oldbury, West Norse Inspection Level [New Survey Date] Institution of Constant Constant III Constant Norse Norse Norse Norse Norse Norse Norse Norse Norse	Midlands, 863 10A			ding details of similar p ed on the 06/07/2022 f ors	Asset Team – Investm Operations & Develop	ent Division

Page 1 of 3

IF IN DOUBT CONTACT THE BUILDING SURVEYING TEAM

Version 2.0 - 8th January 2013 © Sandwell MBC

Sample Locations	Prop Add									
LOCATION	MA	TERIAL	QTY	SURFACE TREATMEN		RESULT	HSE NOTIF Y	Laboratory 7		TION TAKEN ON CONTRACT
IF DURING THE COURSE OF WOR	K SUSPECTED A	CM'S ARE	IDENTIFIE	D THAT ARE N	OT CONTAINED V	VITHIN THIS REP	ORT ST	OP W	ORK &	EEK ADVICE
		NO SI	USPECTED AC	MIS OBSERVED DU	IRING SURVEY					
ITEMS SHOWN BELO	W HAVE BEEN A	SSESSED	ON SITE B	Y THE ASBEST	OS SURVEYOR 8	ARE CONFIRM	ED NOT	TO BE	ACM's	
LOCATION DESCRIPTION	MATERIAL	LOC	LOCATION DESCRIPTION		MATERIAL	LOCATIO	LOCATION DESCRIPTION		ON	MATERIAL
COMMUNAL STAIRS/LANDING WALLS	BRICK	ELECTRIC	ELECTRICITY METER CUPBOARD WALLS		BRICK / BLOCK					
COMMUNAL LANDING CEILINGS/SOFFITS	CONCRETE	ELECTRICITY METER CUPBOARD -BACK BOARD TO ELECTRICAL EQUIPMENT		CHIPBOARD						
2 ¹⁰ FLOOR LANDING CEILING	PLASTERBOARD	ALL	DOOR FRAME	SEALANTS	SILICONE					
FRONT AND REAR ENTRANCE COMBI FRAME PANELS	PLASTIC									
PANELS TO LANDING WINDOWS	PLASTIC									

Page 2 of 3

IF IN DOUBT CONTACT THE BUILDING SURVEYING TEAM

Version 2.0 - 8th January 2013 © Sandwell MBC

ABOUT THE REPORT - PLEASE READ

All Survey Methodology is based upon HSE document HSD 264 - Aabeaba: The Survey Guide. All surveyors are experienced British Occupational Hygiene Society (BOHS) P402 qualified surveyors with extensive Surveying & Refurbishment Project experience specific to Sandwell MBC's managed housing stock.

The periods or periods using this report to requirement work on this are assumed to be completed & superiods in the fail of discussion elutionaries projects & have a subble & sufficient subsets assumes to undershall the acops of this report & apply it to the project. All trade operatives working on site are assumed to be completed & superiods. If IN DOUBT STOP & ADRI Please ensure the report covers the areas that you need it work on BIAPDE States (States) (

Walk, Ricci Usate these will be highlighted within the report. The bining one taken in a construction is a construction of a construction

Site Overview Page 2 - This section is included to aid surveying & to ensure comprehensive survey information is detailed.

		1.1		
Term	Explanation		Term	Explanation
Property Address	Specific Property to which survey relates.		Photo's	These will usually be provided for the front elevation of the property to aid identification.
Surveyed by	Relates to P402 trained surveyor.		Sampled by	P402 trained surveyor.
Action taken on Project	Record what action may have been undertaken to the Asbestos in question. E.g. Nothing, Repair, replace, Manage.		Checked by	P402 trained surveyor who checks report prior to issuing.
Type of Work to be undertaken	Raistee to the envisaged type of work that the Asbeston Survey Report will be used to aid. This axials the asbeston surveyor to guide its survey methodology 5 will help the users of this report decide if it is suitable for the work activity being undertaken.		Survey Report Type	Report type is determined by the type of work to be undertaken. The reader of this report must satisfy thermaines that the scope of the survey is sufficient for the purpose of work being undertaken.
ACM	Asbestos Containing Material.			HSG 264 - Refurbishment & Demolition Survey. Surveying undertaken to all parts of the property presuring full decent homes refurbishment, which may include. New Kitchen, New Bathroom,
HSE Notify	This highlights if a material normally requires notification to the Health & Safety Executive prior to removal. GUIDANCE ONLY.		Refurblehment Survey	Excitoal Review, Re-root, Full Heating System. Taking account of the complete structure of the property & archetyse information available. This survey has been carried out without detailed increases of the works to be understain during inductivityment. Anyone using this report to support building works being understainen to be proceenly should ensure that the report is sufficient for the proof is sufficient for the summary structure.
Bulk Sample	Sample of potential ACM that is representative of the whole.			purposes of the building work being undertaken. The reader should be confident that the areas that are to be disturbed by the proposed work are included.
Request Sample	The item described has not been tested for Asbestos content. The item must be presumed to content subwittes until sampling continns. If work is going to be undertaken in this area sample should be requested prior to work starting.		Management Survey	A management survey is the standard survey. Its purpose is to locate, as for as reasonably precitable, the presence and extent of any suspect ACMs in the building which could be demoged or initiated during normal occupancy, including foreseable maintenance and installation, and to assess their condition.
Availing Results	If no results have been detailed then you must not work on these items until you receive further confirmation.		Refurb & Management Survey	Both Survey Report Types are toked due to vorial identified at survey stage the surveyor has completed Relativithment Survey for the vorial required 6 may have undertaken a management survey on remaining areas of the propert. The report should not be used for vorial outside the scope studied, unless the reader assures themselves that it is suitable 6 sufficient.
Extent	An estimate of quantity will be given where possible to aid work planning $\boldsymbol{\delta}$ valuation.		Cavity Walls / Floor Volds or similar.	Will be assessed at survey stage & desidop assessment of similar archetypes.
Labels	Materials will be labelled where practical. Labeling will be not be undertaken to low risk materials a.g. foor tiles, "textund Costings etc or where labeling could easily be removed or would cause potential exposure if monoved. All presented ALM will be labelled as "Alabetica" where practical. All sampled materials will be labelled with an "Alabetica Sampled" label.		Photo's	Where practical & to aid the identification of ambiguous material locations photos will be included within the report to ansure that materials are identified on-aits correctly. Photos will be annotated where recessory.

Version 2.0 - 8th January 2013 © Sandwell MBC