

Fire Risk Assessment

19-24

**Peartree Lane,
Cradley Heath,
B64 6EH**

What3words: ///incomes.fight.life



Date Completed: 11/11/2025

Review Period: 3 years.

Officer: S. Henley Fire Risk Assessor

Checked by: A. Froggatt Building Safety Manager

Current Risk Rating = Tolerable

Subsequent reviews

<u>Review date</u>	<u>Officer</u>	<u>Comments</u>

Contents

Section 0	Introduction	
Section 1	Significant Findings (executive summary)	
Section 2	People at Significant Risk of Fire	
Section 3	Contact Details	
Section 4	Description of Premises	
Section 5	Building Plan	
Section 6	External Envelope	
Section 7	Means of Escape from Fire	
Section 8	Fire Detection and Alarm Systems	
Section 9	Emergency Lighting	
Section 10	Compartmentation	
Section 11	Fire Fighting Equipment	
Section 12	Fire Signage	
Section 13	Employee Training	
Section 14	Sources of Ignition	
Section 15	Waste Control	
Section 16	Control and Supervision of Contractors and Visitors	
Section 17	Arson Prevention	
Section 18	Storage Arrangements	
Section 19	Additional Control Measures. Fire Risk Assessment	
Appendix 1	Significant Hazards on Site and Information to be provided for the Fire Service	

Section

0

Introduction


The [Regulatory Reform \(Fire Safety\) Order 2005 \(RR\(FS\)O\)](#) places a legal duty on landlords to complete a fire risk assessment (FRA).

Specifically, RR(FS)O article 9. — (1) *“The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order”*.

This type 1 fire risk assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on <https://www.wmfs.net/our-services/fire-safety/#reportfiresafety>. In the first instance however, we would be grateful if you could contact us directly via https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedback_and_complaints or by phone on 0121 569 6000.


The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation. The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment. If the review suggests the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.

The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.



The above processes and procedures are overseen by the Fire Safety, Facilities and Premises Manager who reports to the Business Manager -Surveying and Fire Safety.

These managers attend the Fire Safety Core Group for scrutiny which is part of the governance structure below.



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire. This is recorded here in [section 1](#). Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring and review of the preventative and protective measures. The information shown above is part of this requirement.

Section**1****Significant findings**

The significant findings (executive summary) of the fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005.

Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors and contractors unfamiliar with the building layout as well as those with physical, sensory or mental health issues.

A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring and review of the preventive and protective measures. These are shown in the introduction.

Significant findings

Include a brief summary of protective and preventative measures where relevant along with any issues found.

The escape strategy is '**Stay Put Unless**'. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building, you should stay put unless you are affected by fire or smoke.

Section number	Section Area	Individual Risk Level
Section 6	External Envelope The building is predominantly constructed with brick cavity walls, with uPVC double-glazed units fitted to the flats. The roof is covered with flat concrete interlocking tiles, and uPVC soffits and fascia boards have been installed.	Trivial

Section 7	Means of Escape from Fire There is a single central staircase in each block offering adequate means of escape with FD30s fire doors prior to front and rear final exits doors, with levered handles to open. All communal hallway floors are finished in hard flooring. Some door deficiencies require rectification. Plastic trunking in place on the ground floor and first floor ceilings, recommend upgrading in future refurbishment. Items being kept on the ground floor escape route need relocating. Emailed housing manager 22/10/2025	Tolerable
Section 8	Fire Detection and Alarm Systems Individual flats have a fire detection system fitted to a minimum of a LD3 standard. No detection in communal areas.	Trivial
Section 9	Emergency Lighting These premises are fitted with emergency lighting at the head of the stairways.	Trivial
Section 10	Compartmentation The building is designed to provide as a minimum 1-hour vertical fire resistance and 1-hour horizontal fire resistance around flats. Doors are 30-minute notional fire doors, including those in 1-hour rated walls. Areas of action required, see sections 7/3, 10/10	Tolerable

Section 11	Fire Fighting Equipment The premises have no provision for firefighting equipment.	Trivial
Section 12	Fire Signage 'Fire Door – Keep Shut/Locked' required of internal and external service doors There are sufficient 'No Smoking' signs in place.	Tolerable
Section 13	Employee Training All staff receive basic fire safety awareness training.	Trivial
Section 14	Sources of Ignition The fixed electrical installation should be tested every 5 years. Last EICR was carried out on the 23/10/2025.	Trivial
Section 15	Waste Control Caretakers undertake regular checks and waste bin is stored within a room fitted with a chute and fire doors.	Trivial
Section 16	Control and Supervision of Contractors and Visitors Contractors are controlled centrally, and hot works permits are required where necessary.	Trivial

Section 17	Arson Prevention The entrance/exit doors have door entry systems installed. The doors are to be kept shut at all times and this is highlighted to residents and visitors using 'Keep Door Shut' signage.	Trivial
Section 18	Storage Arrangements Residents should not store fuel or LPG Cylinders in their home or storage facilities. Number of items in the rear courtyard need relocating away from the service door. Emailed housing manager 22/10/2025	Trivial

Risk Level Indicator

The following simple risk level estimator is based on commonly used risk level estimator:

Likelihood of fire	Potential consequences of fire		
	Slight harm	Moderate harm	Extreme harm
Low	Trivial risk	Tolerable risk	Moderate risk
Medium	Tolerable risk	Moderate risk	Substantial risk
High	Moderate risk	Substantial risk	Intolerable risk

Considering the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Low ☐ Medium ☒ High ☐

In this context, a definition of the above terms is as follows:

Low	Unusually low likelihood of fire because of negligible potential sources of ignition.
Medium	Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).
High	Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

Considering the nature of the premises and the occupants, as well as the fire protection and procedural arrangements observed at the time of this fire risk assessment, it is considered that the consequences for life safety in the event of fire would be:

Slight Harm ☒ Moderate Harm ☐ Extreme Harm ☐

In this context, a definition of the above terms is as follows:

Slight harm	Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).
Moderate harm	Outbreak of fire could foreseeably result in injury including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.
Extreme harm	Significant potential for serious injury or death of one or more occupants.

Accordingly, it is considered that the risk to life from fire at these premises is:

Trivial ☐ Tolerable ☒ Moderate ☐ Substantial ☐ Intolerable ☐

Comments

The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021. The enforcing authority is West Midlands Fire Service.

A Type 1 Fire Risk Assessment of the premises at 19-24 Peartree Lane, Cradley Heath has been carried out. The assessment included a thorough inspection of the site's layout, identification of potential fire hazards, and evaluation of existing fire safety measures. The findings and recommendations have been documented.

Based on the assessment, the likelihood of a fire is deemed medium prior to the implementation of the action plan, due to the identified normal fire hazards. Considering the use of the premises and the occupants within the block, the potential consequences for life safety in the event of a fire would be slight harm. This is because all flats appear to be fitted with FD30 rated original notional timber doors, smoke/heat detection systems installed to a minimum of LD3 in all flats, two final exit doors, and a stay-put strategy unless a fire strategy is in place.

Access was gained to a sample of properties as part of the risk assessment. A number of property fire doors inspected required fire safety furniture adding, see section 7.

Overall, the risk level at the time of this FRA is considered tolerable.

Once the recommended actions have been completed, the overall risk rating for the building will be reduced to trivial, subject to the implementation of the suggested measures outlined in this fire risk assessment.

A suitable risk-based control plan (where applicable) should involve effort and urgency that is proportional to risk. The following risk-based control plan is based on one that has been advocated for general health and safety risks:

Risk level	Action and timescale
Trivial	No action is required, and no detailed records need to be kept.
Tolerable	No major additional fire precautions are required. However, there might be a need for reasonably practicable improvements that involve minor or limited cost.
Moderate	It is essential that efforts are made to reduce the risk. Risk reduction measures, which should take cost into account, should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
Substantial	Considerable resources might have to be allocated to reduce the risk. If the premises are unoccupied, it should not be occupied until the risk has been reduced. If the premises are occupied, urgent action should be taken.
Intolerable	Premises (or relevant area) should not be occupied until the risk is reduced.

(Note that, although the purpose of this section is to place the fire risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)

Section

2

People at Significant Risk of Fire

Persons at significant risk of fire does not just refer to those people with physical, sensory or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council has a policy and procedure in place for Personal Emergency Evacuation Plans (PEEPs). This is based on tenants identifying themselves as requiring a PEEP.

Residents are responsible for letting us know whether they might need a Personal Emergency Evacuation Plan (PEEP). The Resident Engagement Officers (Fire Safety) will conduct an assessment visit upon request. Any risk-reduction measures that are found where a PEEP is necessary and completed will be documented and taken quickly.

With the consent of the resident, we will make a referral for West Midlands Fire Service to conduct a Safe and Well visit.

When a PEEP is in place, the relevant information will be kept in the secure Premise Information Box (High Rise Buildings only), which is set up to help WMFS in an emergency. The data is classified as level 1, which means it complies with the General Data Protection Regulations.

Section 3

Contact Details

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.

The Chief Executive has put a structure in place to support the management of the site.

This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

Chief Executive Shokat Lal		
Executive Director Asset Manager & Improvement Alan Lunt		
Assistant Director Asset Manager & Improvement Sarah Agar		
Fire Safety Manager Tony Thompson		
Team Lead Fire Safety Jason Blewitt		
Team Lead Building Safety Anthony Smith		
Housing Office Manager Prabha Patel		
Building Safety Managers Adrian Jones Andrew Froggatt Carl Hill Louis Conway	Fire Risk Assessors Craig Hudson Mohammed Zafeer Stuart Henley	Resident Engagement Officers – Fire Safety Abdulmonim Khan Ethan Somaiya Hannah Russon

Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change.

Section 4

Description of Premises

19-24
Peartree Lane
Cradley Heath
B64 6EH



A Type 1 Fire Risk Assessment of the premises at 19-24 Peartree Lane, Cradley Heath has been carried out. The assessment included a thorough inspection of the site's layout, identification of potential fire hazards, and evaluation of existing fire safety measures. The findings and recommendations have been documented.

These low-rise, three-storey blocks were constructed in 1968 of traditional construction with concrete floors and stair/s. The roofs are pitched and finished with flat concrete interlocking tiles.


The block comprises of 6 flats in total with 2 flats on each floor, each three storeys high. Flats are fitted with uPVC windows. Each block is served by a dedicated central staircase that leads to the timber final exit doors, which are fitted with levered handles to facilitate easy evacuation. This arrangement provides adequate escape routes for occupants.




The front entrance features a porch with a pitched roof covered in flat concrete tiles, with uPVC fascia and soffits. The porch contains the main entrance door, which is timber, self-closing, with glass panels and a spandrel section on the side, as well as a second timber door that provides access to the refuse chute room. This room is secured with a padlock and stores the metal wheelie bin.




The main entrance to the block is accessed off Peartree Lane, with a secondary exit located at the rear. The front entrance is fitted with an intercom door entry system, fob access and a firefighter override switch. The rear entrance is accessed via fob only. Entrance can also be gained by a concierge.



The building has a dedicated central staircase leading to the final exit doors (X2). Prior to reaching these final exits, there are FD30s fire doors positioned to create small lobby area between the fire door and the fire exit at both the front and rear of the property. The final exit doors are fitted with self-closers and have levered handles for easy evacuation, ensuring adequate escape routes.



Residents' refuse is disposed of through an FD30s fire door on the ground floor, which is also fitted with an intumescent vent. Behind this fire door is a small, self-closing FD30s fire door that provides access to the bin chute.



The block is monitored by CCTV that is situated on the outside of the building



The enforcing authority is West Midlands Fire Service.
The nearest fire station is Haden Cross Fire Station,
located approximately 0.5 miles away.



Premise location: What3words: [///incomes.fight.life](https://www.what3words.com/#!/incomes.fight.life)

High/Low Rise	Low-Rise
Number of Floors	3
Date of Construction	1968
Construction Type	Traditional brick & concrete
Last Refurbished	Unknown
External Cladding	None
Number of Lifts	None
Number of Staircases	1
Automatic Smoke Ventilation to communal area	None
Fire Alarm System	None
Refuse Chute	None
Access to Roof	None
Equipment on roof (e.g. mobile phone station etc)	None

Persons at Risk

Residents / Occupants of 6 flats

Visitors,

Sandwell MBC employees,


Contractors,

Service providers (e.g. meter readers, delivery people etc)

Statutory bodies (e.g. W.M.F.S, Police, and Ambulance)

Section 5

Building Plan



Section 6

External envelope

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.

Below is a breakdown of the materials used within the external envelope, it is deemed that the combination and application of these materials present an acceptable level of fire risk.

- 1) The external surface of the building is predominantly brick structure with uPVC soffits and fascia. The roof is pitched and fitted with flat concrete interlocking roof tiles on the roof.



- 2) uPVC double glazed units have been installed to each flat and communal stairway. There is a porched entrance to the block. The canopy roof is a pitched roof with flat interlocking roof tiles. There are uPVC fascia and soffits installed around the porch front. Entrance & rear door are timber and glass units, with small section of spandrel panelling to the side. The bin room door is of timber construction.



Section 7

Means of Escape from Fire

- 1) Each property is fitted with a minimum of an LD3 detection system within the flat. [See Section 8](#)
- 2) Each property has the protection of a minimum of a notional FD30s rated door; self-closers are fitted, some to the external face of the door, some internally.



Peartree Lane 19-24 (O & F BL37480PE13	19-24 Peartree Lane;Cradley Heath;West Midlands;;	Intentionally Blank	
Peartree Lane 19-24 (O & F BL37480PE13	19 Peartree Lane;Cradley Heath;West Midlands;;	Timber Door FD30s	Not glazed
Peartree Lane 19-24 (O & F BL37480PE13	20 Peartree Lane;Cradley Heath;West Midlands;;	Timber Door FD30s	Not glazed
Peartree Lane 19-24 (O & F BL37480PE13	21 Peartree Lane;Cradley Heath;West Midlands;;	Timber Door FD30s	Not glazed
Peartree Lane 19-24 (O & F BL37480PE13	22 Peartree Lane;Cradley Heath;West Midlands;;	Timber Door FD30s	Not glazed
Peartree Lane 19-24 (O & F BL37480PE13	23 Peartree Lane;Cradley Heath;West Midlands;;	Timber Door FD30s	Not glazed
Peartree Lane 19-24 (O & F BL37480PE13	24 Peartree Lane;Cradley Heath;West Midlands;;	Timber Door FD30s	Not glazed


- 3) The following flat doors were accessed at the time of the fire risk assessment to make sure fire safety door furniture was in place and working.

- a) Flat 20: Replace intumescent strip due to being painted over.
- b) Flat 20: adjust self-closer. The door does not close every time on its own.
- c) Flat 20: Fit fire rated letter box



- d) Flat 21: Replace intumescent strip on the hinge side due to being painted over and may compromise the strip.

e) Flat 21: Fit fire rated letter box



f) Flat 23: Door frame and wall need repairing due to damage




g) Flat 23: escutcheon plate needs fitting as original one is missing




h) Flat 24: Fit fire rated letter box



- 4) At a couple of flat entrances door mats are present; the fire rating is not known on these door mats and are deemed to be low risk.



- 5) Within the block each floor is accessed via a single staircase that provides a means of escape and has a width of a minimum of 990mm between the handrails, this includes the minimum width of the landings.




- 6) Corridors and landings are at least 1050mm in width and are kept clear.



- 7) Windows within the communal area are fitted with openers; these would assist in any ventilation required.



- 8) The means of escape are protected to prevent the spread of fire and smoke. There is an FD30s fire door prior the final exit door of the block at the front and rear of the block. These doors are fitted with automatic closing devices. To exit the doors, you do so by using a regular levered handle. These are checked on a regular basis by caretaking teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s). These systems are designed to fail safe i.e. door unlocked in the event of a power failure. This prevents residents being locked in or out of the building.




- 9) Service cupboard situated on the ground floor in the communal area. See section 10/10



- 10) Communal areas are kept free of flammable items. The communal areas are checked on a regular basis by Caretaking / Cleaning teams 365 days per year and all items of rubbish are immediately removed. There is also an out of hour's service that allows combustible items of furniture / rubbish to be removed.



- 11) Emergency lighting is provided to communal landings and stairs as this is required under 3.41 of Approved Document B Volume 1.
[\(Refer to section 9\)](#) Landing windows and standard lighting units also supply light within the communal areas.




- 12) Furthest travel distance from flat door to the top of the stairs in 7.3 metres



- 13) Recommend plastic trunking be upgraded to metal trunking in any future renovations, or at least D Clips are added or metal ties to the exterior of the trunking.



- 14) Flat 19: items being left outside flat door need relocated away from the escape routes. Emailed housing manager 22/10/2025**



Definitions Fire Doors.

Notional fire door - A fire door that is thought to have been installed at the time of construction. This door may not meet current building regulation requirements however is still acceptable if performing as originally intended.

Upgraded notional fire door - A notional fire door that has been upgraded. For example, with intumescent strips and cold smoke seals.

Nominal fire door – A fire door that may meet the standards specified within the building regulations but has not been awarded the official certification of doors manufactured and evaluated by an accredited, third-party testing unit and approved formally with the relevant certificates and documentation.

Certified fire door – A fire door and frame that have been approved and certified by the manufacturer. A competent person must install the door assembly.

Section

8

Fire Detection and Alarm Systems

- 1) Early warning is limited to hard wire or battery smoke alarms within each of the resident's flats the equipment is subjected to a cyclical test.

Based on the sample of properties accessed during the fire risk assessment the smoke alarms within residents' flats are fitted to a minimum of an LD3 standard.

- Flat 20 inspected at the time of the fire risk assessment LD1 installed.
- Flat 21 inspected at the time of the fire risk assessment LD1 installed.

For information

LD1 all rooms except wet rooms

LD2 all-risk rooms e.g. Living Room, Kitchens and Hallway.


LD3 Hallway only

- 2) There is no effective means for detecting an outbreak of fire to communal areas. The reason for this is:
 - I. Such systems may get vandalised.
 - II. False alarms would occur.
 - III. A Stay Put - Unless policy is in place

Section 9

Emergency Lighting

- 1) These premises have been fitted with emergency lighting at the head of the stairways.
- 2) As well as emergency lighting fitted there is also standard lighting and windows to assist in lighting of the communal areas



- 3) Emergency lighting is inspected regularly to ensure it functions correctly. Monthly inspections are carried out by Sandwell, while annual assessments are conducted by Cityfire, a qualified fire safety contractor. These inspections verify that the emergency lighting will operate effectively during a power failure, helping to guide occupants to safety and ensuring compliance with fire safety regulations.



Section 10

Compartmentation

This section should be read in conjunction with Section 4


- 1) A visual inspection of the accessible areas was undertaken as part of the assessment, but areas with restricted access, i.e., false ceilings and void areas, were only inspected where readily accessible. The inspection did not reveal any breaches in compartmentation.

The survey undertaken as part of this risk assessment should not be construed as a full compartmentation survey of the building.

- 2) The building is designed to provide as a minimum 1-hour vertical and vertical fire resistance.
- 3) The building has sufficient passive controls that provide effective compartmentation to support a Stay Put -Unless policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them or if they are advised to evacuate by the emergency services.
- 4) The existing fire-stopping measures are fit for purpose, and a cyclical programme is in place to ensure that the fire-stopping has not been compromised by third parties and to make enhancements where necessary.
- 5) A variety of methods / materials have been used to achieve fire-stopping such as intumescent mastic around penetrations.
- 6) Bin chute room: There is a full-size door to access the room, the door has an intumescent vent installed within it. After this door there is a small FD30s hatch door, both doors are fitted with self-closers.



- 7) Flats are fitted with a minimum of timber notional FD30s doors. A number of flat doors were assessed at the time of the visit and require upgrading see section 7/3
- 8) On the ground floor next to the rear final exit door is situated a storeroom that is used by the cleaner. This room is fitted with an FD30s door that is locked with a 054 lock.



- 9) On the top floor of each block there is a loft hatch. At the time of the Fire Risk Assessment, the loft area was not inspected, so cannot say the area is free of hazards or that they comply fully with fire safety standards. It is recommended that these areas be inspected and kept secure to ensure they do not pose a fire risk or hinder evacuation procedures. An identical block to this, Peartree Lane 1-6 is fitted with doors within the loft area. Due to this, a request for the rapids team to assess the loft area and to carryout 10/9a and 10/9b if required.

a) Fit a lock and handle to the doors within the loft area (if required)

b) Fire doors with intumescent strips and smoke seal (if required)



1-6 Peartree

- 10) The service cupboard on ground floor is fitted with Supalux top panel and a 25mm timber door also secured with a budget key. Upgrade the cupboard to a fire rated cupboard, also include intumescent strips and smoke seals.



- 11) Outside each flat is situated a fire rated electric meter overbox. These are locked with a budget key.



- 12) At the rear of the premises in the courtyard the service cupboard is located. This cupboard is locked with a 054 lock, and the door is an FD30s. Fire Door Keep Locked signage required on the door, see section 12/1

- a) Relocate the items being stored directly outside the service door. Email sent 22/10/2025 to the housing manager.



Section 11

Fire Fighting Equipment

- 1) There is no firefighting equipment on this premises.
- 2) Nearest fire hydrant is indicated within the attached plan



Section 12

Fire Signage

- 1) 'Fire door keep shut' signs are displayed on the entrance and exit doors.



- a) The external service cupboard requires "Fire Door Keep locked" signage fitting



- b) The internal service cupboard requires "Fire Door Keep locked" signage fitting



- c) Smoking is prohibited within any communal parts of the building in line with Smoke Free England legislation.



- 3) Directional fire signage is not displayed throughout the building.
The absence of such signage is not necessarily due to the building not having a complex layout.

Section 13

Employee & Resident Training/Provision of Information

- 1) All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- 2) All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking teams are not currently trained in the effective use of fire extinguishers.
- 4) Fire safety has been provided as part of tenancy pack.
- 5) Staff undertaking fire risk assessments are qualified to or working towards Level 4 Diploma in Fire Risk Assessment.

Section 14

Sources of Ignition

- 1) Smoking is prohibited on entrance and within any communal parts of the building in line with Smoke Free England legislation.
- 2) Hot working is not normally carried out. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager.
- 4) The fixed electrical installation shall be tested every 5 years. The date of the last EICR was 23/10/2025

Electrical Installation Condition Report (EICR)

Contractor: Dodd Group
Client: [Name]
Installation: [Address]
Date: 23/10/2025
Signature: [Signature]

Summary of the Condition of the Installation:

The installation was found to be satisfactory and in compliance with the current version of BS7671. No remedial work was required.

Declaration:


I, the undersigned, being a competent person, hereby declare that the installation has been inspected and tested in accordance with the requirements of BS7671 and that the results of the inspection and testing are as stated in this report.

- 5) Portable heaters are not allowed in any common parts of the premises.
- 6) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the in-house Gas Team.
- 7) The block has a service cupboard located in the courtyard at the rear of the block and is accessible by a FD30s fire rated door, also there is a service cupboard downstairs, inside the communal area (see section 7/11). Service cupboards should be free from any combustibles.
- 8) Electric Meters are situated within the communal areas and kept within a fire rated overbox which should be locked and not to have any damage. See section 10/10

Section 15

Waste Control

- 1) There is a regular Cleaning Service to the premises.
- 2) The refuse bin is located at the front of the block within a room next to the blocks front entrance. Rubbish is disposed of via a bin chute from within the block, the bin is kept in its own room.



- 3) Regular checks are carried out by Caretakers to minimise risk of waste accumulation.



- 4) 'Out of Hours' service is in place to remove bulk items.

Section 16

Control and Supervision of Contractors and Visitors

- 1) Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
 - 2) Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
 - 3) Utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the local housing office. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
 - 4) Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
 - a) Pre-Contract Meetings – where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
 - Health and Safety.
 - Site Security.
 - Safety of working and impact on children/school business.
 - Fire risk, if any.
 - Site Emergency Plan.
 - b) Monthly Site Meetings – in order to monitor, review and share any new information including any new risks.
 - c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
 - d) Final Contractor review on completion of works undertaken
-


Section 17

Arson Prevention

- 1) Regular checks are undertaken by Caretakers / Cleaning Team(s) 365 days per year which helps reduce the risk of arson.
- 2) Restricted access to the premises by means of a fob and door entry system to the front and the rear.



- 3) There is access to the rear via a side gate. This is always padlocked preventing unofficial access



- 4) There have been no reported fire incidents since the last FRA.

Section 18

Storage Arrangements

- 1) Residents instructed not to bring L.P.G cylinders into block.
 - 2) The tenancy conditions, Section 7 – Condition 5.6 stipulates “If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use.”
 - 3) Residents should not store flammable liquids or gas cylinders on site.
 - 4) No Flammable liquids stored on site by Caretakers / Cleaners.
 - 5) Number of items in the rear courtyard need relocating away from the service door. Emailed housing manager 22/10/2025
-

Section 19

Additional Control Measures. Fire Risk Assessment - Action Plan

Significant Findings.

Action Plan

It is considered that the following recommendations should be implemented to reduce fire risk to, or maintain it at, the following level:

Trivial ☒ Tolerable ☐

Definition of priorities (where applicable):

P1 Arrange and complete as urgent – Within 10 days

P2 Arrange and complete within 1-3 Months of assessment date

P3 Arrange and complete within 3-6 Months of assessment date

P4 Arrange and complete exceeding 6 months under programmed work



Fire Risk Assessment Action Plan



Name of Premises or Location:

Peartree Lane 19-24

Date of Action Plan:

18/11/2025

Review Date:

<Insert date>

Question/ Ref No	Required Action	Supporting photograph	Priority	Timescale and Person Responsible	Date Completed
7/3a	Flat 20: Replace intumescent strip due to being painted over.		P2	Within 1-3 months Fire Rapid Response	

Fire Risk Assessment

7/3b	Flat 20: adjust self-closer. The door does not close every time without assistance.		P2	Within 1-3 months Fire Rapid Response	
7/3c	Flat 20: Replace existing letter box with a fire rated letterbox.		P2	Within 1-3 months Fire Rapid Response	
7/3d	Flat 21: Replace intumescent strip on the hinge side due to being painted over and may compromise the strip.		P2	Within 1-3 months Fire Rapid Response	

Fire Risk Assessment

7/3e	Flat 21:fit fire rated letter box		P3	Within 3-6 months Fire Rapid Response	
7/3f	Flat 23: Repair/replace door frame and door.		P3	Within 3-6 months Asset Management	
7/3g	Flat 23: replace missing escutcheon plate to door frontage		P2	Within 1-3 months Fire Rapid Response	

Fire Risk Assessment

7/3h	Flat 24: Fit fire rated letter box		P3	Within 3-6 months Fire Rapid Response	
10/9a	Fit lock and handle to the doors within the loft space (if required)		P3	Within 3-6 months Fire Rapid Response	
10/9b	Fit intumescent strips and smoke seals to the doors within the loft space (if required)		P3	Within 3-6 months Fire Rapid Response	

Fire Risk Assessment

10/10	Upgrade service cupboard door and frame with appropriate fire rated materials to include intumescent strips and smoke seal		P3	Within 3-6 months Repairs	
12/1a	Fit 'Fire Door Keep Locked' signage to the external service room door		P2	Within 1-2 months Caretaker	
12/1b	Fit 'Fire Door Keep Locked' signage to the internal service door		P2	Within 1-2 months Caretaker	

Observations

When undertaking future improvement program(s), it is advised that the observations listed below should be given consideration (noting that the safety of the residents is not jeopardised by these, and all steps to reduce any known risks have been taken).

Replace plastic trunking with metal in future refurbishment or at least add D clips or metal ties to the exterior of the trunking. Plastic cable management systems cannot be the sole means of support. All cables must have supplementary, heat-resistant (metallic) supports, clips, or ties spaced at intervals specified in the IET On-Site Guide (typically in accordance with Regulation 521.10.202). This is to prevent cables from collapsing prematurely in a fire and obstructing the escape route or hindering firefighting efforts.

Signed

	Fire Risk Assessor	Date: 18th November 2025
	Building Safety Manager	Date: 18 November 2025.

Appendix 1

**Significant Hazards on Site and
Information to be Provided for the Fire Service**

Name of property: Peartree Lane 19-24

Updated: 11/11/2025

Premise Manager: Prabha Patel

Tel. No.: 0121 569 2975

Hazard	Location	Information/Comments
An asbestos survey has been undertaken and is held by S.M.B.C. Investment Division (Tel:- 0121 569 5077).		



Report No.: J420629
Nature of Work: Management Survey
Issue Date: 07/05/2025
Client Name: Sandwell MBC (formerly Homes)
Building Services, Direct 2 Trading Estate, Roway Lane,
Oldbury, West Midlands, B69 3ES
UPRN: BL37480PE13 2
Site Address: 19-24 Peartree Lane, Cradley Heath, B64 6EH



Order Placed By: Dean Harding
Site Contact: Communal
Date(s) of Work: 18/04/2025
Technical Manager: D Ely CCP (Asbestos)
Assistant Surveyor(s): Not Applicable
Lead Surveyor:

A handwritten signature in black ink, appearing to be "Jordan Clewes".

Jordan Clewes
Asbestos Consultant

Authorised Signatory:

A handwritten signature in black ink, appearing to be "Louise Farmer".

Louise Farmer
Technical Review Officer and Asbestos Consultant
07/05/2025

Non-accredited activities are present within this report.

Head Office:
20 Stourbridge Road,
Halesowen, West Midlands
B63 3US
Tel: 0121 550 0224
Email: sales@bradley-enviro.co.uk



Report No.: J420629
Issue Date: 07/05/2025



1.0 Introduction & Scope of Work

A management survey was carried out internally and externally to the property, and was conducted in line with our inhouse procedures, which are based on the guidance document "HSG 264: The Survey Guide".

1.1 Aims & Objectives

The purpose of the management survey was to locate, as far as reasonably practicable, the presence and extent of any suspect ACMs in the building which could be damaged or disturbed during normal occupancy, including foreseeable maintenance and installation, and to assess their condition.

1.2 Caveats, Restrictions & Inaccessible Areas

The value and usefulness of a survey can be seriously undermined where either the client or the surveyor imposes restrictions on the survey scope (HSG264).

If any rooms were not accessed during the inspection, they will be indicated on the building plans (in yellow block) in section 5.

Where a room was accessed but specific elements within the room could not be inspected, caveats and their justification will be detailed in section 7.

It is strongly recommended that the client reviews the (general) caveats noted in sections 1.3 and/or 1.4 below, as well as the (room-specific) caveats cited in sections 5 and 7 as soon as possible upon receipt of the report. If the extent of access is less than required, the client should advise the Technical Management Team to arrange additional inspection work as necessary.

Report No.: J420629
Issue Date: 07/05/2025



Contents

1.0 Introduction & Scope of Work

- 1.1 Aims & Objectives
- 1.2 Caveats, Restrictions & Inaccessible Areas
- 1.3 Pre-agreed Caveats
- 1.4 Surveyor Imposed Caveats
- 1.5 UKAS Accreditation
- 1.6 Extent of ACM Identified
- 1.7 Presumption or Identification of ACMs

2.0 Recommendations

3.0 Executive Summary

- 3.1 Asbestos Containing Materials (ACMs) ranked by Risk
- 3.2 Non-Asbestos Materials

4.0 Item Register & Management Report

5.0 Annotated Building Plans

6.0 Room Description Report

7.0 Room Access Report

8.0 Bulk Analysis Results

9.0 Risk Assessment Algorithms

- 9.1 Material Assessment
- 9.2 Likelihood of Disturbance Assessment
- 9.3 Overall Risk Category

Appendix I: Asbestos Remediation

Report No.: J420629
Issue Date: 07/05/2025



1.3 Pre-agreed Caveats:

Representative access only will be made into voids etc. Where access panels have been screwed shut, reasonable efforts will be made to remove, investigate beyond and replace. Where access panels are difficult to open (i.e. paint-sealed, nailed in place, or secured with screws with rounded-off heads), they will not be accessed during a management survey unless specifically requested in the client's written instruction.

Inspection beneath carpets and other fitted floor coverings to identify the presence of ACMs (i.e. floor tiles etc.) or to locate access hatches will only be made during a management survey if the carpet can easily be lifted and replaced without causing a trip hazard to the building's occupants.

Loft spaces will only be fully inspected if suitable walk boards are present to provide safe access, and safe access is available to gain entry. Should no walk boards be present, a cursory inspection will be conducted from the access hatch.

Standard ladder access will be made to a height of 4m from ground level unless the client specifically requests (when the work is being planned) that access above 4m will be required.

Unless a suitable electrical isolation certificate can be provided for the site, electrical boxing, heaters etc. will not be accessed internally.

Items of plant (including boilers etc.) will only be inspected internally where specifically requested in the client's written instruction and a suitable isolation certificate can be provided.

Where suspect asbestos contamination (or other hazard) is likely in voids, access will be minimal unless specifically requested in the client's written instruction.

1.4 Surveyor Imposed Caveats:

No access to 01 Loft and 04 Cleaners Cupboard due to no keys being available.

Report No.: J420629
Issue Date: 07/05/2025



1.5 UKAS Accreditation

Bradley Environmental are accredited by UKAS to both ISO17025 (testing) and ISO17020 (inspections). Please note that the following are outside the scope of UKAS Accreditation:

- Likelihood of disturbance risk assessment;
- Recommendations;
- The sample references cited in section 8.0.

1.6 Extent of ACM Identified

Please note that the extents cited within this report are an approximation only and should not be used for the purposes of quoting asbestos removal works.

1.7 Presumption or Identification of ACMs

Where suspect materials have been located during this investigation, their asbestos content (or otherwise) will have been determined as follows:

A sample of the material will have been taken by the surveyor during the survey. This sample will then have been **analysed using polarised light microscopy** (PLM) to determine its asbestos content.

A material's asbestos content will have been **strongly presumed** where a visual inspection by the lead surveyor indicates the material is visually similar to other items present within the building which have been confirmed to contain asbestos (or otherwise) using PLM.

A material's asbestos content will have been **presumed** where it cannot be accessed or inspected.

Fire Risk Assessment

Executive Summary Report of Asbestos
Containing Materials (ACMs) By Risk

19-24 Peartree Lane, Cradley Heath

Report Number: J420629

Sample No.:	Floor Level:	Block Name:	Location:	Item:	Asbestos Content:	Determination Method:	Extent:	Risk Category:	Recommendations:
No sample - presumed	E - External	Flats	11 External	Asbestos Insulating board soffits	Crocidolite	Presumed	80 linear metres	C10	Monitor condition
No sample - presumed	E - External	Flats	11 External	Asbestos Insulating board undercloaking	Crocidolite	Presumed	16 linear metres	C9	Monitor condition