### Fire Risk Assessment

6-8
Warren Drive,
Rowley Regis,
B65 8NS.



Date Completed: 08/12/2025

Review Period: 3 years.

Officer: C. Hudson Fire Risk Assessor

Checked by: C. Hill Building Safety Manager

**Current Risk Rating = Tolerable** 



### **Subsequent reviews**

Review date	Officer	<u>Comments</u>

#### **Contents**

Section 0	Introduction	
Section 1	Significant Findings (executive summary)	
Section 2	People at Significant Risk of Fire	
Section 3	Contact Details	
Section 4	Description of Premises	
Section 5	Building Plan	
Section 6	External Envelope	
Section 7	Means of Escape from Fire	
Section 8	Fire Detection and Alarm Systems	
Section 9	Emergency Lighting	
Section 10	Compartmentation	
Section 11	Fire Fighting Equipment	
Section 12	Fire Signage	
Section 13	Employee Training	
Section 14	Sources of Ignition	
Section 15	Waste Control	
Section 16	Control and Supervision of Contractors and Visitors	
Section 17	Arson Prevention	
Section 18	Storage Arrangements	
Section 19	Additional Control Measures. Fire Risk Assessment – Action Plan	
Appendix 1	Significant Hazards on Site and Information to be provided for the Fire Service	

### Introduction

The Regulatory Reform (Fire Safety) Order 2005 (RR(FS)O) places a legal duty on landlords to complete a fire risk assessment (FRA). Specifically, RR(FS)O article 9. — (1) "The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order".

This type 1 fire risk assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on <a href="https://www.wmfs.net/our-services/fire-safety/#reportfiresafety">https://www.sanety/#reportfiresafety</a>. In the first instance however, we would be grateful if you could contact us directly via <a href="https://www.sandwell.gov.uk/info/200195/contact\_the\_council/283/feedback\_and\_complaints">https://www.sandwell.gov.uk/info/200195/contact\_the\_council/283/feedback\_and\_complaints</a> or by phone on 0121 569 6000.


The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation. The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment. If the review suggests the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.

The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.



The above processes and procedures are overseen by the Fire Safety, Facilities and Premises Manager who reports to the Business Manager - Surveying and Fire Safety.

These managers attend the Fire Safety Core Group for scrutiny which is part of the governance structure below.



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire.

This is recorded here in <u>section 1</u>. Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring and review of the preventative and protective measures. The information shown above is part of this requirement.

1

### Significant findings

The significant findings (executive summary) of the fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005.

Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors and contractors unfamiliar with the building layout as well as those with physical, sensory or mental health issues.

A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring and review of the preventive and protective measures. These are shown in the introduction.

#### **Significant findings**

Include a summary of protective and preventative measures where relevant along with any issues found.

The escape strategy is 'Stay Put Unless'. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire or smoke or you have been advised by the emergency services to leave.

Section number	Section Area	Individual Risk Level
Section 6	External Envelope The building is of traditional brick construction with a pitched, tiled roof.	Trivial
	UPVC double glazed units are fitted to individual flats and communal windows.	
	The Final exit door is of timber construction with glass panels.	

Section 7	Means of Escape from Fire The premise has a single staircase and one final exit door that provide a sufficient means of escape.	Tolerable
	Both Flat entrance doors are FD30s composite doors.	
	Flat 8 entrance door thumb turn requires attention.	
	Two flats have door mats at their entrances.	
	Top of stairs landing window has a vertical blind fitted.	
	The stairs leading to flat 8 have carpet fitted. A potted plant in a porcelain pot is in the stairwell.	
Section 8	Fire Detection and Alarm Systems Early warning is limited to hard wired or battery smoke alarms within each of the resident's flats. The flats checked were to an LD2 standard.	Trivial
Section 9	Emergency Lighting The premises have no emergency/ escape lighting.	Trivial
Section 10	Compartmentation The premise has sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire between dwellings and support the stay put unless policy.  The electrical support on the ground floor	Tolerable
	The electrical cupboard on the ground floor has items stored inside.	
	The electrical cupboard door requires upgrading.	
L	<u>l</u>	

	Roof void isn't assessable from communal area.	
Section 11	Fire Fighting Equipment The premises have no provision for firefighting equipment.	Trivial
Section 12	Fire Signage No Smoking signage is not displayed in communal area.	Tolerable
Section 13	Employee Training All staff receive basic fire safety awareness training.	Trivial
Section 14	Sources of Ignition The fixed electrical installation was last tested on 22/08/23 and should be tested every five years.	Trivial
Section 15	Waste Control Regular cleaning services take place at the block.  No caretaking services schedule at the block.	Trivial
Section 16	Control and Supervision of Contractors and Visitors Contractors are controlled centrally, and hot works permits are required where necessary	Trivial
Section 17	Arson Prevention The final exit door has euro lock installed. There is no evidence of any arson since the last risk assessment was carried out.	Trivial

Section 18	Storage Arrangements Residents do not have access to any secure storage cupboards.	Trivial
	Residents should not store fuel or LPG Cylinders in their home or storage facilities. This documented in the tenancy agreement.	

#### **Risk Level Indicator**

The following simple risk level estimator is based on commonly used risk level estimator:

Likelihood of fire	Potential consequences of fire				
Likeliilood of fire	Slight harm	Moderate harm	Extreme harm		
Low	Trivial risk	Tolerable risk	Moderate risk		
Medium	Tolerable risk	Moderate risk	Substantial risk		
High	Moderate risk	Substantial risk	Intolerable risk		

Considering the fire prevention measures observed at the time of this risk assessment, it is considered that the hazard from fire (likelihood of fire) at these premises is:

Low $\square$	Medium	$\boxtimes$	High □
In this contex	t, a definiti	ion of	the above terms is as follows:
Low			Unusually low likelihood of fire because of negligible potential sources of ignition.
Medium			Normal fire hazards (e.g. potential ignition sources) for this type of occupancy, with fire hazards generally subject to appropriate controls (other than minor shortcomings).
High			Lack of adequate controls applied to one or more significant fire hazards, such as to result in significant increase in likelihood of fire.

Considering the nature of the premises and the occupants, as well as the fire protection and procedural arrangements observed at the time of this

fire risk assessment, it is co in the event of fire would be	nsidered that the consequences for life safety :
Slight Harm ⊠ Moderat	e Harm □ Extreme Harm □
In this context, a definition of	of the above terms is as follows:
Slight harm	Outbreak of fire unlikely to result in serious injury or death of any occupant (other than an occupant sleeping in a room in which a fire occurs).
Moderate harm	Outbreak of fire could foreseeably result in injury including serious injury) of one or more occupants, but it is unlikely to involve multiple fatalities.
Extreme harm	Significant potential for serious injury or death of one or more occupants.
Accordingly, it is considered is:	I that the risk to life from fire at these premises
Trivial □ Tolerable ⊠ M	oderate □ Substantial □ Intolerable □

#### Comments

After conducting a Type 1 fire risk assessment at 6-8 Warren Drive, I conclude, the likelihood of a fire is at a medium level of risk prior to the implementation of the action plan because of the normal fire hazards that have been highlighted within the risk assessment.

Considering the use of the premises and the occupants within the block, the potential consequences for life safety in the event of a fire would be slight harm. This is because all flats are fitted with composite FD30S entrance doors, smoke detection systems installed to a minimum of LD3 in all flats, the final exit door has a thumb turn lock, and a stay-put strategy unless a fire strategy is in place.

Once the recommended actions have been completed, the overall risk rating for the building will be reduced to trivial, subject to the implementation of the suggested measures outlined in this fire risk assessment.

Overall, the risk level at the time of this FRA is considered tolerable.

When future refurbishments are carried out, there are a number of observations that would improve the building. These observations can be found at the end of this document.

A suitable risk-based control plan (where applicable) should involve effort and urgency that is proportional to risk. The following risk- based control plan is based on one that has been advocated for general health and safety risks:

(Note that, although the purpose of this section is to place the fire risk in context, the above approach to fire risk assessment is subjective and for guidance only. All hazards and deficiencies identified in this report should be addressed by implementing all recommendations contained in the following action plan. The fire risk assessment should be reviewed regularly.)

Risk level	Action and timescale
Trivial	No action is required, and no detailed records need to be kept.
Tolerable	No major additional fire precautions are required. However, there might be a need for reasonably practicable improvements that involve minor or limited cost.
Moderate	It is essential that efforts are made to reduce the risk. Risk reduction measures, which should take cost into account, should be implemented within a defined time period. Where moderate risk is associated with consequences that constitute extreme harm, further assessment might be required to establish more precisely the likelihood of harm as a basis for determining the priority for improved control measures.
Substantial	Considerable resources might have to be allocated to reduce the risk. If the premises are unoccupied, it should not be occupied until the risk has been reduced. If the premises are occupied, urgent action should be taken.
Intolerable	Premises (or relevant area) should not be occupied until the risk is reduced.

2

### **People at Significant Risk of Fire**

Persons at significant risk of fire does not just refer to those people with physical, sensory or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council has a policy and procedure in place for Personal Emergency Evacuation Plans (PEEPs). This is based on tenants identifying themselves as requiring a PEEP. This will be reliant on the outcomes of the government consultation which is yet to be published.

Residents are responsible for letting us know whether they might need a Personal Emergency Evacuation Plan (PEEP). The Resident Engagement Officers (Fire Safety) will conduct an assessment visit upon request. Any risk-reduction measures that are found where a PEEP is necessary and completed will be documented and taken quickly.

With the consent of the resident, we will make a referral for West Midlands Fire Service to conduct a Safe and Well visit.

When a PEEP is in place, the relevant information will be kept in the secure Premise Information Box (High Rise Buildings only), which is set up to help WMFS in an emergency. The data is classified as level 1, which means it complies with the General Data Protection Regulations.

### **Contact Details**

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.


The Chief Executive has put a structure in place to support the management of the site.

This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

Chief Executive				
Shokat Lal				
Executive Di	irector Asset Manager	· & Improvement		
	Alan Lunt			
Assistant Di	rector Asset Manager	& Improvement		
	Sarah Agar	-		
	Fire Safety Manage	r		
	Tony Thompson			
	Team Lead Fire Safe	ety		
Jason Blewitt				
Team Lead Building Safety				
Anthony Smith				
Housing Office Manager				
Prabha Patel				
Building Safety	Fire Risk	Resident Engagement		
Managers	Assessors	Officers – Fire Safety		
Adrian Jones	Craig Hudson	Abdulmonim Khan		
Andrew Froggatt	Mohammed Zafeer	Ethan Somaiya		
Carl Hill	Stuart Henley	Hannah Russon		
Louis Conway				
-				

Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change.



### **Description of Premises**

This type 1 fire risk assessment covers

Warren Drive 6-8 Cradley heath B65 8NS

The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021. The enforcing authority is West Midlands Fire Service.

#### **Description of the Property:**

The Low-rise block was constructed in 1968 of traditional brick cavity and concrete construction with brick walls concrete floors and stairs. The block has double glazed UPVC window frames with a pitched, tiled roof.

The block consists of 2 stories inclusive of ground.



Each of the floors from the ground floor upwards contain 1 individual flat.

The block is also attached to the next block Cromwell Road 53-55.



The building has a pitched roof, with concrete tiles and a brick-built chimney.



The block has a front entrance, that has a mortice lock with euro cylinder fitted, residents require a key to enter but the exit side has a thumb turn lock. The escape route leads to an ultimate place of safety.





This block does not have a dedicated bin store, but the bins are stored away from the building behind a solid brick wall.



The block has a single concrete staircase as the sole means of escape (above ground floor).



The stairs have carpet covering the fire resistance of this is unknown.

Flats 6, is on the ground floor

Flats 8, is on the 1st floor

The service cupboard housing electrical intakes is situated on the ground floor in a small cupboard locked with a push button lock.



The building has been designed and constructed to provide reasonable facilities to assist fire fighters in the protection of life. Reasonable provisions have been made to enable fire appliances to gain access to the building.

Nearest Fire station is Haden Cross Fire Station, which is 2.6 miles.

The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021.

The enforcing authority is West Midlands Fire Service.

The nearest fire station is Haden Cross Community Fire Station.

High/Low Rise	Low-Rise
Number of Floors	2
Date of Construction	1968
Construction Type	Traditional Brick Cavity / Concrete
Last Refurbished	Unknown
External Cladding	None
Number of Lifts	None
Number of Staircases	1
Automatic Smoke Ventilation to	None
communal area	
Fire Alarm System	None
Refuse Chute	None
Access to Roof	No Access from communal area
Equipment on roof (e.g. mobile	None
phone station etc)	

#### **Persons at Risk**


Residents / Occupants of 2 flats in total, Visitors, Sandwell MBC employees, Contractors, Service providers (e.g. meter readers, delivery people etc) Statutory bodies (e.g. W.M.F.S, Police, and Ambulance)

### **Building Plan**

Plan to show the general location/orientation of the building.

#### 6-8 Warren Drive.





### **External envelope**

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.

Below is a breakdown of the materials used within the external envelope.

It is deemed that the combination and application of these materials present an acceptable level of fire risk.

1) The external surface of the building is predominantly traditional brick construction.



- 2) The roof is clad with concrete interlocking tiles with.
- 3) The building has a brick-built chimney, at the time of the FRA it was unknown if it is in use.



4) There is no internal access from the landing to the roof space.

5) Doors and combination frame to the entrances are of timber construction with glass panels.



6) The building has UPVC facias and guttering just below the roof line.



7) UPVC double glazed units have been installed to each flat.



8) In the building the 1<sup>st</sup> floor landing, has a UPVC window, these windows can be opened without the use of a key, these also allow sufficient ventilation. There is no automatic smoke ventilation system installed in this premises.



9) The Gas meter is located on the front elevation and is supplied externally to the flats.







### Means of Escape from Fire

1) All Individual flat doors are FD30s rated composite fire doors.





- 2) Access was attempted to a sample some of the properties as part of the risk assessment. This was to ensure the doors have not been tampered with by residents. Only Flat 8 was accessed.
- 3) Flat 8 door reliably self closes on the latch.
- 4) Flat 8 door lock thumb turn does not correctly operate this will need adjustment or replacement. See action 7/4
- 5) Flat 6 Door was not inspected.



6) The two flats at their entrances have door mats, the fire rating is not known but deemed to be low risk.



7) The cupboard housing the electrical installation has notion doors which have been enhanced with Supalux fire rated board applied to the rear. Observations have been recorded in section 19.



- 8) Recommend upgrading doors on electrical cupboard to fire rated doors with smoke seals and intumescent strips. See observations.
- 9) Flat 8 has a Georgian wired glass panel in a solid timber frame in the hallway that also opens on to the staircase.



10) The means of escape is a stairs case of concrete construction.



- 11) The stairs are carpeted believed to have been fitted by the tenant.
- 12)It is noted that carpet is fitted to the stairs and the fire rating of this is unknown, it is believed the residents had this fitted, please see observations.
- 13) The landing is kept clear to maintain safe means of escape.
- 14) The building has sufficient passive controls that provide effective compartmentation to support a Stay Put Policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them.

- 15)The communal area is kept free of flammable items. The communal areas should be checked on a regular basis by Caretaking / Cleaning teams and all items of rubbish removed.
- 16) Ventilation of the common area is facilitated by openable windows in the stairwell. There is no automatic smoke ventilation system installed in this premises.
- 17)It was noted that the communal window on the landing was covered with a vertical window blind, the fire rating of this is unknown but deemed low risk.



18)A plant was noted in a terracotta pot at the bottom of the stairs.



- 19) No emergency lighting is provided to communal landing and stairs.
- 20) The only communal door within the block is the final exit door. The final exit door has a thumb turn lock and can be secured by residents. The final exit door does not a have a self-closing device installed.

8

### **Fire Detection and Alarm Systems**

- 1) Early warning is limited to hard wire or battery smoke alarms within each of the resident's flats the equipment is subjected to a cyclical test.
- 2) Based on samples taken, the previous fire risk assessment and information kept on file (JM) the smoke alarms within resident's flats are installed to a minimum of an LD3 Standard.

Flat 8 was accessed and was seen to be LD1 standard.



For information LD1 all rooms except wet rooms LD2 all-risk rooms e.g. Living Room, Kitchens and Hallway. LD3 Hallway only

- 3) There is no effective means for detecting an outbreak of fire to communal areas. The reason for this is:
  - I. Such systems may get vandalised.
  - II. False alarms would occur.
  - III. A Stay Put Unless policy is in place.

9

### **Emergency Lighting**

1. The premises has sufficient borrowed light and does not require emergency or escape lighting system in accordance with BS 5266.

### Compartmentation

- The building is designed to provide as a minimum 1-hour vertical fire resistance and 1-hour horizontal fire resistance around flats.
   All flat entrance doors are 30-minute fire doors, including those in 1-hour rated walls.
- 2) The building has sufficient passive controls that provide effective compartmentation to support a Stay Put-Unless policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them or if they are advised to evacuate by the emergency services.
- 3) The premise has sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire. Whilst the existing fire stopping is fit for purpose, there is a cyclical programme to ensure fire stopping as not been compromised by third parties and where applicable enhance the fire stopping.
- 4) A variety of methods / materials have been used to achieve firestopping.
- 5) Any remedial works arising from the fire stopping / compartmentation check(s) will be actioned immediately by the Fire Safety Rapid Response Team.
- 6) Electrical cupboard on the ground floor contains the electrical intake.
- 7) Electrical cupboard has had superlux panels previously installed to the doors and ceiling to enhance its fire resistance.
- 8) Personal Items Stored inside the electrical cupboard require removing. See action 10/8.



9) It was noted on the last FRA that the electrical cupboard doors should be upgraded to 44mm FD30s. See observations



- 10)All individual flats are installed with composite FD30s rated fire doors.
- 11)The block has a pitched roof with no loft access panel on the landing area.

### **Fire Fighting Equipment**

1) There is no firefighting equipment on this premises.

### Fire Signage

- 1) Appropriate signage is displayed throughout the building.
- 2) Directional fire signage is not displayed throughout the building. This is due to the simple layout of the building, and this type of signage is not required.
- 3) Yellow LPG warning signs are not displayed within the block. refer to section 18.
- 4) No smoking (Smoke Free England) signage is not displayed at the front entrance to the premises and requires replacing. See action 12/4




### **Employee & Resident Training/Provision of Information**

- 1) All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- 2) All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking teams are not currently trained in the effective use of fire extinguishers.
- 4) Fire safety information has been provided as part of tenancy pack. Information regarding the Stay Put Unless fire evacuation strategy is provided to tenants.
- 5) Staff undertaking fire risk assessments are qualified to or working towards Level 4 Diploma in Fire Risk Assessment.

### **Sources of Ignition**

- Smoking is prohibited on entrance and within any communal parts of the building in line with Smoke Free England legislation.
- Hot working is not normally carried out. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager.
- 4) Electrical supply is supplied from No 53-55 Cromwell Street
- 5) The fixed electrical installation EICR inspection was last carried out 22/08/23 and is carried out every 5 years.



- 6) Portable heaters are not allowed in any common parts of the premises.
- 7) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the in-house Gas Team. The gas supply is supplied externally.

### **Waste Control**

- 1. Sandwell Cleaning services are not employed at this block
- 2. Refuse bins are stored to the rear of the building behind a solid brick wall in the courtyard. Bins Are regularly emptied.



- 3. Caretaking services are not employed at this block.
- 4. Sandwell Council 'Out of Hours' service is in place to remove bulk items.

### Control and Supervision of Contractors and Visitors

- Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
- Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
- 3. Utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the local housing office. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
- 4. Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
- a) Pre-Contract Meetings where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
  - Health and Safety.
  - Site Security.
  - Safety of working and impact on children/school business.
  - Fire risk, if any.
    - Site Emergency Plan.
- b) Monthly Site Meetings in order to monitor, review and share any new information including any new risks.
- c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
- d) Final Contractor review on completion of works undertaken.

### **Arson Prevention**

- 1. Regular checks are undertaken by Caretakers / Cleaning Team(s) 365 days per year which helps reduce the risk of arson.
- 2. Restricted access to the premises.
- 3. There is no current evidence of arson.
- 4. There have been no reported fire incidents since the last FRA.
- 5. The perimeter of the premises is well illuminated.





### **Storage Arrangements**

- 1. Residents instructed not to bring L.P.G cylinders into block.
- 2. The tenancy conditions, Section 7 Condition 5.6 stipulates "If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use."
- 3. No Flammable liquids stored on site by Caretakers / cleaners.
- 4. There are no flammable liquids or gas cylinders stored on site.
- 5. Some residents have provided themselves with secured external storage sheds detached and away from the building.



### **Additional Control Measures. Fire Risk Assessment - Action Plan**

Significant Findings

Action Plan					
It is considered that the following recommendations should be implemented to reduce fire risk to, or maintain it at, the following level:					
Trivial ⊠ Tolerable □					
Definition of priorities (where applicable):					
P1 Arrange and complete as urgent – Within 10 days					
P2 Arrange and complete within 1-3 Months of assessment date					
P3 Arrange and complete within 3-6 Months of assessment date					
P4 Arrange and complete exceeding 6 months under programmed work					



### Fire Risk Assessment Action Plan



Name of Premises or Location: Warren Drive 6-8

Date of Action Plan: 00/12/2025

Review Date: <Insert date>

Question/ Ref No	Required Action	Supporting photograph	Priority	Timescale and Person Responsible	Date Completed
7/4	Flat 8 entrance door thumb turn requires adjustment. Lock fails to reliably lock.	N/A	P2	1-3 Months Fire Rapid Response	

10/8	Personal Items Stored inside the electrical cupboard require removing.	P2	1-3 Months Housing Manager	
12/4	Install No Smoking signage at front entrance	P2	1-3 Months Fire Rapid Response	

#### **Observations**

When undertaking future improvement program(s), it is advised that the observations listed below should be given consideration (noting that the safety of the residents is not jeopardised by these, and all steps to reduce any known risks have been taken).

Upgrade service cupboards to 44mm FD30s rated lockable doors as part of next improvement works.

Remove carpets fitted by residents in block and upgrade as part of next improvement works.

### Signed

CHAR.	Fire Risk Assessor	Date: 19 <sup>th</sup> December 2025
Chill	Building Safety Manager	Date: 19 <sup>th</sup> December 2025

#### Appendix 1

#### Significant Hazards on Site and Information to be Provided for the Fire Service

Name of property: Warren Drive 6-8

**Updated:** 12/02/2025

**Premise Manager: Prabha Patel** Tel. No.: 0121 569 2975

Hazard Location Information/Comments

An asbestos survey has been undertaken and is held by S.M.B.C. Investment Division (Tel:- 0121 569 5077).



#### CERTIFICATE OF ANALYSIS

Asbestos Fibre Identification in Bulk Sample

Client Sandwell MBC (formerly Homes)
Address: Building Senvices
Direct 2 Trading Estate
Roway Lane
Oldburn

12/02/2025

Job Title: Laboratory Analyst

Report No.: J410711						
Date Analysed:	Lab Ref.:	Site Ref:	Room:	Sample Reference:	Analysis Result:	Analyst:
12/02/2025	XX003620	-	01 - External	Asbestos Bitumen damp proof above door	Chrysotile	Gail Careless

3US 0121 550 0224

ait sales@bradley-enviro.co.uk







#### ABOUT THE REPORT - PLEASE READ

All Survey Methodology is based upon HSE document HSG 254 - Asbestos: The Survey Guide. All surveyors are experienced British Occupational Hygiene Society (BOHS) P402 qualified surveyors with extensive Surveying & Refurbishment Project experience specific to Sandwell MBC's managed housing stock.

The person or persons using this report to programme returbishment work on site are assumed to be competent & experienced in the field of domestic refurbishment projects & have suitable & sufficient assestios awareness to understand the scope of this report & apply it to the project. All trade operatives working on site are also expected to have relevant asbestos awareness training & experience. IF IN DOUBT STOP & ASK! Please ensure the report covers the areas that you need to work on.

SHAPE: Sandwell MSC's Integrated ICT solution holds the Company Asbestos Register. The Asbestos Register is interrogated when completing the asbestos survey report to ensure that ACM's in similar properties are considered where relevant. The Register holds details of all suspected or confirmed ACM's identified unity Refutivishment & Demolition programmes as well ast Repairs activities for the past 11 years. If potential ACM's have been identified within difficult to survey areas such as Cavity Walls, Foro Violes et these will be in Applicable within the report. The interrogation of the Company Asbestos Register compliments as usering survey & report process to does not substitute the Refutivishment & Demolition Survey.

Void Properties – The Building Surveying team who undertake Refurbishment & Demoition Asbestos Surveys also undertake Demoition Demoition Demoition Asbestos Surveys also undertake Demoition Demoit

Site Overview Page 2 – This section is included to aid surveying & to ensure comprehensive survey information is detailed.

Term	Explanation
Property Address	Specific Property to which survey relates.
Surveyed by	Relates to P402 trained surveyor.
Action taken on Project	Record what action may have been undertaken to the Asbestos in question. E.g. Nothing, Repair, replace, Manage.
Type of Work to be undertaken	Relates to the envisaged type of work that the Asbestos Survey Report will be used to aid. This assists the asbestos surveyor to guide his survey methodology & will help the users of this report decide if it is suitable for the work activity being undertaken.
ACM	Asbestos Containing Material.
HSE Notify	This highlights if a material normally requires notification to the Health & Safety Executive prior to removal. GUIDANCE ONLY.
Bulk Sample	Sample of potential ACM that is representative of the whole.
Request Sample	The item described has not been tested for Asbestos content. The item must be presumed to contain asbestos until sampling confirms. If work is going to be undertaken in this area sample should be requested prior to work starting.
Awaiting Results	If no results have been detailed then you must not work on these items until you receive further confirmation.
Extent	An estimate of quantity will be given where possible to aid work planning & valuation.
Labels	Materials will be labelled where practical. Labelling will be not be undertaken to low risk materials e.g. floor tiles. Featured Coatings etc or where labelling could easily be removed or would cause potential exposure if removed. All presumed ACMs will be labelled as "Abestos" where practical. All sampled materials will be labelled with an "Abbestos Sampled" label.

Term	Explanation
Photo's	These will usually be provided for the front elevation of the property to aid identification.
Sampled by	P402 trained surveyor.
Checked by	P402 trained surveyor who checks report prior to issuing.
Survey Report Type	Report type is determined by the type of work to be undertaken. The reader of this report must satisfy themselves that the scope of the survey is sufficient for the purpose of work being undertaken.
Refurbishment Survey	HSG 254 - Returbishment & Demoltton Survey. Surveying undertaken to all parts of the property presuming full decent homes returbishment, which may include, New Kötchen, New Bathroom, surperly & another property information available. This survey has been carried out without debiled knowledge of the works to be undertaken during refurbishment. Anyone using this report to support building works being undertaken to the property should ensure that the report is sufficient for the purposes of the building work being undertaken. The reader should be confident that the areas that are to be disturbed by the proposed work are included.
Management Survey	A management survey is the standard survey. Its purpose its to locate, as far as reasonably practicable, the presence and extent of any suspect ACMs in the building which could be damaged or disturbed during normal occupancy, including foreseeable maintenance and installation, and to assess their condition.
Refurb & Management Survey	Both Survey Report Types are ticked due to works identified at survey stage the surveyor has completed Refurbithment Survey for the works required & may have undertaken a management survey on remaining areas of the property. The report should not be used for works outside the scope stated, unless the reader assures themselves that it is suitable & sufficient.
Cavity Walls / Floor Volds or similar.	Will be assessed at survey stage & desktop assessment of similar archetypes.
Photo's	Where practical & to aid the identification of ambiguous material locations photos will be included within the report to ensure that materials are identified on-lite correctly. Photos will be annotated where necessary.