

# Fire Risk Assessment

## James Clift House



**Martley Road,  
Oldbury,  
B69 1EH**

**Date Completed: 1<sup>st</sup> September 2022**

**Officer: C Hill Fire Risk Assessor**

**Checked By: J Blewitt Team Lead Fire Safety & Facilities**

**Current Risk Rating 0 = Low**

**Subsequent reviews**

<b><u>Review date</u></b>	<b><u>Officer</u></b>	<b><u>Comments</u></b>

---

## Contents

<a href="#">Section 0</a>	<b>Introduction</b>	
<a href="#">Section 1</a>	<b>Significant Findings (executive summary)</b>	
<a href="#">Section 2</a>	<b>People at Significant Risk of Fire</b>	
<a href="#">Section 3</a>	<b>Contact Details</b>	
<a href="#">Section 4</a>	<b>Description of Premises</b>	
<a href="#">Section 5</a>	<b>Building Plan</b>	
<a href="#">Section 6</a>	<b>External Envelope</b>	
<a href="#">Section 7</a>	<b>Means of Escape from Fire</b>	
<a href="#">Section 8</a>	<b>Fire Detection and Alarm Systems</b>	
<a href="#">Section 9</a>	<b>Emergency Lighting</b>	
<a href="#">Section 10</a>	<b>Compartmentation</b>	
<a href="#">Section 11</a>	<b>Fire Fighting Equipment</b>	
<a href="#">Section 12</a>	<b>Fire Signage</b>	
<a href="#">Section 13</a>	<b>Employee Training</b>	
<a href="#">Section 14</a>	<b>Sources of Ignition</b>	
<a href="#">Section 15</a>	<b>Waste Control</b>	
<a href="#">Section 16</a>	<b>Control and Supervision of Contractors and Visitors</b>	
<a href="#">Section 17</a>	<b>Arson Prevention</b>	
<a href="#">Section 18</a>	<b>Storage Arrangements</b>	
<a href="#">Section 19</a>	<b>Additional Control Measures; Fire Risk Assessment – Level 2 Action Plan</b>	
<a href="#">Appendix 1</a>	<b>Significant Hazards on Site and Information to be provided for the Fire Service</b>	

---

## Section

# 0

## Introduction

---


The [Regulatory Reform \(Fire Safety\) Order 2005 \(RR\(FS\)O\)](#) places a legal duty on landlords to complete a fire risk assessment (FRA). Specifically, RR(FS)O article 9. — (1) *“The responsible person must make a suitable and sufficient assessment of the risks to which relevant persons are exposed for the purpose of identifying the general fire precautions he needs to take to comply with the requirements and prohibitions imposed on him by or under this Order”*.

This fire risk assessment has been written to comply fully with the above legislation which is enforced locally by West Midlands Fire Service. If required, complaints can be made to them by telephone on 0121 380 7500 or electronically on <https://www.wmfs.net/our-services/fire-safety/#reportfiresafety>. In the first instance however, we would be grateful if you could contact us directly via [https://www.sandwell.gov.uk/info/200195/contact\\_the\\_council/283/feedb ack\\_and\\_complaints](https://www.sandwell.gov.uk/info/200195/contact_the_council/283/feedback_and_complaints) or by phone on 0121 569 6000.

The date of the fire risk assessment is on the front page, followed by any subsequent reviews. A recurring time frame is not set in legislation. The council has procedures and policies in place that will trigger a review of the fire risk assessment. This then is recorded on the fire risk assessment. If the review suggests the fire risk assessment is not currently suitable and sufficient, then a new fire risk assessment will be undertaken and become the current fire risk assessment. The previous fire risk assessment will be retained in the building safety case for that building.


The following diagrams illustrate those procedures and persons that support the effective planning, organisation, control, monitoring and review of the preventive and protective measures. This information is provided as required under the RR(FS)O.

---



The above processes and procedures are overseen by the Fire Safety, Facilities and Premises Manager who reports to the Business Manager - Surveying and Fire Safety.

These managers attend the Fire Safety Core Group for scrutiny which is part of the governance structure below.



To summarise the fire risk assessment, in this scenario the RR(FS)O requires the prescribed information to be recorded. The prescribed information is the significant findings of the fire risk assessment and those groups or persons especially at risk from fire. This is recorded here in [section 1](#). Also required to be recorded under article 11, are the fire safety arrangements for the planning, organisation, control, monitoring and review of the preventative and protective measures. The information shown above is part of this requirement.

---

**Section**

**1**

**Significant findings**

The significant findings (executive summary) of the fire risk assessment include those measures that have been or will be undertaken by the responsible person in order to comply with the RR(FS)O 2005.

Groups of people especially at risk of fire include such people as remote or lone workers, at risk due to layout of the building, visitors and contractors unfamiliar with the building layout as well as those with physical, sensory or mental health issues.

A third requirement that under the order must be recorded is the fire safety arrangements. This is the effective planning, organisation, control, monitoring and review of the preventive and protective measures. These are shown in the introduction.

**Significant findings**

*Include a brief summary of protective and preventative measures where relevant along with any issues found;*

The escape strategy is ‘**Stay Put Unless**’. This means in the event of a fire in your flat you should evacuate. If there is a fire elsewhere in the building you should stay put unless you are affected by fire or smoke

Section number	Section Area	Individual Risk Level
<a href="#">Section 6</a>	<p><b>External Envelope</b>                      The building is of traditional brick construction with PVC fascia boards and felt to the roof line. Windows are uPVC double glazed units to the flats with aluminium frame units to the communal stairwell.</p> <p>All flats have an individual balcony with steel railings.</p> <p>Flats 3 and 8 have installed wicker screening to balcony railings.</p>	0

<p><a href="#">Section 7</a></p>	<p><b>Means of Escape from Fire</b>                  Each block has a single staircase and 2 final exit doors that provide a suitable means of escape.</p> <p>Service cupboard doors require cold smoke seals installed.</p> <p>Flat 6 requires access door upgrade to FD30s composite to replace temporary door and damage to frame.</p> <p>Flat 8 has a temporary timber flush fd30s door.</p> <p>Flats 5 &amp; 7 require self-closing devices re-instating to entrance door.</p>	<p>0</p>
<p><a href="#">Section 8</a></p>	<p><b>Fire Detection and Alarm Systems</b>                  Flats have a fire detection system fitted to an LD3 standard.</p>	<p>0</p>
<p><a href="#">Section 9</a></p>	<p><b>Emergency Lighting</b>                  The premises have a sufficient emergency / escape lighting system in accordance with BS 5266.</p>	<p>0</p>
<p><a href="#">Section 10</a></p>	<p><b>Compartmentation</b>                  Individual flat doors are FD30s rated fire doors.</p>	<p>0</p>
<p><a href="#">Section 11</a></p>	<p><b>Fire Fighting Equipment</b>                  The premises have no provision for firefighting equipment.</p>	<p>0</p>
<p><a href="#">Section 12</a></p>	<p><b>Fire Signage</b>                  Fire door keep shut &amp; no smoking signs have been installed.</p>	<p>0</p>
<p><a href="#">Section 13</a></p>	<p><b>Employee Training</b>                  All staff receive basic fire safety awareness training.</p>	<p>0</p>
<p><a href="#">Section 14</a></p>	<p><b>Sources of Ignition</b>                  The fixed electrical tests were last completed 25/01/19</p>	<p>0</p>

<a href="#">Section 15</a>	<b>Waste Control</b> Caretakers undertake regular checks and bins are stored away from the building.	0
<a href="#">Section 16</a>	<b>Control and Supervision of Contractors and Visitors</b> Contractors are controlled centrally, and hot works permits are required where necessary.	0
<a href="#">Section 17</a>	<b>Arson Prevention</b> There is external lighting and a door entry system prevents unauthorised access.	0
<a href="#">Section 18</a>	<b>Storage Arrangements</b> Residents each have access to secure storage cupboards in communal lobby, also within rear yard.	0

Risk Categories	
Risk Rating	Description
5	Presents a serious risk to life safety. This matter requires immediate action and must be given a high priority.
4	A significant safety issue.
3	A safety issue, but where the level of risk is reduced by a combination of compensatory factors; or where there is a risk to property only.
2	A desirable improvement to increase protection from fire.
1	A minor improvement to safety.
0	No risks identified

**The highest risk rating selected shall be transferred to the front page of the risk assessment using a RAG rating as follows**

---

**Current Risk Rating 4-5 = HIGH**

**Current Risk Rating 1-3 = MEDIUM**

**Current Risk Rating 0 = Low**

---

## Section

# 2

## People at Significant Risk of Fire

---

Persons at significant risk of fire does not just refer to those people with physical, sensory or mental health issues. It also includes those at risk due to the layout or features of the building such as inner rooms or dead-end conditions. Persons may also be at risk due to remote or lone working.

The RR(FS)O requires that these people are identified in any fire risk assessment.

Sandwell Council is currently writing a policy and procedures for Personal Emergency Evacuation Plans (PEEPs). This is based on tenants identifying themselves as requiring a PEEP. This will be reliant on the outcomes of the government consultation which is yet to be published.

Where this is known and PEEPs have been completed, it will be captured in this fire risk assessment along with any building layout or working practices placing people at significant risk of fire.

---

## Section

# 3

## Contact Details

---

The Chief Executive of Sandwell Metropolitan Borough Council has ultimate responsibility for the site as the responsible person identified by the RR(FS)O 2005.

The Chief Executive has put a structure in place to support the management of the site.

This includes the role of Building Safety Manager who has duties as defined within the Regulatory Reform (Fire Safety) Order 2005.

The contact names to support the management of the site are as follows:

### **Chief Executive**

Kim Bromley Derry (Interim Director)

### **Director of Housing**

Gillian Douglas

### **Business Manager Surveying and Fire Safety (Building Safety Manager)**

Phil Deery

### **Fire Safety, Facilities and Premises Manager**

Tony Thompson

### **Team Lead Fire Safety and Facilities**

Jason Blewitt

### **Fire Risk Assessor(s)**

Pardeep Raw

Carl Hill

Louis Conway (trainee)

### **Resident Engagement Officer - Fire Safety**

Lee Mlilo

### **Neighbourhood Office Manager**

Rachel Price

*Please note, the above details are correct at the time of the production of the risk assessment and may be subject to change*

---

## Section 4

# Description of Premises

---

James Clift House  
Martley Road  
Oldbury  
B69 1EH

### Description of the Property

The low-rise block was constructed in 1962 using a traditional brick cavity build. The roof is flat with no internal access.



The block consists of 3 storeys (inclusive of the ground floor). Each of the floors contains 3 number dwellings accessed by a central stairwell.



The block has a main entrance to the front elevation and a further exit located on the rear elevation. Front entrance has a door entry system with a fob reader installed and a firefighter override switch, the rear entrance has a fob reader.



The communal, any workplace areas and the external envelope of the building are subject to the Regulatory Reform (Fire Safety) Order 2005 as confirmed by the Fire Safety Act 2021.

The enforcing authority is West Midlands Fire Service.

High/Low Rise	Low-Rise
Number of Floors	3
Date of Construction	1962
Construction Type	Traditional Brick
Last Refurbished	Unknown
External Cladding	No
Number of Lifts	None
Number of Staircases	1
Automatic Smoke Ventilation to communal area	No
Fire Alarm System	No
Refuse Chute	No
Access to Roof	Flat Roof – No Internal Access
Equipment on roof (e.g. mobile phone station etc)	No

### Persons at Risk

Residents / Occupants of 9 Flats,  
Visitors,  
Sandwell MBC employees,  
Contractors,  
Service providers (e.g. meter readers, delivery people etc)  
Statutory bodies (e.g. W.M.F.S, Police, and Ambulance)


---

**Section**

**5**

**Building Plan**

A general plan of the building.



## Section 6

### External envelope

Following the introduction of the Fire Safety Act 2021, consideration needs to be given to the external envelope of the building for any fire risk. This predominantly means the external wall construction including any insulation filler. It also includes balconies and any other fixtures as well as doors and windows.

Provide a breakdown of the materials used and whether these or their combination or application present an acceptable level of fire risk.

- 1) The external surface of the building is predominantly brick structure with a uPVC fascia and felt to the roof line.



- 2) uPVC double glazed units have been installed to each flat. Aluminium framed units to the communal stairwell.



- 3) Each flat has an individual balcony with steel railings.



- 4) Flat 3 on ground floor has wicker screening to balcony railings.



- 5) Flat 8 on 2<sup>nd</sup> floor has wicker screening to balcony railings.



## Section 7

### Means of Escape from Fire

- 1) The site has a single staircase that provides a means of escape and is 870mm in width.



- 2) All corridors are of adequate width (at least 1050mm) and will be maintained clear to that width as a minimum.
- 3) None of corridors that form part of the means of escape are dead ends.
- 4) The means of escape are protected to prevent the spread of fire and smoke.
- 5) The only communal doors within the block are the final exit doors which are fitted with automatic closing devices. These are checked on a regular basis by Caretaking Teams as part of their daily checks. Defective closing devices are reported to an external contractor.



- 6) The final exit doors have door entry systems installed. These systems are designed to fail safe i.e. door unlocked in the event of a power failure. This prevents residents being locked in or out of the building.




- 7) Automatic smoke ventilation is not employed.

- 8) Communal windows can only be opened without the use of a key.



- 9) Communal areas are kept free of flammable items. The communal areas are checked on a regular basis by Caretaking / Cleaning teams 365 days per year and all items of rubbish are immediately removed. There is also an out of hour's service that allows combustible items of furniture / rubbish to be removed.



10) Emergency lighting is provided to communal landings and stairs. Checks are done on a monthly basis by Sandwell MBC in house electrical team or approved contractor. ([Refer to section 9](#)).

11) Service cupboards on each floor are FD30 rated, secured with budget locks. Residents have keys for access to electricity meters.

**A. None of the 3 service cupboards have cold smoke seals.**



**B. Ground floor service cupboard has excessive gap on lock edge and is tight on hinge side.**



12) The surface coatings to the communal areas are Class 0 rated.

13) All floors have S.M.B.C fitted carpet. Due to the fact S.M.B.C specified and managed the installation of the carpets it has been presumed that it is class 0 fire rated.



14) The building has sufficient passive controls that provide effective compartmentation in order to support a Stay Put-Unless Policy. Therefore, residents are advised to remain in their flat unless the fire directly affects them.

15) Storage cupboards on communal lobbies have secured non-fire rated doors. Doors are listed for upgrade as part of future programme.



16) Flat entrance doors are accessed from the communal stairwell.

17) Individual flat doors are FD30s rated composite door sets. Flats 6 & 8 have temporary timber flush fire doors fitted.

**A. Flat 6 has temporary timber flush fire rated door. Signs of forced entry with damage to the frame. (access not gained for internal inspection)**



**B. Flat 8 has a temporary timber flush fire rated door.  
(access not gained for internal inspection)**



18) Access is gained to a sample of properties as part of the fire risk assessment to ensure the doors have not been tampered with by residents etc.

**A. Flat 5 self-closing device removed from door.**



**B. Flat 7 self-closing device disconnected from door.**



- 19) The fire rating of individual floor mats to communal areas is unknown.



## Section 8

## Fire Detection and Alarm Systems

---

- 1) Early warning is limited to hard wire or battery smoke alarms within each of the resident's flats. The equipment is subjected to a cyclical test.
- 2) Based on the sample of properties accessed during the fire risk assessment the smoke alarms within resident's flats are installed to an LD3 Standard.

Flat 5 – 1 x Smoke detector in hall.

Flat 7 – 1 x smoke detector in hall.

*For information*

*LD1 all rooms except wet rooms*

*LD2 all-risk rooms e.g. Living Room, Kitchens and Hallway.*

*LD3 Hallway only*

- 3) There is no effective means for detecting an outbreak of fire to communal areas. The reason for this are:
    - I. Such systems may get vandalised.
    - II. False alarms would occur.
    - III. A Stay Put - Unless policy is in place.
-

# Section 9

## Emergency Lighting

- 1) The premises has a sufficient emergency / escape lighting system in accordance with BS 5266 and has test points strategically located.
- 2) The self-contained units are provided to the communal landings and stairs.



- 3) All installed equipment is checked and tested on a monthly basis by Sandwell MBC in house electrical team or approved contractor, in accordance with current standards.

Date	Remarks	Test Points	Signature
11/12/21	All OK	L1-L50	[Signature]
12/12/21	All OK	L1-L50	[Signature]
13/12/21	All OK	L1-L50	[Signature]
14/12/21	All OK	L1-L50	[Signature]
15/12/21	All OK	L1-L50	[Signature]
16/12/21	All OK	L1-L50	[Signature]
17/12/21	All OK	L1-L50	[Signature]
18/12/21	All OK	L1-L50	[Signature]
19/12/21	All OK	L1-L50	[Signature]
20/12/21	All OK	L1-L50	[Signature]
21/12/21	All OK	L1-L50	[Signature]
22/12/21	All OK	L1-L50	[Signature]
23/12/21	All OK	L1-L50	[Signature]
24/12/21	All OK	L1-L50	[Signature]
25/12/21	All OK	L1-L50	[Signature]
26/12/21	All OK	L1-L50	[Signature]
27/12/21	All OK	L1-L50	[Signature]
28/12/21	All OK	L1-L50	[Signature]
29/12/21	All OK	L1-L50	[Signature]
30/12/21	All OK	L1-L50	[Signature]
31/12/21	All OK	L1-L50	[Signature]

## Section 10

# Compartmentation

---

*This section should be read in conjunction with Section 4*

- 1) The building is designed to provide as a minimum 1 hour vertical fire resistance and 30 minutes horizontal fire resistance between dwellings. This is not possible in communal areas due to open plan staircase.
- 2) The premise does not have sufficient compartmentation to limit the travel and effect of smoke and flame in event of a fire in communal areas due to open plan staircase.



- 3) There are no communal doors fitted with automatic closing devices other than the final exit doors. These are checked on a regular basis by Caretaking Teams as part of their checks. Defective closing devices are replaced either by the Caretaking Team(s) or the in-house repairs team(s).



- 4) All service cupboards to communal landings are lockable with budget locks.



- 5) A variety of methods / materials have been used to achieve fire-stopping including Rockwool, foam and intumescent pillows. Whilst the existing fire stopping is fit for purpose, there is a cyclical programme to ensure fire stopping has not been compromised by third parties and where applicable enhance the fire stopping.

Address:		High Rise:		Date of Survey:		Operatives:																			
James Clift House (1-9)		Low Rise: <input checked="" type="checkbox"/>		08/06/2022		Scott Millinchip <input checked="" type="checkbox"/> Glenn Stevens <input checked="" type="checkbox"/>																			
Communal:																									
<b>Electric Meter Cupboard</b>		<b>Fire Stopping Materials</b>				<b>Fire Stopping Materials</b>				<b>Fire Stopping Materials</b>															
Floor No	Segalux	Intu Batt	Intu Sponge	Intu AM Intalox	Capalite Fibre	Intu Pads	Intu Pillars	Rockwool	Segalux	Intu Batt	Intu Sponge	Intu AM Intalox	Capalite Fibre	Intu Pads	Intu Pillars	Rockwool	Segalux	Intu Batt	Intu Sponge	Intu AM Intalox	Capalite Fibre	Intu Pads	Intu Pillars	Rockwool	Floor No
16																									16
15																									15
14																									14
13																									13
12																									12
11																									11
10																									10
9																									9
8																									8
7																									7
6																									6
5																									5
4																									4
3																									3
2			✓	✓	✓	✓																			2
1			✓	✓	✓	✓																			1
0																									0
Communal doors free from defects		✓		Communal windows free from defects		✓		Flat doors free from defects		✓		Communal cupboards locked and secure		✓		Communal areas free from tenants stored items		✓		Communal areas free from repairs materials		✓			
<b>Foam Removal &amp; Enhancement Record</b>				<b>Foam, Enhancements &amp; Other Comments:</b>																					
Foam Present But Not Removed This Visit																									
Foam Present & Partially Removed This Visit																									
Foam Present & Fully Removed This Visit																									
No Foam Present				✓																					
No Enhancement Carried Out This Visit				✓																					
Enhancement Carried Out This Visit																									

6) Individual flat doors are FD30s rated composite fire door construction or timber flush FD30s rated.



## Section 11

### Fire Fighting Equipment

---

- 1) The premise has no provision for firefighting equipment.

## Section 12

### Fire Signage

---

- 1) All fire doors display “Fire Door Keep Shut” where appropriate.



- 2) Fire Action Notices are not displayed throughout the building. This is not necessary due to the building not having a complex layout.
- 3) Yellow LPG warning signs are not displayed ([refer to section 18](#)).
- 4) Smoking is prohibited within any communal parts of the building in line with Smoke Free England Legislation. Signs are displayed throughout the building.



**Section**  
**13**

---

**Employee & Resident  
Training/Provision of Information**

---

- 1) All Caretaking / Cleaning Employees have undertaken fire safety training. This includes use of bespoke 'Fire Safety in High / Low Rise Flatted Accommodation' Video.
- 2) All employees are encouraged to complete 'In the line of fire' training on an annual basis.
- 3) Caretaking Teams are not currently trained in the effective use of fire extinguishers.
- 4) Neighbourhood Directorate employees assigned to undertake Fire Safety Inspections have received IFE approved training via West Midlands Fire Service.
- 5) Fire safety has been provided as part of tenancy pack.

## Section 14

### Sources of Ignition

- 1) Smoking is prohibited within any communal parts of the building in line with Smoke Free England legislation.
- 2) Hot working is not normally carried out. If essential maintenance requires the use of hot work processes, then corporate policies and procedures are to be followed.
- 3) Portable electrical equipment used as part of the Caretaking / Cleaning regime is subject to annual PAT Testing. This information is held by the Estate Services Manager Bryan Low.
- 4) The fixed electrical installation shall be tested every 5 years. It was noted that the last inspection was 25<sup>th</sup> January 2019.




- 5) The electrical installation i.e. risers are contained within dedicated service cupboards that are secure and protected by means of a FD30 door.
- 6) Portable heaters are not allowed in any common parts of the premises.
- 7) Gas appliances and pipework (where installed) are subject to annual testing and certification. This cyclical contract is managed by the in-house Gas Team. It was noted that the incoming supply is external to the building.

**Section  
15**

**Waste Control**

---

- 1) There is a regular Cleaning Service to the premises.



- 2) Refuse containers are located away from the building and emptied regularly.



- 3) Regular checks by Caretakers minimise risk of waste accumulation.
- 4) 'Out of Hours' service in place to remove bulk items.
-

## Section 16

# Control and Supervision of Contractors and Visitors

---

- 1) Responsive Repairs service delivered by Sandwell MBC necessitates the production of an order via the computerised repairs system. Details of any known risks are documented on the repair order.
  - 2) Hot works are not permitted unless authorisation is given via the approved officer. The hot works procedure is to be followed.
  - 3) Owing to the nature of Low Rise flatted accommodation, it is difficult to manage / control individual contractors / utility companies.
  - 4) However, utility companies are not allowed to access any service cupboard or secure area. They must request and collect maintenance keys from the local housing office. This allows scrutiny of what is the scope of any works such as installation of tenant's broadband / phone line etc.
  - 5) Where contractors are appointed to undertake major refurbishment works, Sandwell MBC Urban Design team will put control measures in place. Such Measures include: -
    - a) Pre-Contract Meetings – where contractor is made aware of all working arrangements and safe systems of work to be adopted. Issues covered in this meeting will include:
      - Health and Safety.
      - Site security.
      - Safety of working and impact on children/school business.
      - Fire risk, if any.
      - Site Emergency Plan.
    - b) Monthly Site Meetings – in order to monitor, review and share any new information including any new risks.
    - c) Site monitored daily whilst work is in progress by Clerk of Works / Health and Safety Officers.
    - d) Final Contractor review on completion of works undertaken.
-

**Section**  
**17**

**Arson Prevention**

---

- 1) Regular checks are undertaken by Caretakers / Cleaning Team(s) 365 days per year which helps reduce the risk of arson.
- 2) Restricted access to the premises by means of a door entry system.



- 3) There is no current evidence of arson.
- 4) The perimeter of the premises is well illuminated.



- 5) There has been no reported fire incidents since the last FRA.
-

**Section  
18**

**Storage Arrangements**

---

- 1) Residents instructed not to bring L.P.G cylinders into block.
- 2) The tenancy conditions, Section 7 – Condition 5.6 stipulates “If you live in a flat or maisonette, you, people living with you and any visitors to your property must not keep or use paraffin oil, petrol, bottled gas appliances or any other explosive, FLAMMABLE or dangerous material in the property. This restriction also applies to any storage facility situated in or attached to the block, which has been provided for your use.”
- 3) No Flammable liquids stored on site by Caretakers / cleaners.
- 4) All store cupboards are kept locked.
- 5) There are no flammable liquids or gas cylinders stored on site.
- 6) Residents have access to secured storage cupboards on communal landings and externally at the rear of the building.



**Section  
19**

**Additional Control Measures;  
Fire Risk Assessment - Level 2  
Action Plan**

Significant Findings

**Risk Rating of Additional Control Measures**

Risk Categories	
Risk Rating	Description
5	Presents a serious risk to life safety. This matter requires immediate action and must be given a high priority.
4	A significant safety issue.
3	A safety issue, but where the level of risk is reduced by a combination of compensatory factors; or where there is a risk to property only.
2	A desirable improvement to increase protection from fire.
1	A minor improvement to safety.

The highest risk rating selected shall be transferred to the front page of the risk assessment using a RAG rating as follows

**Current Risk Rating 4-5 = HIGH**

**Current Risk Rating 1-3 = MEDIUM**

**Current Risk Rating 0 = Low**



# Fire Risk Assessment Level 2 Action Plan



Name of Premises or Location:

James Clift House

Date of Action Plan:

2<sup>nd</sup> September 2022

Review Date:

<Insert date>

Question/ Ref No	Required Action	Supporting photograph	Risk Rating	Timescale and Person Responsible	Date Completed
06/04	Flat 3 – Remove wicker screening installed to balcony railings.		3	P2 – 1-3 Months of assessment date. Housing Team	13/10/2022

---

Fire Risk Assessment

06/05	Flat 8 - Remove wicker screening installed to balcony railings.		3	P2 – 1-3 Months of assessment date. Housing Team	13/10/2022
07/11a	Install cold smoke seals to the 3 service cupboard doors.		2	P2 – 1-3 Months of assessment date. Fire Rapid Response Team JM9568014	26/09/2022
07/11b	Correct excessive gap to ground floor service cupboard. (hinge side is tight)		2	P2 – 1-3 Months of assessment date. Fire Rapid Response Team JM9568038	26/09/2022

Fire Risk Assessment

---

					
07/17b	Flat 8 access door requires upgrading to fd30s composite door set.		2	Future Upgrade Programme	n/a
07/18a	Flat 5 – install self-closing device to entrance door.		2	P2 – 1-3 Months of assessment date. Fire Rapid Response Team JM9568114	26/09/2022

---

Fire Risk Assessment

---

07/18/b	Flat 7 – self closing device requires re-connecting on entrance door		2	P2 – 1-3 Months of assessment date. Fire Rapid Response Team JM9568134	26/09/2022
---------	--	--	---	--	------------

C.Hill	Fire Risk Assessor	Date: 02/09/2022
	Premise Manager	Date: 21/09/2022

---

**Name of property: James Clift House**

**Updated: 02/09/2022**

**Premise Manager: Anthony Thompson Tel. No.: 0121 569 2975**

<b>Hazard</b>	<b>Location</b>	<b>Information/Comments</b>
An asbestos survey has been undertaken and no suspected A.C.M.'s were found to any of the communal areas. Survey held by S.M.B.C. Investment Division (Derek Still <a href="tel:01215695077">Tel:- 0121 569 5077</a> ).		